

N450PR



The Standard

PROPELLER CO.

N450PR

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		


 US Sport Planes 5035 Warbird Dr. Denton, TX 76207 940-597-6860

Registration: N450PR S/N: 139 Mfg.: DEUTCH RONALD J Yr/Model: 2004 / Jabiru J450 Engine 3300A S/N 33A675  
 Date: 11-04-2021 Total AC Time: 243 Engine TT: 243 Prop: Jabiru 4A484DOD TT Hub front 4A482POD S/N0361, rear 4A482MOD S/N0361; Blades 4A484DOD S/N0470 and 0481 TT: 91.3  
**Prop:** Performed an annual 100hr/condition inspection in accordance with Jabiru Propeller Technical Manual. Prop removed, dis-assembled, inspected, repaired small nick on back side of SN 470, balance checked, re-installed. Hub inspected for cracks. Torqued mount bolts to 16 nm; Torqued Clamp Bolts to 11 nm. Checked prop track: under 1 mm. Inspected Spinner and Backplate with no defects found. Polished spinner. I certify this work has been performed in accordance with the Jabiru Propeller Technical Manual JPM0001-5 dated June 8, 2016 and was found to be in a condition for safe operation at this time.

For US Sport Planes by: Scott Severen A&P #3543489  Date: 11-04-2021

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____	US Sport Planes 5035 Warbird Dr. Denton, TX 76207 940-597-6860	
Date: _____	Registration: N450PR S/N: 139 Mfg.: DEUTCH RONALD J Yr/Model: 2004 / Jabiru J450 Engine 3300A S/N 33A675	
Next Insp Due: _____	Date: 03-04-2024 Total AC Time: 329 Engine TT: 329 Prop: Sensenich R62HN Blades SN 85633, 85663. TT 0 hrs. <b>Prop:</b> Installed new Sensenich R62HN propeller blades. Inspected hub. Torqued mount bolts to 19 ft lbs., Clamp Bolts to 12 nm with Nordlock washers. Checked prop track: under 1 mm. Inspected Spinner and Backplate with no defects found. I certify this prop has been inspected and work has been performed in accordance with Sensenich Installation and Maintenance Instructions and was found to be in a condition for safe operation at this time.	

For US Sport Planes by: Scott Severen A&P #3543489  Date: 03-04-2024

Next Inspection Due: _____	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>2014</u>	Total Time in Service	Description <u>SET PROP ANGLE TO 63.5.</u> <u>RE TORQUED BOLTS TO 17 FT LBS. RTN'D</u> <u>TO SERVICE</u> <i>[Signature]</i> <u>3062656</u>
Date: <u>8 APR</u>	<u>40</u>	
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station # _____



US Sport Planes 4700 Spartan Dr. Denton, TX 76207 940-597-6860

Year: \_\_\_\_\_  
Date: \_\_\_\_\_  
Next Inspector Due: \_\_\_\_\_  
Year: \_\_\_\_\_  
Date: \_\_\_\_\_  
Next Inspection Due: \_\_\_\_\_

Registration: N450PR S/N: 139 Mfg.: DEUTCH RONALD J Yr/Model: 2004 / Jabiru J450 Engine 3300A S/N 33A675  
Date: 10-04-2018 Total AC Time: 183.5 Engine TT: 183.5 Prop: Jabiru 4A484DOD TT Hub front 4A482POD S/N0361, rear 4A482MOD S/N0361; Blades 4A484DOD S/N0470 and 0481 TT: 31.8  
**Prop:** Performed an annual 100hr/condition inspection in accordance with Jabiru Propeller Technical Manual. Prop removed, dis-assembled, inspected, balance checked, re-installed. Hub inspected for cracks. Increased prop blade pitch to 22 degrees (+.75) at position 508 mm from rotation axis. Torqued mount bolts to 16 nm; Torqued Clamp Bolts to 11 nm. Checked prop track: under 1 mm. Inspected Spinner and Backplate with no defects found. I certify this work has been performed in accordance with the Jabiru Propeller Technical Manual JPM0001-5 dated June 8, 2016 and was found to be in a condition for safe operation at this time.

For US Sport Planes by: Scott Severen A&P #3543489 *[Signature]* Date: 10-04-2018

		Mech. Cert. # or Repair Station # _____
--	--	---

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2004	Total Time in Service	Description INSTALLED ON NY50PR
Date: 11/10	0.0	
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		Ronald Newell

Year: 2004	Total Time in Service	Description CHECKED FOR CONDITION AND CHECKED TORQUE ON PROP BOLTS. ALL NORMAL
Date: 11/22	5.1	
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		Ronald Newell 3062656

Year: 2005	Total Time in Service	Description CHECKED FOR CONDITION AND RETORQUED PROP BOLTS. ALL NORMAL
Date: 3/31	4.0	
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		Ronald Newell 3062656

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2005	Total Time in Service	Description REPLACED PROPELLER WITH NEW PROPELLER MANUFACTURER: JABIRU TYPE: FIXED PITCH WOODEN DWG. NO. C000202-D60P43 DIAMETER 60" PITCH 53"
Date: 4/23	0	
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		Ronald Newell 3062656

Year: 2007	Total Time in Service	Description CHECKED FOR CONDITION AND <del>RETURNED</del> RETORQUED PROP BOLTS AND CHECKED PROP TRACKING. RETURNED TO SERVICE
Date: 5/18	6.0	
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		Ronald Newell 3062656

Year: 2008	Total Time in Service	Description REPLACED PROPELLER WITH NEW PROP MANUFACTURER: SENSINACH TYPE: GRD ADJ COMPOSITE DIAMETER 62. RETURNED TO SERVICE
Date: 3/20	0	
Next Inspection Due:	Time Since Overhaul	
Mech. Cert. # or Repair Station #		Ronald Newell 3062656

**Propeller Record** General Information

Propeller Manufacturer

~~GT PROPELLERS~~ SENSINASH  
ADJ.

Model

~~GT 2/160/VTP FWSAEISRTFC~~

Type

FIXED PITCH COMPOSITE

Hub Series #

R64Z-2

Blade #

N/S/N  
SN 8924, 8936

Date of Manufacture

JAB Comp. Ground Adj. S. Limited

Hub 4A4BZ MOD SN 0361

BLADE 481 DZ 470  
470 DZ 481

Aircraft Installed On:

Make/Model

JABIRU 7450

Serial #

0139