THE AIRCRAFT MAINTENANCE MAINTENANCE RECORDKEEPING SYSTEM

M35411 Engine Log

PROPELLER

MAINTENANCE RECORDS The subject aircraft was involved in an incident / accident on <u>3/3/2025</u> rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: **7106873824US**.

Signed: Underwriters Salvage Company

Date: 4/1/2025 AIG Aerospace Adjustment Services Inc 3500 Lenox Road, Suite 1100

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
¥		<u> </u>		
				2/09/2024 Hours : Tach 6478.9 SOH 249.0TT 4185.9
			Tail#: No Make: Ly	35411
			REMOVED	coming Model: 0-320-E2D S/N: L-40920-27A COWLING. Wash down engine. Check exhaust system no defects
			Changed oi	Cut filter no metal found at this time. Add 7st abilities in the 1150
		_	Run up ops	filter AA48110-2 Compression test #1 74/80 #2 74/80 #3 74/80 #4 72/80. check good Check engine controls,hoses no defects noted. Clean ir engine baffling ,check timing 25%. Replace air filter BA6108. AD 2017-
		_	found rods r	eworked Aircraft Sphesialties w/s 272728 a 46/48/2020 a
			E L Mcclain	Returned to service.
				J 4203040171A
		<u> </u>		
		-		
				SUB-TOTALS this page

Page No									
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	SIG	DESCRIPTION GNATURE & CERTIFICAT	OF WORK PERI TE NO. OF PERSON			
2623			8	TOTALS be	ght forward rom pr	evious page		(
10/19/6	13	0	H.	6159,4				1-1	
	Date: 10/1	9/2023	Hours: Ta	ach SC	OH 0.00 TT 3866.9		Tail : N35411		
	Make: Lyco	ming		Model: 0-3	320-E2D		S/N: L-40920-27A		
	Name: EL N	AcClain Jr.			Cert: 42	20584817IA			
	Co:				Signed:			* 1	
	Lycoming Overhaul Manual p/n602947. Case sent to Divco Inc. WO 139225 8130-3. 0-320 crankcase repair WO 139225 Divco. Parts sent to Aircraft Specialties for repair crankshaft w/o s278720-1,113s19646 gear w/o s278720-2, 4each rods 78030 ,w/o s278720-3. Cylinder complete assy Sl32006W-A21p new s/n 326w000011426,3126w000011423, 326000011424,326w000011428. New bearings,new oil pump gear p/n sl18109a,sl18110a,oil pump housing sl78531. New rod bolts sl78027 8 ea,nuts sl12186 8ea.Overhauled carb MA-4SPA w/o163V.Slick mags overhauled 4370,4371 s/n K-11345,s/n L-01685,new harness assy p/n KA14001.New engine mounts Barry 4ea p/n 94011-20. New gaskets. Engine installed on N35411.New scatt hoses installed. Controls installed and checked for proper operation. Add 7qt. Phillips type M oil. Run up ops check good. See detail parts list in back of log book I certify that this engine has been inspected I/A/W an annual inspection as per FAR43.13 app(d) and was determined to be in an airworthy condition. Returned to service Company of the control of the contr								
2024 2/6/24	4067,6	79,9	Date : 02/ Tail# : N3		o urs : Tach 6229.3S0 3866.9	OH 79.9 TT 4067	7.6	→	
			Changed of Replace of Run up op plugs,chect c/w at ove been insp	D COWLING. Soil. Cut filter not il filter AA4811 is check good ck timing 25%. In haul. See AE ected I/A/W ar Returned to so	o metal found at this 0-2 Compression te Check engine control Replace air filter Ba 0 compliance list in A 100 hr. inspection a	Check exhaust time. Add 7qt ph st #1 74/80 #2 7 bls,hoses no def 6108. ADs chec VC records. I ce	S/N: L-40920-27A system no defects noted. hillips victory oil 50w. 75/80 #3 72/80 #472/80. fects noted. Clean cked thr 2/16/2024. ADs ertify that this engine has ined to be in an airworthy		
				SUB-TOTAL:	S this page	Dage			

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK	
				TOTALS brought forward from previous page	
W/206		Replace oil Run up ops plugs,check c/w at over	oming COWLING Coming Cowline Cout filter Coming Com	Hours: Tach 6223SOH 78.9 TT 4067.6 Model: 0-320-E2D S/N: L-40920-27A S. Wash down engine. Check exhaust system no defects noted. no metal found at this time. Add 7qt phillips victory oil 50w. 110-2 Compression test #1 76/80 #2 76/80 #3 76/80 #476/80. Id Check engine controls, hoses no defects noted. Clean 8. Replace air filter BA6108. ADs checked thr 2/16/2024. ADs AD compliance list in A/C records. I certify that this engine has an 100 hr. inspection and was determined to be in an airworthy.	
		Ma RE Ch Re Rui plui this	ake: Lycominate: L	Model: 0-320-E2D S/N: L-40920-27A WLING. Wash down engine. Check exhaust system no defects noted. at filter no metal found at this time. Add 7qt phillips victory oil 50w. AA48110-2 Compression test #1 72/80 #2 72/80 #3 76/80 #4 76/80. ack good Check engine controls,hoses no defects noted. Clean gine baffling ,check timing 25%. Replace air filter BA6108. ADs 1/2024. ADs c/w See AD compliance list in A/C records. I certify that been inspected I/A/W an annual inspection and was determined to be condition. Returned to service. AP420584817IA	
				SUB-TOTALS this page TOTALS—Carry forward to next page	

Page No.



MAINTENANCE RECORDS

Aircraft Registration No. N35411 Manufacturer LyComing Model 0320-E2D Design No Serial No. L40920-27A	
Blade Serial No's. 1	
Pitch Range: High Low Feather_ Reverse Governor Manufacturer Model No	
Date installed on aircraft	



(All applicable information must be filled in)

AEROTECH PUBLICATIONS ING.

www.adlog.com PO BOX 1359 / SOUTHOLD, NY 11971-0965 (631) 765-9375 1-800-235-6444

FAX: (631) 765-9359