

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C34R-1

PROPELLER S/N DY4011A

LOGBOOK # 2

The subject aircraft was involved in an incident / accident on 3/7/2025 rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: 8375663967US.

Signed: ***Underwriters Salvage Company***


Date: **4/8/2025**


ALG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100



STOVE & GRILL
WESTON
SANTA BARBARA

January 17 2018

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			<i>Accurate Aviation</i> Santa Barbara, CA 101 Hartley Place Goleta, CA. 93117 (805) 770-2500 <u>PROPELLER LOGBOOK ENTRY</u> REG. #: N32371 Piper PA-32-300 S/N: 32-7540035 Hartzell HC-C3YR-1 S/N: DY4011A Tach Time: 3978.3 Total Time: 886.1 Squawk: Propeller Due For Annual Inspection Corrective Action: Completed Annual inspection. Airworthiness directive biweeklies checked through 2011-07. For further details see Piper Inspection report. All work completed IAW appropriate maintenance & service manuals. I certify this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition. Pertinent details of the work are on file at this FBO under Work Order # 11-1121A. Glenn Fuller  A&P 3493937IA April 8, 2011 END

PROP MODEL: HC-C3YR-1 PROP S/N: DY4011A REG. NO: N32371 WORK ORDER: 12-0781A Accurate Aviation Group Inc. 101 Hartley Place Goleta, CA 93117 Phone: (805) 770-2500 Prop Entries (29) Propeller due for Annual Inspection... Completed Annual Inspection. Checked AD Biweekly's through 2012-08. For further details see Piper inspection report. All work completed referencing appropriate maintenance and service manuals. I certify this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition. Pertinent details of the work are on file at this FBO under work order No 12-0781A. DATE: 5/2/2012 SIGNED:  Work Order: 12-0781A Glenn Fuller A&P 3493937 IA Printed by EBis 3 (datcomedia.com)	DATE: 5/2/2012 A/C TSN: 4050.93 PROP TT: 958.73 TACH: 4050.93
--	--

<u>PROPELLER LOGBOOK ENTRY</u> REG. #: N32371 Piper: PA-32-300 S/N: 32-7540035 Hartzell: HC-C3YR-1 S/N: DY4011A Tach Time: 4159.91 Total Time Since New: 1067.66 Completed Annual inspection, Checked airworthiness directive bi-weeklies through 2013-12. For further details see Piper Inspection report. All work completed IAW appropriate maintenance & service manuals. I certify this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. Glenn Fuller  A&P 3493937 IA June 6, 2013 END

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model HC-C3YR-1

Propeller S/N 044011A

Blade Design _____

Blade S/N's

No. 1 J11351

No. 2 J11348

No. 3 J11352

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Piper

Aircraft Model PA-32-300

S/N 32-7540035

Registration N32371

Santa Barbara, CA

PROPELLER LOGBOOK ENTRY

REG. #: N32371 S/N: 32-7540035

Hartzell HC-C3YR-1 S/N: DY4011A

Tach Time: 3913.4 Total Time: 821.2

Corrective Action: Completed Annual inspection. For further details see Piper Inspection report dated this date. All work completed IAW appropriate maintenance & service manuals.

I certify this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition. Pertinent details of the work are on file at this IA's FBO under Work Order # 10-1271A.

Glenn Fuller

A&P 547741244LA

-END-

March 26, 2010

Hartzell Propeller

Manual No. 115-N

**TIONS
DIRECTIVES,
LETTERS,
S**

[illegible]

25

Hartzell Propeller

Manual No. 115 N

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

SPITFIRE AIRCRAFT MAINTENANCE INC.

300 Moffett Place

Goleta, CA. 93117

(805) 967-4373

DATE

REG: N32371 MAKE: HARTZELL HC-C3YR-1 S/N:DY011A

DATE: 03/05/2008 TACH: 3788.0 TTSN: 695.8

I certify that this propeller has been inspected in accordance with a
Annual inspection and was determined to be in airworthy condition

Glenn Fuller A&P 547741244 IA

SPITFIRE AIRCRAFT MAINTENANCE INC.

300 Moffett Place

Goleta, CA. 93117

(805) 692-8587

REG: N32371 MAKE: HARTZELL HC-C3YR-1 S/N:DY4011A

DATE: 03/12/2009 TACH: 3827.1 TTSN: 734.9

I certify that this propeller has been inspected in accordance with a
Annual inspection and was determined to be in airworthy condition

Glenn Fuller A&P 547741244 IA

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

[illegible]

DATE: 12/8/2006
A/C TSN: 3695.43
PROP TT: 603.18
TACH: 3695.43

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		1  Howard Aviation, Inc. Repair Station No. TO3R874L 1401 Fairplex Drive La Verne, CA 91750 Phone: 909-593-2596 DATE: 11/11/2005 A/C TSN: 3615.14 PROP TT: 522.89 TACH: 3615.14 anner and bulkhead I/A/W service manual. een inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was orthy condition. SIGNED:  Work Order: 15961-10-2005 Robin Howard Printed by EBis 3 (datcomedia.com) Certified Repair Station No. TO3R874L	

Repair Station No. TO3R874L
1401 Fairplex Drive
La Verne, CA 91750
Phone: 909-593-2596

DATE: 11/11/2005
A/C TSN: 3615.14
PROP TT: 522.89
TACH: 3615.14

Inspected propeller, spinner and bulkhead I/A/W service manual.

I certify this propeller has been inspected I/A/W a 100 Hour Inspection and repaired in accordance with current Federal Aviation Regulations and was determined to be in an airworthy condition.

DATE: 11/11/2005

SIGNED:

Robin Howard
Certified Repair Station No. TO3R874L

Work Order: 15961-10-2005

Printed by EBis 3 (datcomedia.com)

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,**

Printed by EBis 3 (datcomedia.com)

ITS

IRK

SIGNATURE

PROP MODEL: HC-C3YR-1
PROP S/N: DY011A
REG. NO: 32371
WORK ORDER:
14721-09-2004



Inspected propeller, spinner and bulkhead I/A/W service manual. Blended nicks out of leading edges of blades.

I certify this propeller has been inspected I/AW a 100 Hour Inspection and was determined to be in an airworthy condition.

SIGNED:

21

Hartzell Propeller

Manual No. 115 N

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
Date <u>3-16-00</u> W/O <u>30182</u>			
I certify that this <u>PROP</u> has been inspected in accordance with a <u>ANNUAL</u> inspection and was determined to be in airworthy condition.			
Total Time <u>67.03</u>	Tach. <u>3179.85</u>		
Mechanic <u>W. A. D. 2055</u>	No. <u>COPR 935C</u>		
① Dress and painted propeller blades.			
NAVAJO AVIATION BUCHANAN FIELD 145 JOHN GLENN DRIVE FAA CHS COPR 935C			
File Center			
Sales Center			
Service Center			

MARCH 2, 2001 TACH: 3205.7 N32371

THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AS PER FAR 43 APPENDIX "D." AND HAS BEEN RETURNED TO SERVICE THIS DATE.

DATE 3/2/01 TACH TIME 3205.7

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A/ ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION AS OF THIS DATE. ALL ADS CHECKED FOR COMPLIANCE THRU ISSUE 05/01

SIGNED David D. Dandeth MAINTENANCE EXPRESS
142572771

NORTH FIELD AVIATION

HANGER L908

OAKLAND AIRPORT

OAKLAND, CA 94621

AIRCRAFT # N32371

DATE: APRIL 29, 1998

TACH: 3092.25

RICHARD K. DODGE

555045849 A&P IA

Richard K. Dodge

INSTALLED FACTORY NEW PROPELLER, SPINNER AND SPINNER BULKHEAD IN ACCORDANCE WITH HARTZELL INSTALLATION INSTRUCTIONS AND STC SA1791GL. OPERATIONAL CHECK SATISFACTORY, RPM WITHIN LIMITS. AIRCRAFT WEIGHT AND BALANCE REVISED. SEE FORM 337 THIS DATE.

END

Hartzell Propeller
Manual No. 115 N

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
, SERVICE LETTERS,
JUSTMENTS**



NAVAJO AVIATION
BUCHANAN FIELD
145 JOHN GLENN DRIVE
FAA CRS COPR 935C

6

Date 3/23/99 W/O 29752

I certify that this PROP has been inspected
accordance with a ANR201 inspection and
was determined to be in airworthy condition.

Total Time 53.0 Tach. 3145.82

Mechanic QAC No. COPR 935C

① Dissent PROP BC 205

ION OF WORK

SIGNATURE