

Handwritten initials or signature

The Standard

RECEIVED

APR 24 1941

N113JB

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>2022</u>	Total Time in Service	Description <u>I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND DETERMINED TO BE IN AIRWORTHY CONDITION</u>
Date: <u>09-29</u>		
Next Inspection Due: <u>TACH</u>	Time Since Overhaul	Mech. Cert. # or Repair Station # <u>Randall Watson IA2819514</u>
<u>154229</u>		

Year: _____	Total Time in Service	N113JB Hartzell HC-A2VK-2 S/N: H-576 Date: November 1, 2023 Tach: 1622.4 Right Propeller
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	Performed 100 hour inspection IAW FAR 43 appendix D. Researched AD's through November 1, 2023. Engine run and leak check good.

Year: _____	Total Time in Service	I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	Christopher Boyd <u>Chris Boyd</u> AP37534611A
		Mech. Cert. # or Repair Station # _____

☐ **HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

Year: 10/09/2021
 Date: Left Tach 1534.31
 Left Propeller LOG N113JB
 Serial Number H-567
 Hartzell HC-A2VK-2/V8433-10

Next Inspection Due: AD 97-48-02R1 Alternative method of compliance for prop extension granted. See letter dated May 7th 2021.

Year: *Randy Walter*
 Date: *A3P 28195H*

Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #
----------------------	---------------------	-----------------------------------

Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2022	Total Time in Service
Date: 8/2	UNK
Next Inspection Due:	Time Since Overhaul
Year:	Total Time in Service
Date:	
Next Inspection Due:	Time Since Overhaul
Year:	Total Time in Service
Date:	
Next Inspection Due:	Time Since Overhaul

8/2/2022
 Blade Serial Nos. C67722, C79917
 Inspected and repaired propeller, Serial No. H576, only as needed to comply with A.D. 97-18-02 R1 in accordance with Hartzell Propeller Service Bulletin 217 Rev. 4 and Hartzell Manuals 172 Rev. 3, 133C Rev. 41, 159 Rev. 80, and 202A Rev. 61. Complied with A.D. 97-18-02 R1 (effective 7/31/2003) in accordance with Hartzell Service Bulletin 217 Rev. 4. Complied with Hartzell Service Bulletins 136 Rev. 1, 217 Rev. 4, 280, 301, and 374 Rev. 1. Complied with Hartzell Service Letters 167, 188, 258 Rev. 1, and 366. Complied with Hartzell Service Instruction 159C Rev. 1.
 Maxwell Aircraft Service, Inc.
 Minneapolis, MN 55429
 CRS# UF2R211L
 Repair Order No. 126618

Conrad E. [Signature]

2382511

☐ **HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

Year: <u>2008</u>	Total Time in Service	Description
Date: <u>3-10</u>	<u>3812.2</u>	
Next Inspection Due: <u>500 hrs</u> <u>5 yrs</u>	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

0/11 July 2002. See Green Card in back of log book.

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: <u>2016</u>	Total Time in Service
Date: <u>6/24</u>	<u>UNK</u>
Next Inspection Due: _____	Time Since Overhaul

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due: _____	Time Since Overhaul

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due: _____	Time Since Overhaul

Description
06/24/2016
Serviced Propeller SN: H-576, only as needed to comply with A.D. 97-18-02 R1 in accordance with Hartzell Propeller Service Bulletin: 217 Rev. 3 and Manuals: 172 Rev. 1, 133C Rev. 32, 159 Rev. 53 and 202A Rev. 52. Complied with A.D. 97-18-02 R1 (effective 7-31-03) in accordance with Hartzell Bulletin: 217 Rev. 3. Complied with Hartzell Bulletins: 136I, 137A, 217 Rev. 3, 280 and 301. Complied with Hartzell Service Letters: 167, 188, 258 Rev. 1 and 324. Complied with Hartzell Instructions: 159C Rev. 1.
Maxwell Aircraft Service, Inc.
Minneapolis, MN 55429
CRS# UF2R211L
Repair Order No. 121194

Conrad P. Mohamed
2386511

Propeller Record General Information

Propeller Manufacturer Hartzell

Model HC-A2VK-2

Hub Series # H-576

Date of Manufacture ?

Type

Blade #

C 67722

C 79917

Make/Model

Serial #

Aircraft Installed On:

Piper Aztec
PA 23-250

27-226