

AIRCRAFT MAINTENANCE RECORDS

N 15363

PROP LOG BOOK



Page No. _____

SUB-TOTAL THIS PAGE

TOTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD

Page No. _____

Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
CARRIED FORWARD →	AFT 2629.5	AIRCRAFT PROPELLER WORKS, INC 506 Charlotte Road, Auburndale, FL 33823 CRS# 4TZR125D PROPELLER S/N <u>CH1319</u> WORK PERFORMED <u>Overhauled</u> PROPELLER M/N <u>HC-C2YK-1BF</u> <u>F8468A-4</u> Propeller overhauled in accordance with Hartzell manuals 159, 202A, 113B and 133C. In compliance with SL-61-366 this propeller uses NYCO GN3058 grease, the use of any other grease during the maintenance of this propeller is prohibited. TTSN: Unknown TSO: 00.0 AD Compliance: No AD's apply to this propeller at this time. PERTINENT DETAILS ON FILE UNDER WORK ORDER: <u>4389P</u> DATE: <u>8/26/2021</u> INSTALLER MUST CONFIRM ELIGIBILITY WITH APPLICABLE TECHNICAL DATA AND INSTALL I/AW FAR 43.9
	SPOT Ø	
10/20/2021	AFT 2629.5 SPOT Ø	Complied with a 100 hour inspection on this propeller. I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition. <i>Ulfar Sant</i> A/P 2626167 08

Posada Aviation LLC (954) 822 0546 posadaaviation@gmail.com
A/C: N15363 Tach: 1577.64 Hobbs: 1521.2 Date: 01/13/2022
Hartzell HC-C2YK-1BF/F8468A-4 S/N: CH1319

Performed Annual inspection of the propeller. Lubed w/ aeroshell 6 per propeller service manual. Checked compliance with all applicable AD's; dataBases updated January 10th, 2022 as of Biweekly 2022-01/-02. I certify that this propeller was inspected I/AW Annual inspection per 14 CFR 43 Appendix D and was found to be in an airworthy condition. RTS by


Nicolas Posada
Nicolas Posada Castaneda A&P 36908901A

POSAV LLC (813) 377 3089 niko@flyposav.com
A/C: N15363 Tach: 1753.0 Old Hobbs: 1737.4 New Hobbs: 0.0 TSPOH: 194.72 Date: 03/01/2024
Hartzell HC-C2YK-1 S/N CH1319

Performed Propeller annual inspection in reference to manufacturer's recommendations and inspection criteria of Piper PA-28-235 Service Manual P/N 753586, Dated February 27, 2004. Replaced corroded safety wire on propeller w/ new IAW AC.43.13-1B; verified security of installation. AD compliance verified through Feb 2024. See AD compliance records this date for details. I certify that this propeller has been inspected IAW an annual inspection scope and detail of FAR 43 Appendix D and was determined to be in an airworthy condition. RTS by,

Nicolas Posada
Nicolas Posada Castaneda A/P #36908901A

TOTAL - CARRY FORWARD TO NEXT PAGE



The Standard

PROPELLER LOG

ASA-SP-L

Global Aero Maintenance Inc.
Tampa, FL 33610



6530 Tampa Executive Airport Rd
813-753-4020

N15363 – 2/28/18 – TACH: 1552.9 – ACTT: 2624.2 – ENG TSO: 620.3 – COMPLIED WITH A 100HR INSPECTION ON THIS PROP.

"I CERTIFY THAT THIS PROPHAS BEEN INSPECTED IAW A 100HR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION."

Ne

The above maintenance has been performed IAW current FAR's and Manufacturers Maintenance Instructions and is considered approved for return to service only for the work the performed. Pertinent details are on file at this repair station under WO# VDF18-026.

Name: Eric P. Kunk for CRS# 4GPR388L.

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Date	Total Time	Time Since Overhaul	Description

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
7/10/10	2556.23	552.33	Tech <u>Dressed Blades</u>
1485			

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

I certify as of this date that this Propeller has been inspected in accordance with 100hr inspection and was determined to be airworthy condition. Total Time 2556.23 Tech Time 1485 TSO 552.33

HOWARD KEECH
A&P 32501382 IA

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Date	Total Time	Time Since Overhaul	Description
10/2/11	2564.23	560.33	Tech <u>Dressed Blades</u>
1493			inspect Spinner + Hub

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

HOWARD KEECH
A&P 32501382 IA

I CERTIFY AS OF THIS DATE THAT THIS Propeller HAS BEEN INSPECTED IN ACCORDANCE WITH 100hr inspection and was determined to be in air worthy condition. Total Time 2564.23 Tech Time 1493 TSO 560.33

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

8/19/14 Tech 1485 Removed spinner inspected Hub, spinner and backplate. Greased hub. Inspected Blades. Installed spinner. I certify this propeller has been inspected IAW 100hr inspection and has been determined to be in Airworthy condition.

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

A&P 3700212

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
------	------------	---------------------	-------------

Global Aero Maintenance Inc.
813-600-4053

6530 Tampa Executive Airport Rd
Tampa, FL 33610

N15363 - 11/2/15 - TACH: 1526.97 - PROP. TSO: 594.3 - COMPLIED WITH A 100HR INSPECTION ON THIS ENGINE IAW PA28-235 MM AND FAR 43 APPENDIX D. THE FOLLOWING WORK PERFORMED BY OWNER. DRESSED PROP BLADES. REMOVED PROP TO CHANGE ALTERNATOR BELT, REINSTALLED WITH NEW ORING AND TORQUED. ALLEN CHESTER Allen Chester PILOT # 3484660. I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IAW A 100HR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. REFER TO WO# VDF15-090 FOR DETAILS.

ERICH KNEES Erich Knees A&P 2928839.

Global Aero Maintenance Inc.
Tampa, FL 33610

6530 Tampa Executive Airport Rd
813-753-4020

N15363 - 1/13/17 - TACH: 1530.7 - ACTT: 2602.0 - PROP TSO: 598.1 COMPLIED WITH A 100HR INSPECTION ON THIS PROP IAW PIPER PA28-235 MM. REFER TO WO# VDF17-003 FOR DETAILS.

"I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IAW A 100HR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION."

ANDREW SHELTON Andrew Shelton A&P 3441176.

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
9-14-02	2441.28	437.43	C/W Annual Inspection
I certify That This Prop has been inspected in accordance with Annual inspection and is Airworthy Condition.			
Next Inspection Due: 9-03 Mech. Cert. # or Repair Station # 379325421 JA 2nd Bldg			

Date	Total Time	Time Since Overhaul	Description
12-21-03	2485.5	481.65	C/W Annual Inspection. Applied Prop Grease to Serts Inspected Prop for nicks OK spinner & backplate for cracks OK.
I certify, that this prop has been inspected IAW Annual Inspection and is in Airworthy condition			
Next Inspection Due: 12-04 Mech. Cert. # or Repair Station # AP375824419 IA Mike Henry			

Date	Total Time	Time Since Overhaul	Description
1-12-05	2516.84	512.99	C/W Annual Inspection Replaced 1 outer grease sert. Applied prop grease, Inspected and Filed nicks OK spinner & backplate OK. This prop was inspected IAW an Annual Inspection and is in Airworthy Condition
Next Inspection Due: 1-06 Mech. Cert. # or Repair Station # Mike Henry AP375824419 IA			

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
5/18/06	2537.72	523.87	C/W annual Inspection and found in Airworthy Condition. Mike Henry AP375824419 IA
Next Inspection Due: Mech. Cert. # or Repair Station #			

Date	Total Time	Time Since Overhaul	Description
2-10-08	2537.12		OK FOR RETURN TO SERVICE
Next Inspection Due: Mech. Cert. # or Repair Station # John Chen AP348348986			

Date	Total Time	Time Since Overhaul	Description
July 1 2009	2549.04		OK FOR RETURN TO SERVICE. John Chen AP348348986
Next Inspection Due: Mech. Cert. # or Repair Station #			

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
5-1-97	2185.86	182.02	C/w Annual Inspection Lubricated + Painted Scc.
6-9-95	2185.86		

I certify that this Prop has been inspected in accordance with _____ Mech. Cert. # or Repair Station # _____

Next Inspection Due: _____

Annual inspection and was determined to be in airworthy condition.

Date 6-9-95 Certificate # 379325921 IA

Signature Harold D. Hays

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Date	Total Time	Time Since Overhaul	Description
6-15-96	2216.95	213.11	C/w Annual Inspection

Next Inspection Due: _____ Mech. Cert. # or Repair Station # Harold D. Hays FA 379325921 IA

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
7-1-97	2263.06	259.50	C/w Annual Inspection + Painted Scc.
	2263.06		

Signature Harold D. Hays

Next Inspection Due: Annual Mech. Cert. # or Repair Station # 379325921 IA

Date	Total Time	Time Since Overhaul	Description
8-14-98	2307.06	303.21	C/w Annual Inspection Lubricated + Inspected Hub - Back plate + Spinner

Signature Harold D. Hays

Next Inspection Due: Annual Mech. Cert. # or Repair Station # 379325921 IA

Date	Total Time	Time Since Overhaul	Description
12-27-99	2375.00	371.15	C/w Annual Inspection

Next Inspection Due: Annual Mech. Cert. # or Repair Station # Harold D. Hays 379325921 IA

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
2-21-92	2003.85	0	overhauled by H/S Prop Shop
Invoice No 23160			Oakland Pontiac Airport
AP379325921JA			6220-B-Row Waterford MI
Next Inspection Due: 2000 hrs. Mech. Cert. # or Repair Station #			

Date	Total Time	Time Since Overhaul	Description
4-16-93	2104.83	100.16	Annual Inspection Painted Sides + Lubricated
Hub. I certify That This Prop has been inspected in accordance with			
Annual Inspection and was determined to be in airworthy condition.			
Next Inspection Due: 4-16-94 Mech. Cert. # or Repair Station #			

Date	Total Time	Time Since Overhaul	Description
Next Inspection Due: Mech. Cert. # or Repair Station #			

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
5-22-94	2163.51	159.66	Removed Prop To install Alternator drive belt
Replaced Prop + Set Sundry Mounting Bolts Checked Spinner Hub Plate.			
I certify that this Prop			
Next Inspection Due: been inspected in accordance with Mech. Cert. # or Repair Station #			

Date	Total Time	Time Since Overhaul	Description
Annual inspection and was determined to be in airworthy condition.			
Date 5-22-94 Certificate # AP379325921JA			
Signature <u>Michael D. Harty</u>			
Next Inspection Due: Mech. Cert. # or Repair Station #			

Date	Total Time	Time Since Overhaul	Description
Next Inspection Due: Mech. Cert. # or Repair Station #			

Propeller Manufacturer.

Model HC-C2YK-1

Type

Hub Series # CH-11319

Blade #

C; 21793

Date of Manufacture:

C 21759

Make/Model

Serial #

Aircraft Installed On:

Piper

PA 28-235

28-7310039