

The subject aircraft was involved in an incident /
accident on 3/27/2026 rendering it a Constructive Total
Loss as not repairable within its insured value. For
further details refer to insurance claim: 1680760116US.

Signed: *Underwriters Salvage Company*

Date: **6/23/2026**

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-334F-1RF

PROPELLER S/N FP91176

LOGBOOK # 1

Date	Propeller	A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
------	-----------	-----	--

03-16-2026<>N41CA<>PHC-J3YF-1RF<>Propeller Logbook<>SN:FP9117B<>PTT:673.1

Performed the following maintenance items:

1. Performed annual/100hr. inspection and lube, per Cirrus SR 22 AMM Scheduled Inspection Report 05-20, and Hartzell Owner's Manual 115N, sections 5 & 6.
2. Dressed minor nicks and erosion on propeller blades.
3. AD's checked through 2026-05, see AD list for details.

I certify that this propeller has been inspected in accordance with an annual hr. inspection under FAR91.409(f3) and is approved for return to service. Pertinent details are on file at this agency under invoice number :PST-26-0261.

Date: 03-16-2026 Signature:  Ryan Grenhoff




I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed.




Date: 03-16-2026 Signature:  Ryan Grenhoff

Byerly Aviation, Inc. Greater Peoria Airport, Peoria 61607



FAA Approved Repair Station 9BYR810B

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				<p align="center">01-25-2024<>N41CA<>PHC-J3YF-1RF<>Propeller Logbook<>SN:FP9117B<>PTT:566.8</p> <p>Performed the following maintenance items:</p> <ol style="list-style-type: none"> 1. Performed annual/100hr. inspection and lube, per Cirrus SR 22 AMM Scheduled Inspection Report 05-20, and Hartzell Owner's Manual 115N, sections 5 & 6. 2. AD's checked through 2024-01, see AD list for details. <p>I certify that this propeller has been inspected in accordance with an annual hr. inspection under FAR91.409(f3) and is approved for return to service. Pertinent details are on file at this agency under invoice number :SHO-24-6229.</p> <p>Date:01-25-2024 Signature: <u></u> Ryan Grenhoff</p> <p>I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed.</p> <p>Date:01-25-2024 Signature: <u></u> Ryan Grenhoff</p> <p>Byerly Aviation, Inc. Greater Peoria Airport, Peoria 61607  FAA Approved Repair Station 9BYR810B</p>

				<p align="center">02-10-2025<>N41CA<>PHC-J3YF-1RF<>Propeller Logbook<>SN:FP9117B<>PTT:623.0</p> <p>Performed the following maintenance items:</p> <ol style="list-style-type: none"> 1. Performed annual/100hr. inspection and lube, per Cirrus SR 22 AMM Scheduled Inspection Report 05-20, and Hartzell Owner's Manual 115N, sections 5 & 6. 2. AD's checked through 2025-03, see AD list for details. <p>I certify that this propeller has been inspected in accordance with an annual hr. inspection under FAR91.409(f3) and is approved for return to service. Pertinent details are on file at this agency under invoice number :PST-25-0101.</p> <p>Date:02-10-2025 Signature: <u></u> Ryan Grenhoff</p> <p>I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed.</p> <p>Date:02-10-2025 Signature: <u></u> Ryan Grenhoff</p> <p>Byerly Aviation, Inc. Greater Peoria Airport, Peoria 61607  FAA Approved Repair Station 9BYR810B</p>

Date

Propeller

A/C

Description of all operations pertaining to Airworthiness Directives

02-27-2022<>N41CA<>PHC-J3YF-1RF<>Propeller Logbook<>SN:FP9117B<>PTT:432.5

Performed the following maintenance items:

1. Performed annual/100hr. inspection and lube, per Cirrus SR 22 AMM Scheduled Inspection Report 05-20, and Hartzell Owner's Manual 115N, sections 5 & 6.
2. AD's checked through 2022-05, see AD list for details.

I certify that this aircraft has been inspected in accordance with an annual/150hr. inspection under FAR91.409(f3) and is approved for return to service. Pertinent details are on file at this agency under invoice number :SHO-22-5471

Date:02-27-2022 Signature: Naomi Bohm Naomi Bohm

I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed.

Date:02-27-2022 Signature: Naomi Bohm Naomi Bohm

Byerly Aviation, Inc. Greater Peoria Airport, Peoria



FAA Approved Repair Station 9BYR810B

12-12-2022<>N41CA<>PHC-J3YF-1RF<>Propeller Logbook<>SN:FP9117B<>PTT:501.2

Performed the following maintenance items:

1. Performed annual/100hr. inspection and lube, per Cirrus SR 22 AMM Scheduled Inspection Report 05-20, and Hartzell Owner's Manual 115N, sections 5 & 6.
2. AD's checked through 2022-25, see AD list for details.

I certify that this aircraft has been inspected in accordance with an annual/150hr. inspection under FAR91.409(f3) and is approved for return to service. Pertinent details are on file at this agency under invoice number :SHO-22-5820.

Date:12-12-2022 Signature: Ryan Grenhoff Ryan Grenhoff

I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed.

Date:12-12-2022 Signature: Ryan Grenhoff Ryan Grenhoff

Byerly Aviation, Inc. Greater Peoria Airport, Peoria



FAA Approved Repair Station 9BYR810B

Date	Propeller	A/C
	TSN TSO	Hrs

Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

1-22-2020<>N41CA<>PropSN:FP9117B<>Propeller Logbook<>Model:PHC-J3YF-1RF<>PTT:277.3

Performed the following maintenance items:

- 1.Performed annual/100hr. inspection and lube, per Cirrus SR 22 AMM Scheduled Inspection Report 05-20, and Hartzell Owner's Manual 115N, sections 5 & 6.
- 2.AD's checked through 2020-02, see AD list for details.

I certify that this propeller has been inspected in accordance with an annual inspection and determined to be in an airworthy condition. Pertinent details are on file at this agency under invoice number: SHO-19-4649.

Date: 1-22-20 Signature:  Byerly Aviation, Inc. Greater Peoria Airport, Peoria, IL. 61607
FAA Approved Repair Station 9BYR810B

I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed.

Date: 1-22-20 Signature:  FAA Approved Repair Station 9BYR810B



02-02-2020<>N41CA<>PropSN:FP9117B<>Propeller Logbook<>Model:PHC-J3YF-1RF<>PTT:348.9


Performed the following maintenance items:

- 1.Performed annual/100hr. inspection and lube, per Cirrus SR 22 AMM Scheduled Inspection Report 05-20, and Hartzell Owner's Manual 115N, sections 5 & 6.
- 2.AD's checked through 2021-03, see AD list for details.

I certify that this propeller has been inspected in accordance with an annual inspection and determined to be in an airworthy condition. Pertinent details are on file at this agency under invoice number: SHO-21-5039.

Date: 2-2-21 Signature:  Byerly Aviation, Inc. Greater Peoria Airport, Peoria, IL. 61607
FAA Approved Repair Station 9BYR810B

I certify that this work has been inspected and determined to be in airworthy condition and approved for return to service with respect to the work performed.

Date: 2-2-21 Signature:  FAA Approved Repair Station 9BYR810B



PROPELLER MAINTENANCE RECORD

Position ONE

Propeller Model PHC-53YF-1RF

Propeller S/N FP9117B

Blade Design F7693DFB

Blade S/N's

No. 1 L82463

No. 2 L82464

No. 3 L82465

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer Cirrus Design Corp

Aircraft Model SR22

S/N 4559

Registration N41CA