



HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C2YR-1BFP/F8068D

PROPELLER S/N CH41366B

LOGBOOK # 1

The subject aircraft was involved in an incident / accident on 11/29/2024 rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: 2494317601US.

Signed: ***Underwriters Salvage Company***

Date: **7/14/2025**

ALG Aerospace Adjustment Services Inc

3500 Lenox Road, Suite 1100

[illegible]

Date	Propeller TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
6/30/07	0	0	0	Installed this propeller on N110XP. Delbert Sinor 2863750A&P
Propeller inspection for Experimental Aircraft N110XP Date: 12/1/2008 Hobbs: 17.5 I certify that this propeller has been inspected IAW a condition inspection and was found to be in an airworthy condition. Delbert Sinor 2863750A&P/IA. <i>Delbert Sinor</i>				
Propeller inspection for Experimental Aircraft N110XP Date: 1/6/2010 Hobbs: 17.9 I certify that this propeller has been inspected IAW a condition inspection and was found to be in an airworthy condition. Delbert Sinor 2863750A&P/IA. <i>Delbert Sinor</i>				
Propeller inspection for Experimental Aircraft N110XP Date: 2/8/2011 Hobbs: 18.4 I certify that this propeller has been inspected IAW a condition inspection and was found to be in an airworthy condition. Delbert Sinor 2863750A&P/IA. <i>Delbert Sinor</i>				

Propeller inspection for Experimental Aircraft N110XP Date: 3/4/2012 Hobbs: 18.8 I certify that this propeller has been inspected IAW a condition inspection and was found to be in an airworthy condition. Delbert Sinor 2863750A&P/IA. <i>Delbert Sinor</i>				
Propeller inspection for Experimental Aircraft N110XP Date: 4/7/2013 Hobbs: 19.3 I certify that this propeller has been inspected IAW a condition inspection and was found to be in an airworthy condition. Delbert Sinor 2863750A&P/IA. <i>Delbert Sinor</i>				
Propeller inspection for Experimental Aircraft N110XP Date: 5/10/2014 Hobbs: 20.8 I certify that this propeller has been inspected IAW a condition inspection and was found to be in an airworthy condition. Delbert Sinor 2863750A&P/IA. <i>Delbert Sinor</i>				
Propeller inspection for Experimental Aircraft N110XP Date: 6/8/2015 Hobbs: 21.2 I certify that this propeller has been inspected IAW a condition inspection and was found to be in an airworthy condition. Delbert Sinor 2863750A&P/IA. <i>Delbert Sinor</i>				
Propeller inspection for Experimental Aircraft N110XP Date: 6/14/2020 Hobbs: 22.0 I certify that this propeller has been inspected IAW a condition inspection and was found to be in an airworthy condition. Delbert Sinor 2863750A&P/IA. <i>Delbert Sinor</i>				

PROPELLER MAINTENANCE RECORD

HARTZELL PROPELLER INC

Item Number: C2R10800

INSPECTION

Date: 3/28/2007

Work Order #: M501860

Model Number HC-C2YR-1BFP/F8068D																											
Ass'y Ser No. CH41366B		Hydr Unit No. NA		Bulkhead No. NA		Valve No. NA																					
Blade 1 K53485		Blade 2 K53489		Blade 3		Blade 4		Blade 5																			
Blade 6																											
Reverse NA	Start Lock NA	Low Pitch 13.5	High Pitch 31.0	Feather NA	<table border="1"> <thead> <tr> <th>Position</th> <th>Orient</th> <th>Qty</th> <th>St</th> <th>Screw</th> <th>Washer</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>T</td> <td>1</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>H</td> <td>Bck</td> <td>0</td> <td>0</td> <td>2</td> <td>0</td> </tr> </tbody> </table>					Position	Orient	Qty	St	Screw	Washer	1	T	1	0	0	0	H	Bck	0	0	2	0
Position	Orient	Qty	St	Screw	Washer																						
1	T	1	0	0	0																						
H	Bck	0	0	2	0																						
Ref Radius (inches) for angles: 30																											
Comments: Deice Kit: NA																											
Packing Certified By:				Date:																							

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.

Spinner Assembly Part No. _____