

[illegible][illegible][illegible]

²¹Page 1 of 1

October 15, 2004 Rev. 4

[illegible][illegible][illegible]

²¹Page / of /

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	N194AC	64017	672481	676467	ELEFSINA GREECE	16 JAN 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664	No 1 FREE TURBINE		20338.7	
Today	³³ 0.0	³⁴ 0				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				³⁷ Next Phase Due: 20264.4		³⁸ Phase # <u>511</u>
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
³⁹				⁴⁰		
Mechanic Signature		Repair Station # JYDR439F		Pilot (Signature and Certificate No.)		

[illegible][illegible][illegible]

²¹Page 1 of 1

Form RS-005

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.
572 199	E FREE TURBINE	600603	UNK	1919.5	OFF	20258.2
572 199	E FREE TURBINE	DS 572 199 600407	12,256.8	0.0	ON	20258.2
6435-10382-301	SHAFT + GEAR WHEEL ASSY	FM 108	UNK	5455.1	OFF	20258.2
6435-10382-301	SHAFT + GEAR WHEEL ASSY	FM 117	0.0	0.0	ON	20258.2

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
1	N01 FREE TURBINE REQ REPLACEMENT	DS	1	REPLACED N01 FREE TURBINE REF EAC OUT CHAP 72-50-01/400	DS
2	N01 COMPRESSOR REQ N' 2ND STAGE BLADE INSP. \$B JT12 AUG500	DS	2	\$B JT12 AUG500 REV 1 DATED 11 APR 22 C/W REF EAC OUT CHAP 72-30-01/400 B1+2	DS
3	N01 HIGH SPEED SHAFT REQ REPLACEMENT	DS	3	REPLACED N01 HIGH SPEED SHAFT REF EAC OUT CHAP 72-10-01/400	DS
4	POST MAINT CHECK LEG FOR MAINT PERFORMED	DS	4	POST MAINT CHECK CANNOT BE COMPLETED AT THIS TIME. SEE CARRY OVER	DS
5	APP DRIVESHAFT REQ REMOVAL TO LUBE + INSPECT	DS	5	LUBED + INSPECTED REF EAC OUT CHAP 49-10-05/400 + 600	DS
6	DUAL CHECK	AS	6	DUAL CHECK : N01 FREE TURBINE/STEM CHECK HIGH SPEED SHAFT/ APP DRIVE SHAFT 1ST CHECK :  3 APR 2025 2ND CHECK : A. MASON 3 APR 2025	

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number

Aircraft Daily Totals / Inspection Schedule

²¹Page 1 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	N194AC	64017	672 481	676 467	ELEFSINA GREECE	3 APR 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664	N01 F/I		20338.7	
Today	³³ 0.0	³⁴ 0				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # \$III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹			⁴⁰			
Mechanic Signature		Repair Station # JYDR439F	Pilot (Signature and Certificate No.)			

[illegible][illegible][illegible]


²¹Page 2 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	N194AC	6407	672481	676467	ELEFSINA GREECE	3 APR 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664	No 1 FREE TURBINE		20338.7	
Today	³³ 0.0	³⁴ 0				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # \$III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹			⁴⁰			
Mechanic Signature			Repair Station # JYDR439F		Pilot (Signature and Certificate No.)	

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.
6435-10382-301	SHAFT + GEAR WHEEL ASSY	FM-145	5455.1	5455.1	OFF	20258.2
6435-10382-301	SHAFT + GEAR WHEEL ASSY	FM-114	05 0-200K	0.0	ON	20258.2

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
1	No 2 COMPRESSOR REQ N' 2 nd STAGE BLADE INSP. SB JT12 A6500	DS	1	SB JT12 A6500 REV 2 DATED 31 MAR 25 C/W REF EAC OUT CHAP 72-30-01/400 B 1+2	DS
2	No 2 HIGH SPEED SHAFT REQ REPLACEMENT	DS	2	REPLACED NO 2 HIGH SPEED SHAFT REF EAC OUT CHAP 72-10-01/400	DS
3	FIA PRIMARY SERVO FLIGHT CONTROL ROD REQ REMOVAL TO F.O.M.	DS	3	REMOVED AND RE-INSTALLED FIA PRIMARY SERVO FLIGHT CONTROL ROD REF EAC OUT CHAP 07-00-01/400	DS
4	DUAL CHECK	DS	4	DUAL CHECK SYSTEMS: No 2 Comp Assy / No 2 H.S.S. / FIA FLIGHT CONTROL 1 st  DATE: 5 APR 25 2 nd A.M. DATE: 5 APR 25	
5	RETURN TO SERVICE REQ FOR MAINT PERFORMED	DS	5	MAINT PERFORMED IS APPROVED FOR RETURN TO SERVICE AT AFTT 20258.2  RSJYDR439F. AIRCRAFT IS NOT APPROVED	

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number
SB64B35-10	11 DEC 12	SEL 2	PASSED	20258.2	20348.2	 RSJYDR439F
SB64B20-7	9 APR 12	SEL 2	PASSED	20258.2	20273.2	 RSJYDR439F

Aircraft Daily Totals / Inspection Schedule

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
564E	N194AC	64017	672 481	676 467	ELEFSINA GREECE	5 APR 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ 0.0	³⁴ 0				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # 5 III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹ Mechanic Signature			⁴⁰ Repair Station # JYDR439F		Pilot (Signature and Certificate No.)	

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.
\$B1111-601	BEARING	EAC34884	190.1	0.0	OFF	20,258.2
\$B1111-601	BEARING	EAC34885	190.1	0.0	OFF	20,258.2
\$B1111-601	BEARING	EAC34886	190.1	0.0	OFF	20,258.2
\$B1111-601	BEARING	EAC34887	190.1	0.0	OFF	20,258.2
\$B1111-601	BEARING	EAC34888	190.1	0.0	OFF	20,258.2
\$B1111-601	BEARING	EAC34809	0.0	0.0	ON	20,258.2
\$B1111-601	BEARING	EAC34810	0.0	0.0	ON	20,258.2
\$B1111-601	BEARING	EAC34811	0.0	0.0	ON	20,258.2
\$B1111-601	BEARING	EAC34812	0.0	0.0	ON	20,258.2
\$B1111-601	BEARING	EAC34813	0.0	0.0	ON	20,258.2

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
1	No 6 TRDS REQ'S REPLACEMENT	AM	1	REPLACED No 6 TRDS P/N 6435-60202-043 IN REF TO MM EAC007 CHP 65-10-01 P400	AM
2	No 1-5 TRDS BEARINGS REQ REPLACEMENT	AM	2	REPLACED 5 EA TRDS BEARINGS IN REF TO MM EAC007 CHP 65-10-03 P400	AM
3	MAINT. ITEMS 1 & 2 REQ'S POST MAINT CHECKS	AM	3	POST MAINT CHECKS CANNOT BE PERFORMED AT THIS TIME. SEE CARRY OVER MAINT.	AM
4	DUAL CHECK REQ'D FOR MAINT. ITEMS 1 & 2.	AM	4	DUAL CHECK System Checked <u>TRDS, TRDS</u> <u>BEARINGS</u> 1st Check <u>A. Maslin</u> Date <u>7 APR 25</u> 2nd Check <u>STH</u> Date <u>7 APR 25</u>	

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number

Aircraft Daily Totals / Inspection Schedule

²¹Page 1 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	N194AC	64017	072 481	676 467	ELEFSINA GREECE	7 APRIL 25
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ 0.0	³⁴ 0				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # 5TH	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹			⁴⁰			
Mechanic Signature		Repair Station # JYDR439F	Pilot (Signature and Certificate No.)			

2. 4.

2. 4.

⁸ No.	
------------------	--

AD/SB/Insp

²¹Page 2 of 2

²²A/C Mod

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
1	No 1 & No 2 GENERATOR RETAINING NUT REQ INSP.	AM	1	REMOVED & RE-INSTALLED GENERATORS IN REF TO MM EAC007 CHAPTER 24-20-02 P400. LOCKING MECHANISM FOUND SATISFACTORY	AM PS
2	No 1 & No 2 GENERATOR DRIVE VESPALS REQ REPLACEMENT.	AM	2	REPLACED 2 EA VESPAL P/N 6435-11730-001 IN REF TO MM EAC007 CHAPTER 24-20-02 P400	AM
3	No 1 & No 2 ENGINE COMPRESSOR WASH IS DUE.	AM	3	PERFORMED No 1 & No 2 COMPRESSOR WASH REF MM EAC007 CHAPTER 72-00-01 P700.	AM
4	MRH TORQUE CHECK REQ'D	AM	4	TORQUE CHECKED MRH REF EAC007 CHAPTER 62-20-01 P600	AM
5	TGB CHIP PLUG REQ'S REPLACEMENT.	AM	5	REPLACED 1 EA TGB CHIP PLUG P/N A7260W IN REF TO MM EAC007 CHAPTER 65-20-10 P400.	AM

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number
\$B64B15-4	21JAN15	SEC 2 / 2.4	GOOD	20258.2	OCT 8, 2025	A. MAZUR R:JYDR439F
\$B64B15-8C	28JUL00	SEC 2	GOOD	20258.2	20288.2	A. MAZUR R:JYDR439F

Aircraft Daily Totals / Inspection Schedule

²¹Page 1 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	9 APRIL 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ Ø	³⁴ Ø				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹			⁴⁰			
Mechanic Signature		Repair Station # JYDR439F	Pilot (Signature and Certificate No.)			

Parts Removed / Installed

[illegible]

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
6	MRB'S REQ INSTALL.	AM	6	INSTALLED 6 EA MRB REF MM EAC007 CHAPTER 62-10-01 P400	AM
7	DUAL CHECK REQ'D FOR MAINT. ITEMS 4 & 6.	AM	7	DUAL CHECK System Checked <u>MRH, MRB</u> 1st Check <u>A. M. SW</u> Date <u>9 APR 25</u> 2nd Check <u>[Signature]</u> Date <u>9 APR 25</u>	
8	RETURN TO SERVICE REQ'D FOR MAINT. PERFORMED	AM	8	MAINT. PERFORMED IS APPROVED FOR RETURN TO SERVICE AT AFTT 20258.2 RSJYDR439F . AIRCRAFT IS NOT APPROVED.	

[illegible]

Aircraft Daily Totals / Inspection Schedule

²¹Page 2 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	NI94AC	64017	672481	676467	ELEFSINA, GREECE	9 APRIL 2023
Total Time		Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.
Lift Off	²⁹	20258.2	³⁰	13664		
Today	³³	Ø	³⁴	Ø		
Shut Down	³⁵	20258.2	³⁶	13664		
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				³⁷ Next Phase Due: 20264.4		³⁸ Phase # \$ III
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
³⁹				⁴⁰		
Mechanic Signature		Repair Station # JYDR439F		Pilot (Signature and Certificate No.)		

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
1	No 2 ENGINE CHIP DETECTOR REQ ⁵ REPLACEMENT.	AM	1	REPLACED ^{1EA} No 2 ENGINE CHIP DETECTOR PN 3307671 REFERENCING MM EAC007 CHAPTER 31.00.03 P400. OPS CHK GOOD	AM
2	LEFT MLG OUTER WHEEL BEARING & CONE REQ REPLACEMENT.	AM	2	REPLACED 1 EA WHEEL BEARING PN 39250-20629 & 1 EA CONE PN 39412-20629 IN REF TO MM EAC007 CHAPTER 32.40.01 P400(B).	AM
3	LEFT MLG WHEEL BRAKE KEY REQ ⁵ REPLACEMENT.	AM	3	REPLACED 1 EA WHEEL BRAKE KEY PN 259-39 IN REF TO MM EAC007 CHAPTER 32.40.08 P400(B).	AM
4	NOSE WHEEL INB BEARING & CONE & OB BEARING REQ REPLACEMENT.	AM	4	REPLACED 1 EA INB BEARING PN 18790-2629, 1 EA INB CONE PN 19628 AM 1926B-2-629, 1 EA OUTB BEARING PN 18720-20629 IN REF TO MM EAC007 CHAPTER 32.40.02 P400.	AM

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number
\$B64B15-9	15 DEC 06	SEC 2	GOOD	20258.2	20273.2	A. MAZU RSJYDR439F
\$B64B15-10	1 APR 13	SEC 2	GOOD	20258.2	20,303.2	A. MAZU RSJYDR439F

Aircraft Daily Totals / Inspection Schedule

Page 1 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$G4E	N194AC	64017	672481	676467	ELEFSINA, GREECE	12 APRIL 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ Ø	³⁴ Ø				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # <u>III</u>	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹			⁴⁰			
Mechanic Signature		Repair Station # JYDR439F	Pilot (Signature and Certificate No.)			

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
5	LEFT MLG WHEEL BRAKE HYDRAULIC HOSE & FITTING'S REQS REPLACEMENT.	AM	5	REPLACED 1 EA HYDRAULIC HOSE PN AE3660000E0860, 1 EA UNION PN A\$5174J0404, 1 EA UNION PN A\$5174D0404 IN REF TO MM EAC007 CHAPTER 32.40.08 P406(B).	AM
6	TAIL ROTOR BLADES REQ INSTALL.	AM	6	INSTALLED 4 EA TAIL ROTOR BLADE REF MM EAC007 CHAPTER 64.10.01 P400.	AM
7	DUAL CHECK REQ'D FOR MAINTENANCE PERFORMED	AM	7	DUAL CHECK System Checked NOSE LG WHEEL & TIRE, MLG WHEEL & TIRE ASSY, TAIL ROTOR BLADES 1st Check <u>A. HANSEN</u> Date 12 APR 25 2nd Check <u>[Signature]</u> Date 12 APR 25	
8	RETURN TO SERVICE REQ'D FOR MAINT PERFORMED	AM	8	MAINT. PERFORMED IS APPROVED FOR RETURN TO SERVICE AT AFTT 20258.2 <u>[Signature]</u> RSJYDR439F. AIRCRAFT IS NOT APPROVED.	

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number

Aircraft Daily Totals / Inspection Schedule

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	12 APRIL 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ Ø	³⁴ Ø				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # \$III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
Mechanic Signature			Repair Station # JYDR439F		Pilot (Signature and Certificate No.)	

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
1	POST MAINT CHECKS REQ FOR No 1 F/T REPLACEMENT. SEE AML 3 APR 2025 & CARRY OVER MAINT.	DS	1	PERFORMED POST MAINT. CKREF MM EAC007 CHAPTER 72-50-01 P400 & TABLE 601. SEE ATTACHED SHEET.	AM
2	POST MAINT. CHECKS REQ FOR No 6 TROS & TROS BEARINGS REPLACEMENT. SEE AML 5 APR 2025 & CARRY OVER MAINT.	AM	2	PERFORMED POST MAINT CHKS REF MM EAC007 CHAPTER 65-10-01, P400 & MM EAC007 CHAPTER AM P400	AM DS
3	No 1 & No 2 TORQUE CAL A DUE.	AM	3	PERFORMED No 1 & No 2 TORQUE CAL A REF MM EAC007 CHP 77-10-08 P500.	AM
4	300 HR LUBE DUE	AM	4	PERFORMED 300 HR LUBE REF EAC007 CHP 12-21-01 FIG 301.	AM
5	RETURN TO SERVICE REQ'D FOR MAINT. PERFORMED.	AM	5	MAINT PERFORMED IS APPROVED FOR RETURN TO SERVICE AT AFTT 20258.2 RSTYDR439F- AIRCRAFT IS NOT APPROVED	

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number

Aircraft Daily Totals / Inspection Schedule

²¹Page 1 of 4AM.2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	14 APR 25
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ Ø	³⁴ Ø				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # \$III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹			⁴⁰			
Mechanic Signature		Repair Station # JYDR439F	Pilot (Signature and Certificate No.)			

[illegible][illegible][illegible]

²¹Page 2 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
AN 64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	14 APR 25
Total Time		Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.
Lift Off		²⁹ 20258.2	³⁰ 13664			
Today		³³ Ø	³⁴ Ø			
Shut Down		³⁵ 20258.2	³⁶ 13664			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				³⁷ Next Phase Due: 20264.4		³⁸ Phase # III
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
³⁹				⁴⁰		
Mechanic Signature		Repair Station # JYDR439F		Pilot (Signature and Certificate No.)		

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
1	No 1 ENG IDLE REQ'S ADJUSTMENT	AM	1	ADJUSTED No 1 ENGINE IDLE REF MM EAC007 CHP 76-10-04 P500.	AM
2	150 HR PHASE DUE	DS	2	certify this aircraft has been inspected IAW DCO #RS-003 EAC S-64E Phase inspection program and approved for return to service. A 150 HR inspection was completed at AFTT 20258.2 on 15 APR 2025 RSJYDR439F by 	
3	No 1 OUTBOARD EXCITER BOX NOT WORKING ON COMPRESSOR	DS	3	REPLACED No 1 COMPRESSOR HARNESS ASSY P/N 6455-40026-303 REV D. REF EAC007 CHAP 71-50-01/400	DS
4	ELT FUNCTION TEST REQ	DS	4	ELT FUNCTION TEST 912 REF FAR 91.207	DS
5	DUAL CHECK FOR MAINT PERFORMED	DS	5	DUAL CHECK SYSTEM: IDLE ADJ. / ENG HARNESS 1st:  DATE: 15 APR 25 2nd: A. M. DATE: 15 APR 25	

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number

Aircraft Daily Totals / Inspection Schedule

Page 1 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
564E	N194AC	64017	672481	676467	ELEFSINA, GREECE	15 APR 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ 	³⁴ 				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # <u>III</u>	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹			⁴⁰			
Mechanic Signature		Repair Station # JYDR439F	Pilot (Signature and Certificate No.)			

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

²¹Page 2 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
664E	N194AL	64017	672481	676467	ELEFSINA GREECE	15 APR 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ 6.6	³⁴ 0				
Shut Down	³⁵ 20258.2	³⁶ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20264.4		³⁸ Phase # \$ III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹			⁴⁰			
Mechanic Signature		Repair Station # JYDR439F	Pilot (Signature and Certificate No.)			

Aircraft Maintenance LogBook

Parts Removed / Installed	
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	NI94AC	64017	672481	676467	ELEFSINA, GREECE	16 APR 25
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20258.2	13664				
Today	Ø	Ø				
Shut Down	20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 202732		Phase # 1	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
A. MAZOW A-P 3738304						
Mechanic Signature		Certificate No.	Pilot (Signature and Certificate No.)			

Parts Removed / Installed

¹ Part Number	² Nomenclature	³ S/N	⁴ T.S.N.	⁵ T.S.O.	⁶ Off/On	⁷ A/C T.T.

Maintenance Actions

⁸ No.	⁹ Aircraft Discrepancies	¹⁰ Initials	¹¹ No.	¹² Action Taken	¹³ Initials
1	POST MAINT. CHECKS REQ FOR IDLE ADJ ON No1 COMPRESSOR & ENGINE HARNESS REPLACEMENT. SEE AML 15 APR 2025 & CARRY OVER MAINT.	AM	1	PERFORMED POST MAINT. CHKS FOR IDLE ADJ IN REF MM EAC007 CHP 72-00 02 P 200 FIG 201. PERFORMED POST MAINT CHKS FOR ENGINE HARNESS REPLACEMENT BY PERFORMING GROUND RUN. OPS CHK GOOD.	AM
2	TAIL ROTOR BALANCE REQ'D	AM	2	PERFORMED TAIL ROTOR BALANCE IN REF TO MM EAC007 CHP 64-10-01 P 500.	AM
3	EAC AML REQ'S CLOSING STATEMENT DUE TO CHANGE OF OWNERSHIP.	AM	3	ERICKSON INCORPORATED IS TERMINATING THEIR MAINT. RESPONSIBILITIES FOR AIRCRAFT N194AC SIN 64017 AFTT 20258.2 TOTAL CYCLES 13664 ON 16 APR 2025. LAST COMPLETED INSP. WAS FAA APPROVED ERICKSON INC. OWNER/OPERATOR PHASE INSP RS-003 ALL PHASES, ALL ZONES COMPLETED @ AFTT 20258.2. ON 15 APR 2025, HELICOPTER EXPRESS IS NOW RESPONSIBLE FOR MAINT AND INSP REFER TO HELICOPTER EXPRESS AIRCRAFT MAINT. LOGBOOK FOR FUTURE MAINT. & INSP. IT IS THE RESPONSIBILITY OF HELICOPTER EXPRESS TO DESIGNATE THE NEXT INSP PROGRAM.	

¹⁴ AD/SB/Inspection	¹⁵ Rev Date	¹⁶ Compliance Method	¹⁷ Results	¹⁸ ACTT	¹⁹ ACTT/Date Next Due	²⁰ Signature & Cert Number
3364B15-3	24 MAY 76	SEC 2	GOOD	20258.2	20408.2	A. M. W. RSTYDR439F

Aircraft Daily Totals / Inspection Schedule

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	16 APR 2025
Total Time	Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.	
Lift Off	²⁹ 20258.2	³⁰ 13664				
Today	³³ 0.0	³⁴ 0.0				
Shut Down	³⁵ 202.58.2	³⁵ 13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			³⁷ Next Phase Due: 20273.2		³⁸ Phase # 5 I	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
³⁹ A. M. W. Mechanic Signature			⁴⁰ RSTYDR439F Repair Station # JYDR439F		Pilot (Signature and Certificate No.)	

[illegible][illegible][illegible]

²¹Page 2 of 2

²² A/C Model	²³ N- Number	²⁴ A/C S/N	²⁵ L Engine S/N	²⁶ R Engine S/N	²⁷ Location Name	²⁸ Date
\$64E	NI94AC	64017	672481	676467	ELEFSINA, GREECE	16 APR 25
Total Time		Aircraft	Cycles	³¹ Parts Due Off <200 Hrs		³² Due @ A/C T.T.
Lift Off	²⁹	20258.2	³⁰	13664		
Today	³³	Ø	³⁴	Ø		
Shut Down	³⁵	20258.2	³⁶	13664		
	The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				³⁷ Next Phase Due: 20273.2	³⁸ Phase # 5I
					Aircraft has been pre-flighted and/or test flown and is returned to service.	
³⁹				⁴⁰		
A. N. ANN		RSJYDR439F				
Mechanic Signature		Repair Station # JYDR439F		Pilot (Signature and Certificate No.)		

Parts Removed / Installed

[illegible]

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1	TAIL ROTOR PC LINK HARDWARE REQ'S CLEANING & ANTI-CORROSION COMPOUND	AM	1	CLEANED & APPLIED ANTI-CORROSION COMPOUND TO TAIL ROTOR PC LINK HARDWARE REF EAC 007 CHAPTER 64.20.05 P400.	AM
2	STINGER ATTACHING HARDWARE REQ'S CLEANING & ANTI-CORROSION COMPOUND	AM	2	CLEANED & APPLIED ANTI-CORROSION COMPOUND TO STINGER ATTACHING HARDWARE IN REF TO EAC007 CHAPTER 32.70.01 P400.	AM
3	RH & LH LOWER OBSERVATION WINDOWS REQ REPLACEMENT.	AM	3	REPLACED LH OBSERVATION WINDOW PIN: 6420-61332-301 & RH OBSERVATION WINDOW PN: 6420-61332-302 IN REF TO EAC007 CHAPTER 56.10.04 P400	AM
4	S.S.O.E DUE FOR MAINT ITEMS 1-3.	AM	4	SSOE COMPLETED BY <i>Steve May</i> AIP 3728058	ST

[illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	21 APR 25
Total Time		Aircraft		Cycles		Parts Due Off <200 Hrs
Lift Off		20258.2		13664		Due @ A/C T.T.
Today		Ø		Ø		
Shut Down		20258.2		13664		
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.					Next Phase Due: 20273.2	
					Phase # 51	
Aircraft has been pre-flighted and/or test flown and is returned to service.						
A. MAZAN			A.P 3738304			
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]Aircraft Daily Totals / Inspection Schedule Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
564E	N194AC	64017	672481	676467	ELEFSINA , GREECE	25/APR/25
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off		20258.2	13664			
Today		Ø	Ø			
Shut Down		20258.2	13664			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 1
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
A+P 5110399						
Mechanic Signature		Certificate No.		Pilot (Signature and Certificate No.)		

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
S-64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	29/APR/2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20.258.2	13664				
Today	Ø	Ø				
Shut Down	20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20273.2		Phase # 51	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
 AIP 5110399						
Mechanic Signature		Certificate No.	Pilot (Signature and Certificate No.)			

Aircraft Maintenance LogBook

[illegible][illegible]

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1	AFT STROBE LIGHT COVER CRACKED	AW	1	REPLACED AFT STROBE LIGHT ASSY. P/N 65 6455-10305-101 REF EAC 007, REV 41, 33-40-02, OPS CHECK GOOD <i>(Signature)</i> AEP 4956956, AFTT 20258.2, 05/02/2025 S.S.O.E. COMPLETED BY <i>AW</i> . ATP 5110399	
2	AIRCRAFT FIRE EXTINGUISHER MONTHLY INSP. DUE	P.A.	2	PERFORMED AIRCRAFT FIRE EXTINGUISHER PA MONTHLY INSP. IN REF MMAMEREX NFPA - 10 <i>(Signature)</i> - ATP 5110399 02/MAY/2025, AFTT 20258.2 NO DEFECTS	

[illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	2/MAY/25
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20258.2	13664				
Today	Ø	Ø				
Shut Down	20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20273.2		Phase # \$1	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
Mechanic Signature <i>Adam Ward</i> AEP 4956956			Certificate No. Pilot (Signature and Certificate No.)			

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

Aircraft Daily Totals / Inspection Schedule							Page	of
A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date		
S-64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	5/MAY/2025		
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.		
Lift Off	20258.2		13664					
Today	0		0					
Shut Down		20258.2	13664					
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 1		
				Aircraft has been pre-flighted and/or test flown and is returned to service.				
 AIP 5110399								
Mechanic Signature			Certificate No.	Pilot (Signature and Certificate No.)				

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1	#1 ENGINE FUEL HEATER FWD MOUNT FOUND LOSE.	AW	1	TIGHTENED FWD. FUEL HEATER MOUNT & SAFETIED REF. P/N 435107, REV. 44 11/JAN/2021, SEC. 2-236 Adam Ward AEP 4956956, 6/MAY/25 AFTT. 20258.2 SSOE COMPLETED BY <i>AW</i> . A+P 5110399	
2	RIGHT BRAKE CALIPER NICK BLENDING REQUIRED	P.A	2	BLENDED NICK ON RIGHT BRAKE CALIPER IN REF. EAC 007, REV 41 15/DEC/2023 32-10-00 PAR A(C) <i>PA</i> . A+P 5110399, 6/MAY/2025 AFTT 20258.2 SSOE COMPLETED BY <i>Stannley</i> HP 3728058	

[illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

Aircraft Daily Totals / Inspection Schedule							Page	of
A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date		
\$-64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	6/MAY/2025		
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs			Due @ A/C T.T.		
Lift Off	20258.2	13664						
Today	Ø	Ø						
Shut Down	20258.2	13664						
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20273.2			Phase # \$1		
			Aircraft has been pre-flighted and/or test flown and is returned to service.					
Adam O'Kard AEP 4956956								
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)			

Parts Removed / Installed	
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

[illegible]

Maintenance Actions

[illegible][illegible]Aircraft Daily Totals / Inspection Schedule Page 1 of 1Page 1 of 1

Aircraft Daily Inspection Schedule							Page 1 of 1
A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date	
5-64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	8/MAY/2025	
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off		20258.2	13664				
Today		Ø	Ø				
Shut Down		20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 1	
				Aircraft has been pre-flighted and/or test flown and is returned to service.			
 A+P 5110399							
Mechanic Signature			Certificate No.	Pilot (Signature and Certificate No.)			

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions


[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

Aircraft Daily Total / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
S-64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	9/MAY/2015
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off		20258.2	13669			
Today		Ø	Ø			
Shut Down		20258.2	13664			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 51
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
 AIP 5110399						
Mechanic Signature		Certificate No.		Pilot (Signature and Certificate No.)		

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
564E	N194AC	64017	672481	676467	ELEFSINA, GREECE	11/MAY/2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20258.2	13664				
Today	Ø	Ø				
Shut Down	20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20273.2		Phase # 51	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
Adam Kard AP 4956956						
Mechanic Signature		Certificate No.	Pilot (Signature and Certificate No.)			

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 2

Page 1 of 2

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$-G4E	N194AC	64017	672481	676467	ELEFSINA, GREECE	18/MAY/2025
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off	20258.2		13664			
Today	Ø		Ø			
Shut Down		20258.2	13664			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # \$1
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
Mechanic Signature			Certificate No.	Pilot (Signature and Certificate No.)		

Parts Removed / Installed

Part Number	Nomenclature	S/N	T.S.N.	T.S.O.	Off/On	A/C T.T.

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1413	FWD & MIDDLE FIRETANK ACCUMULATOR PRESSURE GUAGES REQ REPLACEMENT.	AM	1413	REMOVED 3 EA. ACCUMULATOR BY REMOVING 3 EA. HYDRUALIC LINES. REPLACED 2 EA PRESSURE GUAGES PN M528061-T7 IN REF TO MM EAC009 CHP 93-10-02 P 800. REV 9 DEC 30, 2022. RE-INSTALLED IN REVERSE ORDER. A.M. W A.P 3738304 AFTT 20258.2. 18 MAY 2025. SSOE COMPLETED BY <u> </u> A/P 3550755	
4	SLEEVE AND SPINDLE ASSY ON GREEN MRB REQ REPLACEMENT	DS	4	MAINT CANNOT BE COMPLETED AT THIS TIME SEE CARRY OVER MAINT. AIRCRAFT IS ADG. <u> </u> 18 MAY 25 A/P 3550755	

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number

Aircraft Daily Totals / Inspection Schedule Page 2 of 2

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	18 MAY 25
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20258.2	13664				
Today	Ø	Ø				
Shut Down	20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20273.2		Phase # \$1	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1	1 EA MRB (GREEN) REQ REMOVAL TO F.O.M.	DS	1	REMOVED GREEN MAIN ROTOR BLADE REF EAC007 PARA W G2-10-01 PARA 400 REV 41 15/DEC/2025, Adam Ward AEP 4956956, AFTT 20258.2, 19 MAY 2025 SSOE COMPLETED BY [Signature] ATP 3550755	
2	GREEN MAIN ROTOR SLEEVE AND SPINDLE ASSY. REQUIRES REMOVAL	AW	2	REMOVED GREEN MAIN ROTOR SLEEVE AND SPINDLE ASSY. REF EAC007 REV W G2-20-04 PARA 400 REV 41 15/DEC/2025, Adam Ward AEP 4956956, AFTT 20258.2, 19/MAY/2025, SSOE COMPLETED BY [Signature] ATP 3550755 AIRCRAFT IS NOT APPROVED FOR RETURN TO SERVICE	

[illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA GREECE	19 MAY 25
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20258.2	13664				
Today	0.0	0				
Shut Down	20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 202732		Phase # \$1	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions	

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	21 MAY 2024
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20258.2	13664				
Today	0.0	0				
Shut Down	20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20273.2		Phase # \$1	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	22 MAY 2023
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20258.2	13664				
Today	Ø	Ø				
Shut Down	20258.2	13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 1
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
Mechanic Signature		Certificate No.		Pilot (Signature and Certificate No.)		

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	24 MAY 25
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off		20258.2	13664			
Today		Ø	Ø			
Shut Down		20258.2	13664			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 1
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
Mechanic Signature				Certificate No.		Pilot (Signature and Certificate No.)

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date		
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	26 MAY 25		
Total Time		Aircraft		Cycles		Parts Due Off <200 Hrs	Due @ A/C T.T.	
Lift Off		20258.2		13664				
Today		Ø		Ø				
Shut Down		20258.2		13664				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.						Next Phase Due: 20273.2		Phase # \$1
						Aircraft has been pre-flighted and/or test flown and is returned to service.		
Mechanic Signature						Certificate No.		Pilot (Signature and Certificate No.)

Aircraft Maintenance LogBook

Parts Removed / Installed	
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

[illegible]

Maintenance Actions				
No.	Align & Displacement			

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1	3 CRACKS ON #2 ENGINE FREE TURBINE CASE	AW	1	WELDED 2 EA. CRACKS ON OUTER SKIN FLOATING VANE AREA AT 5 O'CLOCK POSITION AND 1 EA. CRACK ON THE OUTER SKIN FLOATING VANE AREA AT 8 O'CLOCK POSITION REF. M/M #435107 REV/DATE, 43, JAN 2024 (SRI) EAC-Q-01-204, REVH, SEE WORK ORDER (ERICKSON INC.) # 211218, 18 JUN 2025, AFTT 20263.3 SSOE COMPLETED BY Adams - Ward A+P 4956956	
2	#2 ENGINE TOP FIREWALL REQUIRES REMOVAL FOR MAINTENANCE	AW	2	REMOVED AND INSTALLED #2 ENGINE TOP FIREWALL REF EAC007, REV 41, 15-DEC-2023, 71-30-01, Adams Ward A+P 4956956, AFTT 20263.3, 18 JUN 2025 SSOE COMPLETED BY <i>[Signature]</i> A+P 5110399	
3	HARDWARE REMOVAL REQUIRED TO FACILITATE MAINTENANCE	P.A	3	REMOVED AND REINSTALLED 1 each BOLT ON # 2 FREE TURBINE	

[illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 2

Page 1 of 2

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
SG4E	N1944C	64017	672481	676467	IELEFSINA GREECE	18 JUNE 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20263.3	13668				
Today	0	0				
Shut Down	20263.3	13668				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20273.2		Phase # ⁵⁷ 51	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
Mechanic Signature			Certificate No.		441 6892	
					Pilot (Signature and Certificate No.)	

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

Aircraft Daily Status / Inspection Schedule							Page	Of
A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date		
564E	N194AC	64017	672481	676467	ELEFSINA, GREECE	20 JUN 2025		
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.		
Lift Off	20263.3		13668					
Today	2.1		1					
Shut Down		20265.4	13669					
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 31		
				Aircraft has been pre-flighted and/or test flown and is returned to service.				
 AIP 3550755				 4416892				
Mechanic Signature		Certificate No.		Pilot (Signature and Certificate No.)				

Parts Removed / Installed

[illegible][illegible][illegible]

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
504E	N194AC	64017	672481	676467	ELEFSINA, GREECE	22/JUNE/2025
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off		20265.4	13669			
Today		4.2	4			
Shut Down		20269.10	13673			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 51
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
 AIP 3550755				 441 6892		
Mechanic Signature		Certificate No.		Pilot (Signature and Certificate No.)		

Parts Removed / Installed

[illegible][illegible]

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 OCT 13	SEC F3 + F4	PASSED	20269.6	20272.6	 ADP 3550755
SB64B85-7	14 AUG 17	SEC 2B	PASSED	20269.6	DAILY	 ADP 3550755
AD2013-23-07	30 OCT 17	SEC F3	PASSED	20271.6	20274.6	 ADP 3550755
AD2013-23-07	30 OCT 13	SEC F3	PASSED	20275.7	20276.7	 ADP 3550755
SB64B20-7	9 APR 12	SEC 2	PASSED	20275.7	20300.7	 ADP 3550755
SB64B15-9	15 DEC 06	SEC 2	PASSED	20275.7	20300.7	 ADP 3550755

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
564E	N194AC	64017	672481	676467	CHIOS, GREECE	23-June 2025
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off		20269.6	13673			
Today		6.1	3			
Shut Down		20295.7	13674			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 51
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
 ATP 3556755				 4416892		
Mechanic Signature				Pilot (Signature and Certificate No.)		

Parts Removed / Installed

[illegible][illegible]

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 OCT 13	SEC F3/F4	PASSED	20275.7	20278.7	 A.P. 3550755
SB64B85-7	14 AUG 17	SEC 2B	PASSED	20275.7	DAILY	 A.P. 3550755
AD2013-23-07	30 OCT 13	SEC F3	PASSED	20277.8	20280.8	 A.P. 3550755
AD2013-23-07	30 OCT 13	SEC F3	PASSED	20279.8	20282.8	 A.P. 3550755
AD2013-23-07	30 OCT 13	SEC F3	PASSED	20281.8	20284.8	 A.P. 3550755
AP2013-23-D7	30 OCT 13	SEC F3	PASSED	20,283.9	20,288.9	A. Guider AP4801051
AD2013-23-07	30 OCT 13	SEC F3	PASSED	20285.7	20288.7	A. Guider AP4801051
SB64B15-9	15 DEC 06	SEC 2	PASSED	20285.8	20300.8	 A.P. 3550755
SB64B20-7	9 APR 12	SEC 2	PASSED	20285.8	20300.8	 A.P. 3550755
SB64B15-9C	28 JAN 00	PARA 2A	PASSED	20285.8	20315.8	 A.P. 3550755

Page 1 of 1

Aircraft Daily Inspection Schedule							Page 1 of 1
A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date	
\$64E	N194AC	64017	672481	676467	CHIOS, GREECE	24 June 2005	
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off		20275.7	13676				
Today		10.1	6				
Shut Down		20285.8	13682				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20288.2		Phase # PI	
				Aircraft has been pre-flighted and/or test flown and is returned to service.			
 AH 3556755				 4416892			
Mechanic Signature				Pilot (Signature and Certificate No.)			

Aircraft Maintenance LogBook

Parts Removed / Installed	
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
564E	N194AC	64017	672 481	676467	CHIOS, GREECE	25 Jun 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20285.8	13682				
Today	4.0	4				
Shut Down	20289.8	13686				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20303.2		Phase # \$II	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
 AIP 3550755			 4416892			
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	

Parts Removed / Installed

[illegible]

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1	30 HR LUBE REQ'D	AM	1	30 HOUR LUBE C/W REF EAC 007 CHP 12-21-01 FIG 301 A.M.A.W. A.P. 3738304 AFTT 20297.1 26 JUNE 2025. S.S.O.E. COMPLETED BY Jaid ~ 429485495	
2	COMP WASH REQ'D FOR #1 & #2 COMPRESSORS	AM	2	#1 & #2 COMP WASH C/W REF EAC 007 CHP 72-00-01 P 700. A.M.A.W. A.P. 3738304 AFTT 20297.1 26 JUNE 2025. S.S.O.E. COMPLETED BY Jaid ~ 429485495	

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 Oct 13	SEC F3/F4	PASSED	20289.8	20292.8	[Signature] ATP35507SS
\$B64B85-7	14 MAR 17	SEC 2B	PASSED	20289.8	DAILY	[Signature] ATP35507SS
AD2013-23-07	30 Oct 13	SEC F3	PASSED	20291.7	20294.7	[Signature] ATP35507SS
AD2013-23-07	30 Oct 13	SEC F3	PASSED	20293.7	20296.7	[Signature] ATP35507SS
AD2013-23-07	30 Oct 13	SEC F3	PASSED	20295.3	20298.3	[Signature] ATP35507SS
\$B64B20-7	9 APR 12	SEC 2	GOOD	20297.1	20312.1	A. HAWK A-P3738304
\$B64B35-9	15 DEC 06	SEC 2	GOOD	20297.1	20312.1	A. HAWK A-P3738304
\$B64B15-10	1 APR 13	SEC 2	GOOD	20297.1	20342.1	A. HAWK A-P3738304

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

Aircraft Daily Totals / Inspection Schedule							Page 1 of 1
A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date	
564E	N194AC	64017	672481	676467	CHIOS, GREECE	26 JUNE 2005	
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20289.8		13686	RIGHT LATERAL SERVO		20486.5	
Today	7.3		4				
Shut Down		20297.1	13690				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20303.2		Phase # 57	
				Aircraft has been pre-flighted and/or test flown and is returned to service.			
A. Masun				A.P 3738304			
Mechanic Signature				Pilot (Signature and Certificate No.)			

Parts Removed / Installed

Part Number	Nomenclature	S/N	T.S.N.	T.S.O.	Off/On	A/C T.T.

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 OCT 13	SEC F3 + F4	PASSED	20297.1	20297.1 20300.1	A. M. W. A.P 3738304
SB64385-7	14 AUG 17	SEC 23	PASSED	20297.1	DAILY	A. M. W. A.P 3738304

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	29 Jun 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20297.1	13690	RIGHT LATERAL SERVO		20486.5	
Today	.1	1				
Shut Down	20297.2	13691				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20303.2		Phase # \$II	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	
 ATP 3550755			441 6892			

Aircraft Maintenance LogBook

Parts Removed / Installed

Part Number	Nomenclature	S/N	T.S.N.	T.S.O.	Off/On	A/C T.T.

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1	MAG RPM SENSOR WAS ELECTRICAL WIRING FOUND TO BE BROKEN.	AM	1	REPAIRED ELECTRICAL WIRING FOR MAG RPM SENSOR REF A350881 REV H JAN 13, 2023. SE ATP 355075 28 JUN 2025 AFTT 20297.2 SSOE COMPLETED BY A. WABW A.P 3738304	
2	1 EA TORQUE KEY ON LEFT MLG BRAKE ASSY REQ'S REPLACEMENT	AM	2	REPLACED 1 EA TORQUE KEY PN 259-39 IN REF TO EAC007 CWP 32-40-01 P400 REV 41, 15 DEC 2023. Adam Ward ATP 4956956, 28 JUN 2025, ACTT 20297.2 SSOE COMPLETED BY A. WABW A.P 3738304	
3	FIRE EXTINGUISHER MONTHLY INSPECTION DUE	AM	3	I CERTIFY THE MONTHLY AIRCRAFT FIRE EXTINGUISHER INSP HAS BEEN PERFORMED I/A/W AMEREX MANUAL 14425 & NFPA-10 AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. A. WABW A.P 3738304 AFTT 20297.2, 28 JUNE ^{JULY} 2025 INSP NEXT DUE ON 27 JULY 2025	

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 OCT 13	SEC F31F4	PASSED	20297.2	28 JUN 2025	SE ATP 355075
5864885-7	14 AUG 17	SEC 2B	PASSED	20297.2	DAILY	SE ATP 355075

Aircraft Daily Totals / Inspection Schedule

Page 1 of 2

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
564E	N194AC	64017	672481	676467 4040	ELEFSNA GREECE	28 JUN 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20297.2	13691	R/L SERVO		20486.5	
Today	Ø	Ø				
Shut Down	20297.2	13691				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20303.2		Phase # 9II
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
Mechanic Signature			Certificate No.	Pilot (Signature and Certificate No.)		

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 2 of 2

Aircraft Daily Totals / Inspection SchedulePage 2 of 2

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
SG4E	N194AC	64017	GT2481	GT6467	BEPSINA, GREECE	18/JUNE/2025
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off		20263.3	13668			
Today		Ø	Ø			
Shut Down		20263.3	13668			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20273.2		Phase # 51
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
 AJP 5110399						
Mechanic Signature		Certificate No.		Pilot (Signature and Certificate No.)		

Aircraft Maintenance LogBook

Parts Removed / Installed	
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

[illegible]

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
4.	GREEN POSITION ADJUSTABLE PC LINK GREASE FITTING ORIENTATION INCORRECT.	AM	4	RE-ORIENTATED GREEN ADJUSTABLE PC LINK GREASE FITTING REF EAC007 CAP 62-20-10 P400 REV 41 15 DEC 2023 Adam O'Kard A/P 4956956, 28 JUN 2025 ACTT 20297.2 SSOE COMPLETED BY A. M W A.P 3738304	
5	RIGHT BAM POSITION PILOT COLLECTIVE FRICTION LOCK FEELS "RATCHETY".	AM	5	REPLACED RIGHT POSITION PILOT FRICTION LOCK 2 EA COLLETS PN 6440-61418-101 REF EAC007 CAP 67-10-10 P400 & P500. REV 41 15 DEC 2023 A. M W A.P 3738304 SSOE COMPLETED BY Adam O'Kard A/P 4956956 AFTT 20297.2 28 JUNE 2025	

[illegible]

Aircraft Daily Totals / Inspection Schedule Page 2 of 2

Page 2 of 2

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
564E	N194AC	64017	672481	676467	ELEFSINA, GREECE	28 JUN 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20297.2	13691	R/L SERVO		20486.5	
Today	Ø	Ø				
Shut Down	20297.2	13691				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20303.2		Phase # 5II	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
A. Masun A.P 3738304						
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	

Parts Removed / Installed	

[illegible]

Maintenance Actions	

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
564E	N194AC	64017	672481	676467	ELEFSINA, GREECE	29 JUNE 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20297.2	13691	R/L SERVO		20486.5	
Today	Ø	Ø				
Shut Down	20297.2	13691				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20303.2		Phase # 511	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
4N A.P 3738304						
Certificate No.			Pilot (Signature and Certificate No.)			

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	NI94AC	64017	672481	676467	ELEFSINA, GREECE	1 July 2025
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off		20297.2	13691	R/L SERVO		20486.5
Today		00	0			
Shut Down		20297.2	13691			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20303.2		Phase # \$II
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
 AIP 3550755						
Mechanic Signature			Certificate No.	Pilot (Signature and Certificate No.)		

Parts Removed / Installed

[illegible][illegible]

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 OCT 13	F3 + F4	GOOD	20297.2	20,300.2	A. Maw AP3738304
SB64B85-7	14 AUG 17	SEC 2B	GOOD	20297.2	DAILY	A. Maw A.P 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20298.8	20301.8	A. Maw A.P 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20299.4	20302.4	4416892
AD2013-23-07	30 OCT 13	F3	GOOD	20301.3	20304.3	A. Maw A.P 3738304
SB64B20-7	9 APRIL 12	SEC 2	GOOD	20301.3	20316.3	A. Maw A.P 3738304
SB64B15-9	15 DEC 06	SEC 2	GOOD	20301.3	20316.3	A. Maw A.P 3738304

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELFEINA, GREECE	2 JULY 2023
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs			Due @ A/C T.T.
Lift Off	20297.2	13691	R/L PRI SERVO			20486.5
Today	4.1	3				
Shut Down	20301.3	13694				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20303.2		Phase # \$H	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
1A-P 3738304			4416892			
Mechanic Signature			Pilot (Signature and Certificate No.)			

Parts Removed / Installed

[illegible][illegible]

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 OCT 13	F3 + F4	GOOD	20301.3	20304.3	A. Mason A.P 3738304
SB64B85-7	14 AUG 17	SEC 2B	GOOD	20301.3	DAILY	A. Mason A.P 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20303.2	20306.2	A. Mason A.P 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20305.2	20308.2	A. Mason A.P 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20307.3	20310.3	A. Mason A.P 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20309.4	20312.4	A. Mason A.P 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20310.5	20313.5	A. Mason A.P 3738304
SB64B20-7	9 APR 12	SEC 2	GOOD	20310.5	20325.5	A. Mason A.P 3738304
SB64B15-9	15 DEC 06	SEC 2	GOOD	20310.5	20325.5	A. Mason A.P 3738304
SB64B15-8C	7 MAR 24	SEC 2	GOOD	20310.5	20340.5	A. Mason A.P 3738304
SB64B15-10	1 APR 13	SEC 2	GOOD	20310.5	20355.5	A. Mason A.P 3738304

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	CHANIA, GREECE	3 JULY 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20301.3	13694	R/L SERVO		20486.5	
Today	9.2	5				
Shut Down	20310.5	13699				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20318.2		Phase # II	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
W. MAJAW A.P 3738304			4416892			
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	

Aircraft Maintenance LogBook

Parts Removed / Installed	

[illegible]

Maintenance Actions	

[illegible]

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 OCT 13	F3 + F4	GOOD	20310.5	20313.5	A. Maslow A.P. 3738304
SB64B85-7	14 AUG 17	SEC 2B	GOOD	20310.5	DAILY	A. Maslow A.P. 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20312.6	20315.6	A. Maslow A.P. 3738304
AD2013-23-07	30 OCT 13	F3	GOOD	20314.8	20317.8	A. Maslow A.P. 3738304
AD2013-23-07	30 OCT 13	F3	PASSED	20316.8	20319.8	A. Maslow A.P. 3550775
SB64B15-09	15 DEC 06	SEC 2	PASSED	20317.3	20332.3	A. Maslow A.P. 3550775
SB64B20-7	9 APR 12	SEC 2	PASSED	20317.3	20332.3	A. Maslow A.P. 3550775

Aircraft Daily Totals / Inspection Schedule Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	HERAKLION, GREECE	4 JULY 2025
Total Time		Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.
Lift Off		20310.5	13699	R/L SERVO		20486.5
Today		6.8	4			
Shut Down		20317.3	13703			
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.				Next Phase Due: 20318.2		Phase # II
				Aircraft has been pre-flighted and/or test flown and is returned to service.		
 AIP 355075J				EDWIN AUL 3248502 AIP		
Mechanic Signature		Certificate No.		Pilot (Signature and Certificate No.)		

Aircraft Maintenance LogBook

Parts Removed / Installed	
Part Number	

[illegible]


Maintenance Actions				
No	Aircraft Discrepancy	Location	Date	Remarks

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
964E	N194AC	64017	672481	676467	ELEFSINA, GREECE	5 JULY 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20317.3	13703	R/L PRIMARY SERVO		20486.5	
Today	Ø	Ø	No 1 FC4		20510.7	
Shut Down	20317.3	13703				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20318.2		Phase # PII	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
						
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	

Aircraft Maintenance LogBook

Parts Removed / Installed

[illegible]

Maintenance Actions

[illegible][illegible]

Aircraft Daily Totals / Inspection Schedule

Page 1 of 1

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	NI94AC	64017	672481	676467	ELEFSINA, GREECE	7 JULY 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20317.3	13703	R/L PRIMARY SERVO		20486.5	
Today	Ø	Ø	No! FCU		20516.7	
Shut Down	20317.3	13703				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20,333.2		Phase # \$ III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
A. MAZOW Mechanic Signature			A.P. 3738304 Certificate No.		Pilot (Signature and Certificate No.)	

Parts Removed / Installed

Part Number	Nomenclature	S/N	T.S.N.	T.S.O.	Off/On	A/C T.T.

Maintenance Actions

No.	Aircraft Discrepancies	Initials	No.	Action Taken	Initials
1	APP SPEED SWITCH OIL SEAL IS LEAKING.	AM	1	REPLACED 1 EA OIL SEAL PN: 8677 1 EA GASKET PN: A53491-01 ON APP SPEED SWITCH REF EAC067 CHAPTER 49-30-05 P400 REV 41, 15 DEC 2023 A.MANUW A.P 3738304, AFTT 20317.3 8 JULY 2025. SSOE COMPLETED BY Tony Worbel A/P 3855252	
2	UPPER SEASNORKEL CRADLE ASSY BRACKET CRACKED & REQ'S REPLACEMENT.	AM	2	REPLACED 1 EA GUSSET PN: 10555-005 REF EAC012 CHAPTER 93-30-01 P400 G(3) REV 9, 30 DEC 2022 Tony Worbel A/P 3855252, AFTT 20317.3 on 8 July 2025, S.S.O.E. COMPLETED BY A.MANUW A.P 3738304	
3	SEA SNORKEL REF LINE REQ	DS	3	SEA SNORKEL REF LINE APPLIED REF CSL 25-003 DATED 6/29/25 DS A/P 3855255 AFTT 20317.3 8 JULY 2025. S.S.O.E C/W Tony Worbel A/P 3855252	

AD/SB/Inspection	Rev Date	Compliance Method	Results	ACTT/ Date	ACTT or Date Next Due	Signature/Cert Number
AD2013-23-07	30 OCT 13	SEC F3+F4	PASSED	20317.3	20320.3	 A/P 3855255
\$B64B85-7	14 AUG 17	SEC 2B	PASSED	20317.3	DAILY	 A/P 3855255

Aircraft Daily Totals / Inspection Schedule

A/C Model	Reg. Number	A/C S/N	L Engine S/N	R Engine S/N	Location Name	Date
\$64E	N194AC	64017	672481	676467	ELEFSINA, GREECE	8 JULY 2025
Total Time	Aircraft	Cycles	Parts Due Off <200 Hrs		Due @ A/C T.T.	
Lift Off	20317.3	13703	R/L PRIMARY SERVO		20486.5	
Today	Ø	Ø	No.1 FOU		20516.7	
Shut Down	20317.3	13703				
The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and is approved for return to service.			Next Phase Due: 20333.2		Phase # \$ III	
			Aircraft has been pre-flighted and/or test flown and is returned to service.			
A. MANUW			A.P 3738304			
Mechanic Signature			Certificate No.		Pilot (Signature and Certificate No.)	