STARTED 10/19/2023

AIRCRAFT MAINTENANCE RECORDS

N 90874

AIRFRAME

LOG BOOK



AIRCRAFT MAINTENANCE RECORD Page No.

Date	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
Nose til	re flat: RR tire an orthy condition w	d tube w new 072-312-0 \$3135T00319 and 6L50678. Aircraft returned to service respect to work completed at this time. Dated: November 21st, 2024. Dated: November 21st, 2024.
RR L ti	re and tube w ne	ew 06-07900 and 06-00754; cleaned, inspected, and repacked wheel bearings. rvice in airworthy condition w respect to work completed at this time.
\$ #4 X	8 - 1 0 N	Elijah Williams AP4846067 CLA LLCAL Dated: November 25th, 2024
	S	SUB-TOTAL THIS PAGE
		OTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD D Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 TACH: 5330.1 HM: 284.7 100 hr insp cw IAW Piper PA28-181 MM & LOM. L brake line lk: RR O-ring w new MS28775-222 for L brake caliper also bled brake for L side. OAT probe corrosion/loose: cleaned corrosion, tightened nut. L pilot RH rudder pedal pad missing: reinstalled L pilot RH rudder pedal pad. L brake worn: RR L brake lining w 2 new 066-10500. LTB corrosion: cleaned corrosion and primed affected area. Cody Haynes AP3348610_ Dated: Aug 15th, 2024. I certify that this aircraft has been inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr inspection, has been found airworthy at this time, and is returned to service. All applicable AD's noted to have been complied with at this time. Cody Haynes AP3348610 Dated: Aug 15th, 2024. Make: Piper Model: PA-28-181 SN: 28-8690014 REG: N90874 TACH: 5259.3 HM: 300.3 Elevator Trim Stuck: Turnbuckle went past pulley; Turnbuckle pulled forward and straightened, trim adjusted on both sides for proper pulley clearance and adjusted aft trim screw; OPS Check – Good; NDN. Airframe corrosion noted on fwd lower part of rudder; Removed corrosion, cleaned and recovered with primer. Landing light INOP; replaced wires with new and installed new 4509 bulb. Upper cowling deformity note; Damage inspection CW. All work Completed IAW Piper PA-28-181 MM and IPC. Dated: August 27th, 2024. Make: Piper Model: PA-28-181 SN: 28-8690014 REG: N90874 TACH: 5412.2 HM: 502.8 Nose strut low: Nose strut removed disassembled and rebuilt with new seal kit PN: TPNS1, serviced with dry nitrogen and Aviation hydraulic fluid 5606 to recommended height and clearance. Ops checked- Good; NDN. All work completed IAW Piper PA-28-181 MM and IPC. Barthelomew Modica 3705278AP Dated: September 9th, 2024. Make: Piper Model: PA-28-181 SN: 28-8690014 REG: N90874 TACH: 5412.2 HM: 502.8 Nose landing gear fairing removed from Aircraft, New Weight and Balance Calculated and installed in POH. All work Completed IAW Piper PA-28-181 MM and IPC. Dated: September 9th, 2024

SUB-TOTAL	THIS PAGE
-----------	-----------

TOTAL - CARRY FORWARD TO NEXT PAGE

AIDODAET MAINTENAMOE BEGOR

	Total Time	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NUMBER OF PERSON PERFORMING WORK
ARRIED		
	Model: DA 39 19	11 SN 28 8500044 PEC MONEY TANK FERRAL WAY
R\H Brake	cylinder O-ring h	1 SN: 28-8690014 REG: N90874 TACH: 5509.8 HM: 99.9 as been replaced with new due to hydraulic leak. PN:MS28775-222
All work Co	mpleted IAW Pip	per PA-28-181 MM and IPC.
		St.
SKY BL	LUE FORM	k Ergur AP4205442 Dated: September 30th, 2024
	Taru	k Ergur AP4205442 Dated: September 30 th , 2024
	r a	G
	R A	
		SN: 28-8690014 REG: N90874 TACH: 5518.6 HM: 0110.6
		- Repaired using fiberglass and resin, reinstalled clipnuts and reinstalled on
		ced with new LED Light PN: 11-129760, ops checked – Good; NDN. Missing installed new lock washer. All work completed IAW Piper, PA-28 MM and IPC.
	To an later lasterier	The state of the s
	B	arthelomew Modica 3705278AP Ja Mallula Dated: October 3rd, 202
	1	
ake: Piper	Aircraft: N90874	Model: PA-28-181 SN: 28-8690014 TACH: 5528.1 HM: 122.0
10 hr insp cv	v IAW Piper PA28-	181 MM & LOM. Cabin heater hose torn: RR w new 63633-208. Air filter
w new BA-	104. Screw on ve	ert stab frozen: drilled out and RR w new. R aileron bellcrank bolt rusted:
w new 401	-289, 404-534, 69	90-612. R aileron rod end corroded: RR w new 452-335; adj for proper missing: RR w new 06-SW10-96. R flap hinges and bolts corroded: RR w
w 401-270	400.444 404 52	1. R main strut lwr section corroded: removed surface corrosion,
spected, tre	ated primed and	recovered w paint. L main lwr section corroded: removed surface
rrosion, inst	pected, treated, p	rimed and recovered w paint. L flap hinges and bolts corroded: RR w new
1-270, 400-	444, 404-534, La	ileron bellcrank bolt rusted: RR w new 401-289, 404-534, 690-612. L
eron rod en	-1 - 1 1 00	이 그리고 하는 어린 이번 경기에 가지 않는 아이들이 되었다. 그는 사람들은 사람들은 사람들은 사람들이 되었다. 그는 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은
	a corroaea: RR w	new 452-335, 401-270, 404-534; adj for proper ops. Both fuel tank gas
ps corroded	with degraded ga	new 452-335, 401-270, 404-534; adj for proper ops. Both fuel tank gas askets: removed surface corrosion, inspected, treated, primed and
covered w n	with degraded ga	askets: removed surface corrosion, inspected, treated, primed and prew 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004,
covered w p	with degraded ga paint; gaskets RR w	askets: removed surface corrosion, inspected, treated, primed and new 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, and Two excessively corroded clip nuts on vert fairing RR w new 04-
covered w p 2-897, 402-	with degraded ga paint; gaskets RR w 890, 404-556, 452	Askets: removed surface corrosion, inspected, treated, primed and which was new 05-18500. R hinge for stabilator exfolilating: RR which mew 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR which mew 04-294. The foliation of the foliation
covered w p 2-897, 402- 152. Radio ach Avionic	l with degraded ga paint; gaskets RR w 890, 404-556, 452 control unit RR w s CRS# M14R363N	Askets: removed surface corrosion, inspected, treated, primed and work new 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm // (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut
covered w p 2-897, 402- 152. Radio ach Avionic	l with degraded ga paint; gaskets RR w 890, 404-556, 452 control unit RR w s CRS# M14R363N	Askets: removed surface corrosion, inspected, treated, primed and work new 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm of (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut dreplaced w new, strut reserviced.
covered w p 2-897, 402- 152. Radio ach Avionic b bolt shear	with degraded ga paint; gaskets RR w 890, 404-556, 452 control unit RR w s CRS# M14R363N ed: drilled out and	askets: removed surface corrosion, inspected, treated, primed and vinew 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-5VC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut direplaced w new, strut reserviced. Dated: Nov 15 th , 2024.
covered w p 2-897, 402- 152. Radio ach Avionics bolt shear	with degraded ga paint; gaskets RR w 890, 404-556, 452 control unit RR w s CRS# M14R363N ed: drilled out and	AP3267745 Dated: Nov 15 th , 2024. Primed and Windows and State Corrosion, inspected, treated, primed and Windows and State Corrosion, inspected, treated, primed and Windows and State Corrosion and State
covered w p 2-897, 402- 152. Radio ach Avionics bolt shear	with degraded ga paint; gaskets RR w 890, 404-556, 452 control unit RR w s CRS# M14R363N ed: drilled out and	AP3267745 Dated: Nov 15 th , 2024. Primed and Windows and State Corrosion, inspected, treated, primed and Windows and State Corrosion, inspected, treated, primed and Windows and State Corrosion and State
covered w p 2-897, 402- 152. Radio ach Avionics bolt shear ertify that the pection, has	with degraded ga paint; gaskets RR w 890, 404-556, 452 control unit RR w s CRS# M14R363N ed: drilled out and	new 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut d replaced w new, strut reserviced. AP3267745 Dated: Nov 15 th , 2024. En inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr orthy at this time, and is returned to service. All applicable AD's noted
covered w p 2-897, 402- 152. Radio ach Avionics bolt shear ertify that the pection, has have been c	with degraded gapaint; gaskets RR was 890, 404-556, 452 control unit RR was CRS# M14R363N ed: drilled out and mis aircraft has been somplied with at the complied with at the complication.	askets: removed surface corrosion, inspected, treated, primed and a new 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm of (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut direplaced w new, strut reserviced. AP3267745 Dated: Nov 15th, 2024. En inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr orthy at this time, and is returned to service. All applicable AD's noted this time.
covered w p 2-897, 402- 152. Radio ach Avionics bolt shear ertify that the pection, has have been c	with degraded gastaint; gaskets RR was 890, 404-556, 452 control unit RR was CRS# M14R363Ned: drilled out and Matthew Hood his aircraft has been somplied with at the earth of the somplied with at the earth of the	askets: removed surface corrosion, inspected, treated, primed and a new 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm of (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut direplaced w new, strut reserviced. AP3267745 Dated: Nov 15th, 2024. En inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr orthy at this time, and is returned to service. All applicable AD's noted this time.
covered w p 12-897, 402- 152. Radio each Avionics p bolt shear ertify that the spection, has have been c	with degraded gapaint; gaskets RR was 890, 404-556, 452 control unit RR was CRS# M14R363N ed: drilled out and mis aircraft has been somplied with at the complied with at the complication.	askets: removed surface corrosion, inspected, treated, primed and a new 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm of (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut direplaced w new, strut reserviced. AP3267745 Dated: Nov 15th, 2024. En inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr orthy at this time, and is returned to service. All applicable AD's noted this time.
covered w p 02-897, 402- 0152. Radio each Avionics p bolt shear ertify that the spection, has have been c	with degraded gapaint; gaskets RR was 890, 404-556, 452 control unit RR was CRS# M14R363N ed: drilled out and mis aircraft has been somplied with at the complied with at the complication.	askets: removed surface corrosion, inspected, treated, primed and a new 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm of (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut direplaced w new, strut reserviced. AP3267745 Dated: Nov 15th, 2024. En inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr orthy at this time, and is returned to service. All applicable AD's noted this time.
covered w p 02-897, 402- 0152. Radio each Avionics p bolt shear ertify that the spection, has have been c	with degraded gapaint; gaskets RR was 890, 404-556, 452 control unit RR was CRS# M14R363N ed: drilled out and mis aircraft has been somplied with at the complied with at the complication.	askets: removed surface corrosion, inspected, treated, primed and vinew 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm VI (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut direplaced w new, strut reserviced. AP3267745 Dated: Nov 15 th , 2024. En inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr orthy at this time, and is returned to service. All applicable AD's noted this time.
covered w p 02-897, 402- 0152. Radio each Avionics p bolt shear ertify that the spection, has have been c	with degraded gapaint; gaskets RR was 890, 404-556, 452 control unit RR was CRS# M14R363N ed: drilled out and mis aircraft has been somplied with at the complied with at the complication.	askets: removed surface corrosion, inspected, treated, primed and vinew 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm VI (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut direplaced w new, strut reserviced. AP3267745 Dated: Nov 15 th , 2024. En inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr orthy at this time, and is returned to service. All applicable AD's noted this time.
covered w p 02-897, 402- 0152. Radio each Avionics p bolt shear ertify that the spection, has	with degraded gapaint; gaskets RR was 890, 404-556, 452 control unit RR was CRS# M14R363N ed: drilled out and mis aircraft has been somplied with at the complied with at the complication.	askets: removed surface corrosion, inspected, treated, primed and vinew 05-18500. R hinge for stabilator exfolilating: RR w new 62645-004, 2-394. Two excessively corroded clip nuts on vert fairing RR w new 04-SVC 066-1055-03 \$2529 due to static com 2 freq. Unit tested by Palm VI (cf WO# 35157 dated 10/31/2024): ops ck good on install. Nose strut direplaced w new, strut reserviced. AP3267745 Dated: Nov 15 th , 2024. En inspected IAW PA28-181 MM, LOM, and 14CFR43 Appdx D for 100 hr orthy at this time, and is returned to service. All applicable AD's noted this time.

TOTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT MAINTENANCE RECORD Page No.

			-
Date	Total Time	DESCRIPTION OF WORK PER SIGNATURE & CERTIFICATE NUMBER OF PERS	
96. Complied wi	d with AD 20-26-16	Model: PA-28-181 SN: 28-8690014 TACH: 5230.3 on: R/H and L/H aileron inboard static wick broken; RR b Section H, No further action needed at this time.AD 76 me. All work Completed IAW Piper PA-28-181 MM and I	HM: 164.4 both with new PN: DW-SW10-
I certify that airworthy at	this aircraft has be	een inspected IAW 14CFR43 Appx D for Annual inspection eturned to service. All applicable AD's noted to have been	on Aircraft has been found
time.	-	11	
	SICY BLUE	Cody Haynes AP3348610IA	5
		Cody Hayries AP3348610IA	Dated: June 17 th , 2024.
DATE OF THE		Model: PA-28-181 SN: 28-8690014 TACH: 5235.3	
Make: Senser OPS Flight per Normal flight performed.	rformed for New of and Landing. Com	engine installation for 5.0hrs , Engine Operated for Normalied with Lycoming Break-in Procedures. No Discrepance of the State of the St	al procedures Tavi Take off
The ATC transfound to meet	t the performance s	and inspected as required by FAR 91.413 and pecification of FAR 43 Appendix F. The standard	
performance s proper corres and found to (c). The aircra	specification of FA pondence and the e meet the performan aft static system wa	as required by FAR 91.411 and found to meet the R 43 Appendix E. The encoder was tested for ncoder/transponder system integration was tested ce specification of FAR 43 Appendix E. paragraph s tested as required by FAR 91.411 and found to	
	FAR 43, Appendix		
Transponder:	Appareo: Stratus E meter: United: 593	SG, S/N 201920	-
	co: AR-500 S/N 25		
		entified above was inspected in accordance with	
		s found airworthy and approved for the return to service.	
n i on the		Qf	
Palm Beach A Work Order: 3		A CRS MI4R363M	
Trans a der		Authorized Signature	
		Li constant de la con	
-			
- 1		SUB-TOTAL THIS PAGE	

TOTAL - CARRY FORWARD TO NEXT PAGE

Date	Total Tin	ne		DESCRIPTION OF WORK PERFORMED CERTIFICATE NUMBER OF PERSON PERFORMING WORK
RRIED ->				
LTIMETER CALIBRAT			6 26 2024	
ORK ORDER NUMBE	MODEL 5934		_	
	ARCO MODEL AR			
AROMETRIC SCALE				
ressure altitude differe plerance +/- 25 ft	ence	Case Leak (3 1 tolerance 100 tt Reading	m" ,	
	Difference 27 - 1715	Reading	11 11/20	
28.50 13 29.00 -8	40 1345	Hysteresis tes	e l	
29 92	92 - 390	60% Max A1 1 40 5 Max A1		
30 90 8	31 535 93 405 74 990	After effect tes	n Result • 15 -	
		ALTITUDE EN		
ALTIMETER ALTITUDE Tol +/-	Error	Actude	er Tolerance +// 125 ft	
-1000 20 0 20 500 20	5	0	+20 15 0 5 +20 10	
1000 20 1500 25	12	1500	+25 10	
2000 30 3000 30 4000 35	15	2000 3000	+30 15	
6000 40 8000 60	- 5	5000	+ 35 35 -	
10000 80 12000 90	-15	10000	50 90	
14000 100 16000 110	-25	19000	+ 65 10 + 70 60	
18000 120 20000 130	145		+20 32	
FRICTION Tol +/-			nerá Avation Airport -	
1000 70 2000 70 3000 70	20	Nest Pain Bear	R F 33412	
3000 70 5000 70 10000 80	40 40	TECH TECH		
15000 90 20000 100	55	INSF	Q.	
	1			
7				TACH: 5262 9 HM: 201.4
				SN: 28-8690014 TACH: 5262.9 HM: 201.4 seals and o rings using Kit PN: TPNS-1, Reserviced with Aviation
Avdraulic flu	v; kemovea s id MII -H- 560	Strut and I	nitrogen to requ	ired parameters: NDN. All work completed IAW Piper PA28-
81 MM and	IPC.			
	CK	WILL OF	E	AP4797485 July Maue Dated: July 11th, 2024
	AV	141,000	Triston Stone	д АР4/9/485_ <u>() (А/АССССССССССССССССССССССССССССССССССС</u>
		1		3-181 SN: 28-8690014 TACH: 5288.7 HM: 233.9
Make: Pi	per Aircraft	t: N90874	Model: PA-2	
Lndg Lt II	NOP due to l	oose wire	e: resecured wir	
SKY W	Barth	elomew	Modica AP3705	278 Later Dated: July 23rd, 2024.
A. V. J. A. T.		1		
an I Dimo	. Aircraft: I	N90874	Model: PA-28-1	.81 SN: 28-8690014 TACH: 5322.8 HM: 277.0
K Main ure fairings ren	noved due to	missing	fasteners. W&I	B recalculated and updated in POH. NAV updated.
idii iliga teli	and a			1/ 1/ 1// 1
BIKE EN	Bartheld	omew Mo	odica AP370527	On Market Guera. Aug July 2024.
WALL STATE				
AVIATO				

TOTAL - CARRY FORWARD TO NEXT PAGE

AIRCRAFT **MAINTENANCE RECORDS**

Owner
Aircraft Registration N 90874
Manufacturer PIPER
Model PA-28-181
Serial No. <u>28-869004</u>
Position

AIRCRAFT MAINTENANCE RECORD DESCRIPTION OF WORK PERFORMED Total Time Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 TACH: 5129.2 Hobbs: 32.3 Co-pilot PTT switch INOP; Complied with RR of Co-pilot PTT switch with new PN: 11-01899. Ops checked- Good; NDN. Alternator belt worn; Complied with RR of alternator belt with new PN: MC73965-015, reinstalled alternator torqued and safety wired bolt, reinstalled propeller torqued and safety wired prop mounting bolts. Gascolator leaking; Complied with RR of gascolator gasket with new PN: 10536-1, reinstalled and safety wired. Ops checked and leak checked - Good; NDN. All work completed IAW PIPER PA-28-181 MM and IPC. Cody Haynes AP3348610IA Dated: October 19th, 2023 Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 TACH: 5186.6 Hobbs: 107.0 Strobe light power supply INOP: Complied with RR of strobe light power supply with new PN: A413A SN: DA.28.04617 IAW PA-28-181 MM and IPC. Bryan Patrick AP4736086 Dated: November 28th, 2023 Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 TACH: 5189.0 Hobbs: 110.2 R/H Brake caliper leaking: RR brake caliper packing with new. Reinstalled caliper and bled brakes. Ops checked-Good; NDN all work completed IAW PIPER PA-28-181 MM and IPC. Bryan Patrick AP4736086 Dated: November 29th, 2023 Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 TACH: 5200.0 Hobbs: 124.6 Landing light breaker keeps popping. Inspected and broken wire found; complied with repair of broken wire. Ops checked- Good; NDN. Nav Database update complied with. Cody Haynes AP3348610IA. Dated: December 5th, 2023 Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 Landing light INOP: Complied with RR of wires with new 14 AWG wires with new connectors and replaced bulb with new PN:4509. Landing gear panes noted to have loose fasteners; Replaced and retorqued fasteners as necessary. Radio static noted when flying; Connectors cleaned and retorqued. Dated: December 15th, 2023 Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 TACH:5228.4 HOBBS: 162.0 L/H MLG tire worn; Removed wheel assembly, disassembled, cleaned and inspected; NDN. Packed bearings with new grease and reassembled wheel with new 6.00-6 6 ply tire, inflated and reinstalled, complied with torque of axle nut, cotter pinned, reinstalled brake caliper and torqued. Wheel fairing latch broken; RR latch assembly with new PN: 472-553. All work completed IAW PIPER PA-28-181 MM AND IPC Cody Haynes AP3348610IA Dated: December 20th, 2023 SUB-TOTAL THIS PAGE

TOTAL - CARRY FORWARD TO NEXT PAGE

Date

N90874 Current log





The Standard

-AIRCRAFT LOG

ARTEX AIRCRAFT SUPPLIES. INC.
14405 Kell Rd. NE Autora, OR 97002
(503) 679-7929 800-547-8901

LOG BOOK ENTRY 10/5/0/

E.L.T. BAITERY
REPLACEMENT DATE

ASA/SA-

MEMORANDA

Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 TACH: 5176.1 HM: 93.1 Complied with 100HR inspection; Nose gear strut leaking; RR of Nose landing gear strut with new seals SN: TPNS-1, serviced with MIL-H-5606 hydraulic fluid and Nitrogen, Ops checked- Good; NDN. Landing light breaker keeps popping; complied with re-termination of broken wire at landing light. Ops checked- Good; NDN. Left Mic jack popping; complied with re-termination of broken wire at landing light. Ops checked- Good; NDN. Left Mic jack popping; Removed mic jack, cleaned reinstalled – Radios removed, cleaned and reinstalled. Ops checked- Good; NDN. Strobe light not working; Strobe light marked as INOP on console. Complied with AD 20-26-16 at this time, factored hours are 398.59. Section H due in next 100HR inspection. All work completed IAW PIPER PA-28-181 MM and IPC.

I certify that this aircraft has been inspected IAW 14CFR43 Appx D for 100HR inspection, Aircraft has been found airworthy at this time, and is returned to service. All applicable AD's noted to have been complied with at this time.

Cody Haynes AP3348610IA

Dated: November 14th, 2023

DATE	TOTAL TIME IN SERVICE	EQUIPMENT ADDITION, REMOVAL OR EXCHANGE ITEM — MFG NAME — MODEL — SERIAL		Make: Piper Aircraft: N90874 Model: PA-28-181 SN: 28-8690014 Hobbs: 5274.7 Lower Rudder bearing worn; RR rudder bearing with new PN452-387. Door hinge pins worn; RR Cabin door hinge pins with new PN: MS20392-343 and installed new cotter pins. Lower stab cable broken; Complied with RR of lower horizontal stabilator control cable with new PN MS20701 212
19	SERVICE	The ATC Transponder tests required by FAR 91.413 have been performed and found to be in compliance with FAR 43 Appendix F. #1 Make Model STRATUS ESG SN: 201920 #2 Make Model SN:	nal Equipment ed—Exchanged for Optional red—Exchanged for Optional nal Equipment ed—Exchanged for Optional red—Exchanged for Optional nal Equipment nal Equipment ed—Exchanged for Optional red—Exchanged for Optional red—Exchanged for Optional nal Equipment nal Equipment nal Equipment red—Exchanged for Optional	horizontal stabilator control cable with new PN: MC62701-012 and complied with recommended cable tensions. Pilot seat gas shock blown out; complied with RR of pilot seat gas shock with new PN: 587-404. Hobbs meter INOP; Complied with RR of Hobbs Meter with new PN: 100690-26. Fire extinguisher missing; Installed new PN: H3R-A400. R/H strobe INOP; complied with RR of R/H strobe with new PN: 762-003. Complied with AD 2020-26-16; Eddy current inspection of wing spar, 4 new spar bolts installed PN: NAS 6606-14 and new nuts PN: MS21042L6. Conformity inspection: Complied with conformity inspection; Aircraft found to be in good flying condition and is released for flight training use. All work completed IAW Piper PA-28-181 MM and IPC HOBBS METER OFF: TIME- 5274.7 ON: TIME- 000.1 Aircraft returned to service in airworthy condition at this time with respect to work completed; pertinent details are on file at Hood Aircraft. Cody Haynes AP3348610IA Dated: September 22 nd , 2023.
		Removal of Requir	red—Exchanged for Optional	

Beaufort, NC 28516 Avionics/Airframe Log DATE Date: 11/07/19 **Tailwind Avionics Total Time:** Registration: N90874 Hobbs Time: 5274.7 Model: PA28-181 TAILWIND **Tach Time: 5049.1** S/N: 28-8690014 W/O#: 19-00077 Repair station#: 38TR208 Removed KT76A SN: 45428. Installed Stratus ESi IAW STC SA04112CH. Wired unit to GNS 430W and encoder. Setup unit IAW installation manual. MOC of system was ok. Transponder tested as required by 91.413 appendix F Make: Stratus EG SN: 201920 I certify that the maintenance operations outlined above were conducted IAW current federal regulations and are approved for return to service at this time. Steven Ponder

EQUIPMENT ADDITION, REMOVAL OR EXCHANGE



02/28/2023

N90874

Cleaned, inspected and greased all wheel hearings, repaired r main wheel fairing and nose strut fairings, removed surface corrosion from right wheel halves, treated and

painted, replaced right main tire. Repaired left wing tip, left stab tip, removed surface

Lubricated flight controls and landing gear, serviced nose strut. Replaced RH aft Horz trim cable pulley. Replace Rt Aileron inbd static wick, replaced left aileron otbd static

checked thru 02/28/2023. CW 76-07-12 Bendix Ignition switch op ck. no defects noted.

next due 02/24 or tach 5192.1, CW AD2013-02-13, visual insp of Horz stab control cables next due 3/2030 or tach 7056.AD 2020-26-16, lower spar fatigue crack insp. net due at this time, recalculate at next 100 hour or Annual. Ground run and ops checks

corrosion from left wing, right wing and vert stab. Replaced main battery RG35A.

wick, Repainted RT side N number Replaced vacuum relief valve filter B3-5-1. Inspected E.I. TIAW FAR 91.207D, replaced battery, Battery due 04/25, A.D. list

good. All work accomplished IAW manufacturer's instructions.

and was determined to be in an airworthy condition.

C.A. Buterbaugh

Tach: 5092.1

Performed Annual Inspection on this aircraft using Aircraft Manufacturer's checklist.

I certify that this arreraft has been inspected in accordance with an Anaual Inspection







10-9-19 Tach: 5043.1 Actt 5043.1 Aircraft N90874 Aircraft s/n 28-8690014 Aircraft m/n PA-28-181 Tested ELT IAW FAR 91.207 tested good- battery due 11-2020. Complied with the following ADs: 76-07-12 Bendix Ignition Switch (ops check good) next due 5143.1 actt. AD#18-07-03 Fuel Selector Placard Improper Installation-checked placard and its installed correctly- no further action required. Installed the following new parts -air filter p/n BA3, right side cowling forward bushing p/n MC69790-00. McCreary 6.00x6 nose wheel tube, nose wheel bearings and races p/n LM29749(2ea) and LM29710(2ea), carb heat cable attach stud and fitting p/n CA70371-002 and CA70371-003 . I certify this aircraft has been inspected IAW ANNUAL inspection as per FAR 43 APP D and Piper INSPECTION CHECKLIST and was determined to be in airworthy condition and is returned to service. Andy Rosman 3524208 IA




Aircraft N90874 12-10-2020 Tach: 5056.5 Actt 5056.5 Aircraft m/n PA-28-181 Aircraft s/n 28-8690014 Installed a new ELT battery p/n BP-1010 and tested ELT IAW FAR 91.207 tested good- battery due 12-2022. Complied with the following ADs: 76-07-12 Bendix Ignition Switch (ops check good) next due 5156.5 actt. Installed the following new parts -air filter p/n BA3,new main wheel assemblies p/n 40-86B, landing light bulb p/n GE-4509, wheel pant southcos retainers p/n 85-34-201-20 (17ea), southco fasteners p/n 85-11-220-20 (17ga), left nav light bulb p/n A508-14, and new brake pads p/n 66-105 (4ea) . I certify this aircraft has been inspected IAW ANNUAL inspection as per FAR 43 APP D and Piper INSPECTION CHECKLIST and was determined to be in airworthy condition and is returned to service. Andy Rosman 3524208 IA










DATE	TOTAL	DATE <u>i ルー1イ・17</u> AC HRS <u> 4961・8</u> N <u> 9 8 </u> P フ 4	IONS TO
9	SERVICE	I CERTIFY THAT THE ALTIMETER, ALTITUDE REPORTING AND STATIC SYSTEM TESTS REQUIRED BY CFR 91.411 HAVE BEEN PERFORMED. TESTS WERE PERMORMED TOFT.	TE APPROVING AGENCY.
		ALTDATE	
		ENCODERDATE	
		STATIC SYSTEM 12-14-17 DATE	
		THIS KTOLA TRANSPONDER S/N 45428 HAS BEEN TESTED AND FOUND TO BE IN COMPLIANCE WITH THE REQUIREMENTS OF CFR 91.413(PART 43 APP F).	
		DATE	
		SIGNED Rosald in Cularge 9.	
		BAY AVIONICS, LTD. HM1R197K	
	 	-	




Aircraft N90874 Date 9-30-16
Installed the following; Horizon p/n KG258 s/n 10542 after overhaul at Century Instruments w/o K152468, Repaired KC190 Computer p/n 065-0055-02 s/n1380 at Autopilot Central w/o SH16-30416. Installed Directional Gyro KG-107 p/n 060-0022-00 s/n 1813 after overhaul at Pacific Southwest Instruments w/o 298053, Transponder KT76A p/n 066-1062-00 s/n 45428, Narco AR500 s/n 25440 after repair at Sparkchasers w/o 103115, Ops check good.

Andy Rosman 3524208 A&P



Aircraft N90874	land Aviation, Ltd.
Aircraft m/n PA-28- tested ELT IAW 91.3 Switch (ops check g air filter p/n BA3, no Light W1290-14, Va been inspected IAW	207C Battery due 8-2018. Complied with the following ADs: 76-07-12 Bendix Ignition ood),17-14-04 Oil Cooler Hose no defects noted. Installed the following new parts use wheel bearing p/n LM 29749 (2ea), nose wheel race p/n LM 29710(2ea), Lh nacuum Filter RAB3-5-1 and cowling intake seal p/n 63086-00. I certify this aircraft head of the country of th

Rarrier Is.	and Aviation, Ltd.	R OF RIES.)
Aircraft N90874	Date 7-1 16 Tach 4880.1 airhawk 6,00 x 6,6ply tire and tube on I/h main. Ground run good.	




bearing p/n LM 2974 and treated airframe	Dattery p/n BS2166 and test Ds: 76-07-12 Bendix Ignition A3, landing light p/n GE 45 Ps. nose wheel race p/n LN With corposion X. I certify and Pipen NSPECTION CHE	Actt 4881.8 ft s/n 28-8690014 sted ELT IAW 91.207C Battery now due 8-2018.Complie on Switch (ops check good). Installed the following new 509, left main brake pads p/n 66-105 (2ea), nose wheel 1 29710 and rh wing tank drain p/n CCA-1550. Cleaned this aircraft has been inspected IAW ANNUAL inspection ECKLIST and was determined to be in airworthy conditions.
---	---	--

08 IA Mh	dition and is returned to	

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN	DESCRIPTION OF INSPECTIONS THE PROPERTY OF THE
	TIME	FLIGHT	SERVICE	DATE 12-15-15 AC HRS 4816.7 N 90874
				I CERTIFY THAT THE ALTIMETER, ALTITUDE REPORTING AND STATIC -
				SYSTEM TESTS REQUIRED BY CFR 91.411 HAVE BEEN PERFORMED. TESTS WERE PERMORMED TO 16,000 FT.
_	-			ALT
				ENCODER/F
_		-		STATIC SYSTEM 12-15-15 DATE
				SIAIIC STSTEW
_	-			THIS K176A TRANSPONDER S/N 4542F
_				THE DEEN TESTED AND FOUND TO BE IN COMPLIANCE WITH
				REQUIREMENTS OF CFR 91.413(PART 43 APP F).
_				DATE 12-15-15
				DATE 13-13
			-	SIGNED WISESTOR
_				INSPECTOR — BAY AVIONICS, LTD. HM1R197K
				BAY AVIONICS, LTD. HIMINISTA
_				

DATE RECORDING TOTAL DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS TACH TODAYS TIME IN ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF TY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) Aircraft N90874 Aircraft N90874	
DATE 12 - 18-13 AC HRS 4671-1 N 90874 LEGRTIFY THAT THE ALTIMETER. ALTITUDE REPORTING AND STATIC SYSTEM TESTS REQUIRED BY CFR 91.411 HAVE BEEN PERFORMED. TESTS WERE PERMORMED TO 12,000 FT. ALT 13-18-13 DATE ENCODER 12-18-13 DATE STATIC SYSTEM 12-18-13 DATE TRANSPONDER S/N 45-42-8 HAS BEEN TESTED AND FOUND TO BE IN COMPLIANCE WITH THE REQUIREMENTS OF CFR 91.413(PART 43 APP F). DATE 13-18-13 DATE 13-18-13) and LM right main outer



Aircraft N90874	Date 5-15-12	Tach 4528.3	Actt 4528.3	16-
Aircraft m/n DA-28-	181	Aircraft s/n 28	3-8690014	
Installed now ELT Ba	attery n/n BS2166 a	and tested ELT	AW FAR 91.207D—ops check good, batte	ery now -
due 5/14. Complied	d with the following	g ADs: 76-07-12	Bendix Ignition Switch (ops check good).	Installed _
La following new n	arts -air filter p/n E	BA3, new nose v	vheel bearings p/n LM29749 (2ea) & race	e p/n
1120710 (202) Rem	loved copilots brak	e cylinders and	replaced orings p/n MS 28775-110(4EA)-	
42/25Aland 006/2	FAlthen reinstalled	d. bled system a	nd checked for leaks and proper operation	on. I -
this aircraft k	as been inspected	IAW ANNUAL II	ispection as per FAR 43 APP D and Piper	
INCRECTION CHECK	IST and Was deter	mined to be in a	irworthy condition and is returned to ser	rvice.
Andy Rosman 3524	208 IA			
Andy Rosman 332				
	v			
	57 July 2017			

Barrier Island Aviation, Ltd.	
 TV AT ULCONO DE	

AIICIAIL N908/4	and Aviation, Ltd. 5-16-13 Tach: 4608.1	Actt 4608.1
Aircraft m/n PA-28-	181 Aircraf	ft s/n 28-8690014
Tested ELT IAW FAR	8 91 2070 one shock good	hattery now due 5/14. Complied with the following
AUS: 76-07-12 Bond	iv lonition Coultable forms about	-1 ad/12 02 12 Horizontal stabilizer Cable Inspection
defects noted Inst	alled the following now no	rts -air filter p/n BA3, landing light p/n GE4509,nose wheel
bearings and races	aned the following new pa	9748(2ea),left main wheel bearings and races p/n
1388992eal and 139	93.6/2) 1/10(ea) and Livi 2	nd 452-335 . I certify this aircraft has been inspected IAW
ANNUAL inspect:	836(2ea), left aileron rod e	riper INSPECTION CHECKLIST and was determined to be in
airworth	as per FAR 48 APP D and P	iper INSPECTION CHECKLIST and was determined
And D	and is rejurned to service.	
Andy Rosman 3524	208 IA	
	/ V	

DATI 19	AC MAKE: PIPER AC MODEL: PA 28-181 AC S/N: 28-8690014 Date: November 15, 2011 SPARKCHASERS TACH TIME: 4501.30 LONS UMBER OF ENTRIES.) AC MODEL: 4501.30 LONS UMBER OF ENTRIES.) AC S/N: 28-8690014 AIRFRAME LOGBOOK ENTRY A/C REG. #: N90874	AC MAKE: PIPER SPARKCHASERS TACH TIME: 4501.30 BER OF NTRIES.) AC MODEL: PA 28-181 AC S/N: 28-8690014 AIRFRAME LOGBOOK ENTRY A/C REG. #: N90874 Date: November 15, 2011
	Removed defective Kollsman Altimeter and replaced with new United Instruments 5934P-3 Altimeter s/n 491394. Correlated with Narco AR500 Altitude Reporter s/n 25440. Transponder, Altitude Reporter and Altimeter checked through altitude operating envelope of aircraft and found to meet the requirements of FAR Part 43, Appendix E(c). Repaired numerous static system leaks in order to comply with FAR Part 91.411. WO# 101007 on file at Sparkchasers Aircraft Services, Inc., FAA CRS# XSPR699K. Signed	I certify that the altimeter and static system tests and inspections required by FAR 91.411 have been performed. The LH Altimeter, P/N United Instruments 5934P-3, S/N 491394 certified to FAR Part 43, Appendix E by Sparkchasers Aircraft Services, Inc., CRS# XSPR699K on WO# 101007 was tested to 20,000 ft. on on file under WO# 101007, dated 11/15/2011. I certify the below transponder(s) has(have) been inspected and found to comply with the requirements of FAR Part 91.413 on Work Order No. 101007, dated 11/15/2011.
		#1 Transponder: Make King / Bendix, Model KT76A, S/N 45428. Signed Sparkchasers Aircraft Services, Inc. FAA CRS# XSPR699K

N90874 11-24-10 Tach 4413.5 Actt 4413.5 Installed J.P. instruments EDM-700 engine analyzer with fuel flow and new fuel line p/n 124F001- 6CR0052 in accordance with STC SA00432SE approved instructions. See 337 dated 11-24-10. Ops	Barrier Island Aviation, Ltd. Aircraft N90874 Date 5-5-11 Tach 4443.3 Actt 4443.3 S.S.)
Check good. Andy Rosman 3524208 A&P Barrier Island Aviation, Ltd. N90874 12-21-10 Tach 4417.4 Actt 4417.4 Installed serviceable KG-258 horizon gyro p/n 060-0020-01 s/n 10542	Aircraft m/n PA-28-181 Aircraft s/n 28-8690014 Tested ELT IAW FAR 91.207D—ops check good, battery now due 4/12. Complied with the following ADs: 76-07-12 Bendix Ignition Switch (ops check good) and 10-15-10 Control wheel column shaft -PCW. Installed new air filter p/n BA3. Installed new nose wheel bearing p/n LM29749 & race p/n LM29710. Replaced I/h main with McCreary Air Hawk 6.00-6 6ply tire and installed new bearing p/n 13889 and race p/n 13836 on I/h main wheel. I certify this aircraft has been inspected IAW ANNUAL inspection as per FAR 43 APP D and Bisser McCreary and the second s
after overhaul at Century Instrument Corp. w/o K138583. Ops check normal. — Andy Rosman 3524208 A&P Barrier Island Aviation, Ltd.	per FAR 43 APP D and Piper INSPECTION CHECKLIST and was determined to be in airworthy condition Andy Rosman 3524208 IA

	NOOD -		
### ### ##############################	ABER OF Installed	I-6-10 Tach: 4354.9 Actt: 4354.9 new ELT Battery p/n BS2166 and tested ELT IAW 91.207D. Battery di	ue 4-12. Installed new
Aircraft stripped etched alodined primed and painted using PPG Delfleet chemical resistant paint by Sebastiao Nassimbeni and Alberico Cruz-Neto of Aircraftpainting.com under supervision. Flight controls and flaps removed before painting. Checked flight control balance and reinstalled flaps and controls in accordance with Piper service manual. Replaced Fwd. dorsal fin cover. Replaced spar bolt covers. Replaced upper and lower tailcone half. Installed new wing gap seals. Installed new vertical stabilizer cap. PPG Aerospace Coatings Matterhorn White: 913189 Wine Metallic: 500740 Gloss Titanium: 302240 A&P3168209IA	following outboard LM29749 following (2ea) & w dated 4-6 Piper Insp Andy Ros BARRIER NS In Op	BA3. Complied with AD AD 76-07-12 Bendix Switch Test—no defects new parts: Cleveland Brake disc p/n 164-02000 (2ea), brake pads p/l bearing p/n 13889, r/h outboard bearing p/n 13889 & race p/n 1389 & race p	In 66-105 (4ea), I/h 36, nose wheel bearing 0121 (12ea) and the assembly p/n K136-173 through spar IAW 337 n as per FAR 43 APP D a nd returned to service.

TODAYS	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBE MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENT	DAT Cape Fear Airworks, Inc Brunswick Co. Airport, NC 19— 910-232-2230/ 910-367-3344	PAIRS AND ALTERATIONS ; AND CERTIFICATE NUMBER FOR OTHER SPECIFIC ENT
		DATE 11-23-09 AC HRS 4337.2 N 90874 I CERTIFY THAT THE ALTIMETER, ALTITUDE REPORTING AND STATIC SYSTEM TESTS REQUIRED BY CFR 91.411 HAVE BEEN PERFORMED. TESTS WERE PERMORMED TO 20,000 FT. ALT. 11-23-09 DATE ENCODER 11-23-09 DATE STATIC SYSTEM 11-23-09 DATE THIS XT 76 A TRANSPONDER S/N 4540F HAS BEEN TESTED AND FOUND TO BE IN COMPLIANCE WITH THE REQUIREMENTS OF CFR 91.413(PART 43 APP F). DATE 11-23-09 SIGNED Renald W. Cappend INSPECTOR BAY AVIONICS, LTD. HM1R197K	Mechanic: Lichard A&P 1759P92 - N90874 1-16-10 Tach: 4343.0 Actt: 4343.0 Repaired right hand wing using the following new parts: leading edge skin p/s Stringer n/n 35118-13 (202) page sib n/n 35118-23 & ton l/h leading edge ski	n 35118-829 & 35118-847

DATE 19	">xxxxxxxx 5/12/08 A CTT: 4694.4 TACH: 4285.4	ATIONS NUMBER OF IC ENTRIES.)	N90874 2-12-09 Tach: 4322.3 Replaced L/H static wick P/N SW10-96. Installed the following new parts: alternator bolt Replaced L/H static wick P/N SW10-96. Installed the following new parts: alternator bolt Replaced L/H static wick P/N SW10-96. Installed the following new parts: alternator bolt Replaced L/H static wick P/N SW10-96. Installed the following new parts: alternator bolt Replaced L/H static wick P/N SW10-96. Installed the following new parts: alternator bolt Replaced L/H static wick P/N RAB3-5-1, air duct assembly P/N 79855-02, & fuel P/N AN3-pump P/N CA35328-800E S/N 6757. Repaired battery box by installing new P/N AN3-pump P/N CA35328-800E S/N 6757. Repaired battery box by installing new P/N AN3-pump P/N LM29749, & nose wheel race P/N remove corrosion. Replaced nose wheel bearing P/N LM29749, & nose wheel race P/N LM29710.Installed Airtex Products Inc PMA carpet set. I certify this aircraft has been inspected IAW ANNUAL inspection as per FAR 43 APP D and Piper Inspection Checklist and was determined to be in air worthy condition and returned to service.	_
		·	Andy Rosman 122489894 IA BARRIER ISLAND AVIATION, Ltd.	- -
	N90874 6/13/08 ACTT: 4704.7 TACH: 4296.0 Replaced L/H p/n # 761-253 strobe lens, p/n # 7755-076 retainer & p/n # 762-003 strobe light Ops check normal. Melville W. Towle 2641462 A&P BARRIER ISLAND AVIATION, Ltd.	nt bulb	N90874 2-12-09 Tach: 4322.3 Actt: 4322.3 All applicable Airworthiness Directives have been complied with at this time. Andy Rosman 122489894 A&P	- - -

-	N90874 12/08/07 ACTT: 4239.9 TACH: 4239.9 Removed propeller to facilitate installation of new alternator belt P/N 564-852. Installed propeller and torqued IAW Piper Maintenance Manual. Treated aircraft with Corrosion X. Installed new ELT battery P/N BP1010, ops checked ELT IAW FAR 91.207 D.	! OF	DATE	RECORDING TOTAL DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS TACH TODAYS TIME IN ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF THE ELICHT SERVICE HECHANIC OF DEPAIR EACHITY (SEE BACY BACES FOR OTHER SERVICES.)
	New battery due: 12-09. Installed new left main wheel bearing and races P/N 13889 (2ea) and P/N 13836 (2ea) and nose wheel bearings and races P/N LM29749-2629 (2ea) and P/N LM29710-2629 (2ea). Installed new left main brake pad P/N 66-105. Installed new	_	-	O&N AIRCRAFT MODIFICATIONS, INC. SEAMANS AIRPORT 210 WINDSOCK LANE FACTORYVILLE, PA LOG ID# 3760 07-January-2008 WO# 14052/1 Pg 1 / 1 N90874 S/N 28-8690014 PIPER PA-28-181
_	P/N LM29710-2629 (2ea). Installed new left main brake pad P/N 66-105. Installed new fuel cap seals P/N 462-056 (2ea). Install new starter bendix p/n EBB-131A. I certify this aircraft has been inspected IAW ANNUAL inspection as per FAR 43 APP D and Piper Inspection Checklist and was determined to be in hirworthy condition and returned to service.		1 1 1	**** ITEM # 14052-1 Update GNS430W software. **** Model: GNS-430W Part#: 011-01060-00 Serial#: 23400745 ACTION: Updated Main and GPS software levels to 3.0 per Garmin Service Bulletin No. 0740 Rev. A on GNS-430W p/n 011-01060-00 s/n 23400745. Replaced FMS with new FMS p/n 190-00356-03 Rev. A and installed in Flight Manual. All final tests satisfactory.
	Andy Rosman 122489894 IA BARRIER ISLAND AVIATION, Ltd.	_	1	ONFR798K William L. Miller Date
			-	



FAR TESTS AND INSPECT	IONS		
Transponder # 2 P/N S/N S/N S/Signature Date	with and comply to		
10)			

'ECTIONS, TESTS, REPAIRS AND ALTERATIONS

WITH NAME, RATING AND CERTIFICATE NUMBER OF TY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)

NATE RECORDING	TOTAL	DESCRIPTION OF	INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS 'SED WITH NAME, RATING AND CERTIFICATE NUMBER OF CILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
FIRS	TFLIGHT		
FAR TESTS	AND INSPECTIO	ONS	
CRS#TVMR353S certifies the FAR 91.411 were performed Appendix E of Part 43. Aircare certified for a maximum This aircraft is returned to saltimeter # 1 PIN CAPTAINS Altimeter # 2 PIN Signature Next Due 6/2009	at altimeter & statil in accordance with a statil raft N# 90814 altitude of 20,00 service. S/N AS S/N Date	ic tests required by th and comply to	

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE 19	BARRIER ISLAND AVIATION, Ltd. ALTERATIONS ICATE NUMBER OF SPECIFIC ENTRIES
2-1-06	4014.		SERVICE	Blad 4H Broke, Serviced 4H Strut with nitropen & Replaced Rivet in Cabia Doce Holder. Installed new 6:11 6-35 serviced to Manufactures spec's ops check good 122485894 APP		Installed BA-3 bracket air filter, replaced left aileron control rod, rod end with new P/N: 452-335, and replaced stabilitor trim washer P/N: 494-159, thrust washer P/N and circlip P/N: 484-747. Treated aircraft with Corrosion X. C/W AD 76-07-12 Bendix Ignition Switch Test- no defects noted. Tested ELT IAW FAR 91.207 D. Tested good -battery due: 10-07. I certify this aircraft has been inspected IAW ANNUAL inspection as per FAR 43 APP D and Piper Inspection Checklist and was determined to be in airworthy condition and returned to service. Andy Rosman 122489894 IA
						My

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENT	R
	-	lach	viction		- 1	OG ID# 2342	FT MODIFIC 2 26-July- N 28-86900	2005 WO	INC. SEAMANS AIRPORT 210 WINDSOCK LANE FACTORYVILLE, PA # 12963/1 AC TT 4342.3 ER PA-28-181	T
C /\Allie	N90874	5/5 of transponders D Mich	101 Hangar Road International Aureon • Ave (570) 457-3400 /2005 Tach der for compli- oes not apply nael DiStadio # TVMR353S	3898 iance with AD98-14-03 by serial # 45428.	- Long to the control of the control	Mu	2963-1 Gl to defecti 09 for Gli liam L. Mi	lle	inop. **** litter p/n DMC67-1. Replaced splitter. Replaced open wire between lag. Reassembled as required. All final tests satisfactory. 7/26/05 Date	

ATE	RECORDING TACH	TOTAL TOTAL			NS, TESTS, REPAIRS AND	
9	TIME	FLIGHT SERVICE	MECHANIC O	R REPAIR FACILITY. (SE	EE BACK PAGES FOR OTHE	R SPECIFIC ENTRIES.)
		N Number	Date	TACH/HOBBS	AFTT	_
			10/7/2004	3832.3	3832.3	
		90874	10///2004	3032.3	3032.3	
		AF Entry				
	1	Performed ann	nual inspection on th	is aircraft in accordance	e with FAR 43 appendix D. (Checked all —
		controls for pro	oper rigging and lubr	icated. Checked all cal	bles for proper tension, chec	ked all
			ts, inspected all nose	es, lines and wiring Re	enacked all wheel hearings	shooked tires
		wheels and bra	akes for condition. In	nspected ELT in accord	epacked all wheel bearings, of dance with FAR 91.207(d), ba	
		wheels and bra replacement d	akes for condition. In ate 10/2005. Replac	nspected ELT in accord ced instrument air filters	dance with FAR 91.207(d), bas as required, checked and s	
		wheels and bro replacement d fluid levels, lub applicable AD'	akes for condition. In ate 10/2005. Replace pricated controls and as for compliance to c	nspected ELT in accord ced instrument air filters washed aircraft. Chec date. All work performe	dance with FAR 91.207(d), bas as required, checked and solved MFG SB's to date. Checked in accordance with Piner so	
		wheels and bro replacement d fluid levels, lub applicable AD' manual and st	akes for condition. In ate 10/2005. Replace pricated controls and is for compliance to condition as li	nspected ELT in accord ced instrument air filters washed aircraft. Chec date. All work performe	dance with FAR 91.207(d), bas as required, checked and sicked MFG SB's to date. Checked in accordance with Piper streturn this aircraft to service is	
		wheels and bro replacement d fluid levels, lub applicable AD' manual and st	akes for condition. In ate 10/2005. Replace pricated controls and is for compliance to condition as li	nspected ELT in accord ced instrument air filters washed aircraft. Ched date. All work performe sted in FAR part 43 to r	dance with FAR 91.207(d), bas as required, checked and sicked MFG SB's to date. Checked in accordance with Piper streturn this aircraft to service is	attery erviced all ked ervice
		wheels and bra replacement d fluid levels, lub applicable AD manual and st condition. Ref	akes for condition. It ate 10/2005. Replace or controls and s for compliance to condition and practice as lifer to WO# M00239 of the controls.	nspected ELT in accord ced instrument air filters washed aircraft. Ched date. All work performe sted in FAR part 43 to r	dance with FAR 91.207(d), bas as required, checked and sicked MFG SB's to date. Checked in accordance with Piper streturn this aircraft to service is	

DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF DATE RECORDING TOTAL MECHANIC OR REPAIR FACILITY, (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) TACH TODAYS TIME IN 19___ FLIGHT SERVICE





FAR TESTS AND INSPECTIONS CRS#TVMR353S certifies that altimeter & static tests required by CRS#TVMR353S certifies the transponder tests required by FAR 91.411 were performed in accordance with and comply to Appendix E of Part 43. Aircraft N# 90874 altimeters are certified for a maximum altitude of 20,000 feet. This aircraft is returned to service. Altimeter # 1 P/N PILOT Altimerer # 2 P/N S/N S/N CR80272 5-5-05 Signature Work Order # Date Next Due 5/07 Form# TA149

FAR TESTS AND INSPECTIONS

FAR 91.413 were performed in accordance with and comply to Appendix F of Part 43. Aircraft N# 90874 Transponder # 1 P/N KT 76A S/N 45 428

Transponder # 2 P/N 5-5-05 Signature

CR\$ 0271 Work Order # Date

Next Due 5/07

Form# TA150

DATE RECORDING TACH TODAYS TIME IN TIME TODAYS FLIGHT SERVICE TOTAL TOTAL TODAYS FLIGHT SERVICE TOTAL TODAYS TIME IN SERVICE TODAYS TIME IN SERVICE TOTAL TODAYS TIME IN SERVICE TO TOTAL TOTAL TODAYS TIME IN SERVICE TO TOTAL TOTAL TODAYS TIME IN SERVICE TO TOTAL TO	IFIC ENTRIES)
	THE ENTINEERS
N Number Date TACH/HOBBS AFTT 8645 15-50 AEROSCELL	
90874 10/3/2003 3652.3 3652.3 CH 48/10 Filter	
Performed annual inspection on this aircraft in accordance with FAR 43 appendix D. Checked all controls for proper rigging and lubricated. Checked all cables for proper tension, checked all	
structural points, inspected all hoses, lines and wiring. Repacked all wheel bearings, checked tires, wheels and brakes for condition. Inspected ELT in accordance with FAR 91 207(d)	
replaced ELT battery, new replacement date 10/2005. Replaced instrument air filters as required, checked and serviced all fluid levels, lubricated controls and washed aircraft	
Checked SB's and AD's for compliance to date. All work performed in accordance with Piper service manual and standard practice as listed in FAR part 43 to return this aircraft to service in	
airworthy condition. Refer to WO# M00056. Ron D. Dillon	
Ron D. Dillon A&P 239482895 IA	

DATE Sections Compared Com	DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
altimeter, altitude encoder and static system test and littled by FAR 91.411 have been performed. The altimet by SN HF 436744 Artified to AGORO In. The PIN AR. 5003. SN AS 400 is certified to PIN AR. 5003. SN AS 400 is certified to Date QU-10-03 wolf 1355 Artified to Bate Artif		N Num 90874 Date 1/17/: Log En Drain filter 7564 Stuar CRS	per 2003 atry ed engin with P/N	TACH/HOB 3538.3 / in e oil and s CH48110 his FAA CF	BBS 3944.8 serviced with 8 quarts Aersohell 40 wt oil and replaced Ground ran aircraft, no leaks noted. Refer to WO# RS.
Aircraft 9087 I certify that the inspections requestive encoder 20,000 ft. Dillon's Aviation FAA CRS Y14R SNN 415 408 With requirement of FAA CRS Y14R FAA CRS Y14R	E/S/e	3	2		73642.1 H4055.0 01 change 808 Acashell 15-50 CH48 110 Filter

E CONTRACTOR DE LA CONT

DATE RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, INS. AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATIL OF AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGE, FOR OTHER SPECIFIC ENTRIES.)	DATE	RECORDING TACH	TODAYS	TOTAL TIME IN		JMBER OF
11-2-01 3427.8			MSI INOP, REMOVED HSI + RETURNED TO REPAIR STATUS PART # 060-0020-01 SN 10542, REINSTANCED SAME PART # + SERIM NUMBER AFTER REPAIR. GND JOK May are 2667572		TIME	controls for points, insurance for 07/2003. controls a 492-153 a accordance aircraft to	ed annual instor proper rig aspected all hor condition. Replaced in and washed and P/N 462 nce with Pipe o service in a	Date TACH/HOBBS AFTT 10/17/2002 3507.3 3507.3 Inspection on this aircraft in accordance with FAR 43 appendix D. Checked all igging and lubricated. Checked all cables for proper tension, checked all structura hoses, lines and wiring. Repacked all wheel bearings, checked tires, wheels and Inspected ELT in accordance with FAR 91.207(d), battery replacement date instrument air filters as required, checked and serviced all fluid levels, lubricated diaircraft. Replace nose gear axle P/N 86062-056. Replace fuel cap vent seals P/N 82-056. Checked SB's and AD's for compliance to date. All work performed in per service manual and standard practice as listed in FAR part 43 to return this airworthy condition. Refer to WO# 7374 on file this FAA CRS.	

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	19	RECORDING TACH TIME	TODAYS FLIGHT	E IN	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
10/5/01	3420.6	,	3470.6.	THIS TIME & DATE PERFORMED AN ANNUAL	IU5TH	KLEDA	FILLE	VIFL.C	APCASKETS STOP DRILLED ORACL WEAR APCASKETS STOP DRILLED ORACL WEAR
				IPER CHECKLIST. INSTALLED ANEW ELT	STORI	Dum	0001	AUA	PPCASKETS. STOP DRILLED ERMO ACUB. 13-18 PPLIED A SURFACE PATCH FAW ACUB. 13-18
BATTE	RY. I	USPE	CTED	ELT IAW FARGE ZOT (d) NO DEFECTS	PAGE	3.7/	1- =16	ME	B-JJ. RAR HORIZONGYRO PN. 060-0020-01
WERE	E NOTE	50 7	BATTE	EY DUE. 7/03, RELAMPED LANDING LIGHT. ED NEW FULD MUFFLER ASSIV DART NO.	50.7	Emay	100 -1	0102	LITALLED SN. 10542 - OF. CR. SOCO.
				ED NEW FULD MUFFLER ASSY. PART NO.	ICF	ATTEN	0.1	114.5,	MIR CHAFT WAS INSPECTED IN ACCORDANCE
66890	1-03 4	VITH	NEU) GASKETS AND HARDWARE. RAR GAS	WIT	TITY	HAT	11:115	THE CHAFT WAS INSPECTED FOR RETURN.
COLA	TOR GI	75KC	TI LE	PAK CK. GOOD, INSTACLED A NEW RT.	TO	ERVIC	ANNIC	NCC. IN	SPECTION
MAIL	TTRE	, RE	SEAC	ED LEFT & RIGHT BRAKE HOUSINGS		PEUK	LE.		miscelees ASP 26402534ILA
INSTI	ELLED	NEU) LEA	TARIGHT BRAKE UNING, TUSTALLED	_	-			MINSCHLEET ASPOSESTECH AVIATION.
ANE	U 571	ZUT	BUMA	ER BRACKET PN. 790 71-00 TUSTALLED	_	+			TON !
NEW	VACL	UM	FILTE	RS B-3-5, D9-18-1 REPAIRED DT DILFRON	_	-	4.1/		
BONO	NG STY	26P.	RdR (CEFT AIELROW & LEFT HORIZ. STATIC WCK.	_	-			
				Date: String to	-				

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
8/21/00	3275		3275.	REPAIREDOPEN CIRCUIT IN BUNUNCIATOR	10/4/00	3335.9			RER HORIZON-GYRO PART NUMBER 060-
LIGIT	T CIR	WIT	OP.	CK, G000.	0000	-01.5	ERIA	LNUN	VBER 12193 INSTALLED, SW. 12941 REMOVED
				modelley ASP364095341 FORTECH AVIATION.	00.0	HECK	GOOD		111 Xaley H&P364035541
-									O FORTECH AVIATION.
916100	3298.3		32983	REMOVED NOSE AND MAIN WHEEL PANTS	10/10/c	3338.	4		CIW MANDATORY \$B 1041 INSPECTION!
	BALA			IGE NOTEDS	REPI	ACEMA	TITE	AIRF	BORNE 09-18-1 AIRFILITECS. NO DEFECTS
				moduley Ad P 364035341 FOR TECH AVIATION	NOT	ED. 11		TUED	NEW FILTER ATTIME ANEW
					B3-	5-11	FICIE	E	moRaleef AdP264035341
9111100	3306		3306	The Shot Cidili, Opi Chi					FOR TECH AVIATION.
REA	ACE) NC	SETI	RE WITTE WEW, CLEANED, INSPECTED					
& RE	PACK	ED	N050	WHEEL BEARINGS	10/2/1			3339	A REPAIRED BROKEN GROUND WIRE ON LANDIN
-				my Hale of APP 26.4025341 FORTECH AVIATION	961	67. RE	ELAM.	DED, OF	P.CK. 600D. m. faley Ad P364035341
-									FOR TECH AVIATION.

DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF RECORDING RECORDING ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF TOTAL MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) TODAYS TIME IN TACH 2000 MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.) TACH TODAYS TIME IN FLIGHT SERVICE TIME FLIGHT SERVICE SERVICED S'HIMMY DAMPER, LEAK CK. GOOD RIA ALTIMETER SN 98609 REMOVED, SN 1/20/00 32 UZ 7-14-00 3237.2 myaley AAPA640A5341 FOR TECH AVIATION. 43-67440 INSTALLED + ALSO ENCOSE ALSOO SN 25440 WAS REMOVED REPARED + RE-INSTAUD 3360 THIS TIME & DATE PERFORMED AN ANNUAL DURING 91.411 + 91.413 TESTS UNDER WORK ORDER 116100 3360 USING PIPER CHECKLIST. INSPECTED ELT IAW # CRS 0144. BOTA RETURN TO SERVICE. (d) NO DEFECTS NOTED. BATTERY DUE 7/3001. ASB 193424449 INDUCTION AIR FILTER, CHECKED BRAKE WEAR & SAB BE WITH IN LIMITS, CLEANED & LUBED LANDING 7/17/00 3237.2 3237.2 INSTALLED OVERHAULED ENGINE SERIAL AIRFRAME, SERVICED BATTERY. ICERTIFY L-27647-36B. USING NEW J-9613-10 WAD NUMBER, AIRCRAFT WAS INSPECTED IN ACCORDANCE REAR TOP DOOR ISINGE &LATCH, INSTALLED WHEEL MOUNTS. LANDURG INSPECTION AND IS APPROVED FOR PANTS modeled ASP 264025341 FORTECITAVIATION. SERVICE. MIGHELY ASIPAGGOD5341IA. FORTECH AVIATION.

DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS

TOTAL

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND AL ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICA	TERATIONS ATE NUMBER OF TIC ENTRIES.)		INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS DRSED WITH NAME, RATING AND CERTIFICATE NUMBER FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTI
			 ,	Tech Aviation 101 Hangar Rd. Avoca, PA 18641		Tech Aviation 101 Hangar Rd. Avoca, PA 18641	7-14-00 TACH 3237, 2 Clw AD 98-14-03 AUIED
		स्तर के के किया के किय किया किया किया किया किया किया किया किया		FAR 91.411 TESTS AND INSPECTION CRS# TVMR353S certifies that altimeter and static tests required by FAR 91.411 were performed in accordance with and comply to Appendix E of Part 43. Aircraft N# 1087 4 altimeters are certified for a maximum altitude of 20 000 feet. This aircraft is returned to service Altimeter# 1 P/N C-12 S/N 43 - 67440 Altimeter# 2P/N S/N S/N Work Order # NEXT DUE 7 - 2002		FAR 91.413 TESTS AND INSPECTIONS CRS# TVMR353S certifies that the transponder tests required by FAR 91.413 were performed in accordance with and comply to Appendix F of Part 43. Aircraft N# 90874 This aircraft is returned to service. Transponder# 1 P/N KT76A S/N 45 428 Transponder# 2P/K S/N Work Order # NEXT DUE 7-2002	SIGNAL KT76A TRANSPONDER DOES NOT APPLY BY SERIAL NUMBER #45428 PART ## 066-1062-00 ARP 192424444

	- /	100								
1	TAC TIM		TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
3/30/00				3079.	RAB TURN COORDINATOR PN. 1394T100-TZ-	AILES	CN. BU	LAM	DED UF	NOING LIGHT, OP. OK. GOOD. RER DOME LIGH
009,					D: 8509-324-5N. 8911-261 RENIOVED.	SWITE	H, PN	. 456	-732	OP. CHECK GOOD, SELVICED BATTERY,
OPIC	HEC	CK	GOC	D.	A Company of the Comp	LUBE	DLAN	DING	SFAP.	AIR FRAM IAW PIPER MAINT. MANUAL
and the second second	11 01	53 5		motes motes discounts	FOR TECH AVIATION.	_			OCTIZ.	inspection and was determined to be in
6/1/00	314	60 ·	ent Tr	3160	THIS TIME & DATE PERFORMED AN ANNUAL			-		Airworthy emertion.** AD'S reviewed through 99-05-09.
11.5PC	076	1)1	0511	EFECT	S NOTED BATTERY DUE ALO ELT JAW FAR					Tach Time 3/60 Total Time 3/60
KIT-LL	11/17	-/ K	7 1710	11/1/11	TIM TIKES SEPVINENSTA					Michael A. Luney 6/1/2000
AME	AMO	104	11/6	· WITE	REPAIRED BROKEN BONDING STRAPON LEFT.					Mechael a Heleg

4					-			1	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS OF THE PROPERTY OF
DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)	19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERNUSER OF ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC STRIES.)
3/31	3065		3065	THIS TIME & DATE PERFORMED AN ANNUAL					
111-1	ECTIC	NU	SING	PIPER CHECK LIST . INSPECTED ELT	_				Loon. B
TAIL	FAR	71.3	07(d)	NO DEFECTS WERE NOTED BAILDY	_				certify that this AIRCRAFT. has been
3/16	+ 7/2	1001	REPI	HIRE CABIN DOOR SI INFR BRACKEI. TY	_				in every feet III sector to de to be III
DCO	R HIN	GE 1	1N5.	SERVICED BATTERY, CLEANED, INSPECTED	_				
ARE	PACK	ED U	VHEL	BEHICIOS, CHECKED BRAKE WE'S	_				AP'S reviewed through Tech Time 3065 Total Time 3065
AND	FOUR	1070	BE	WITHIN LIMITS . CLEANED & LUBED	_			1/1	Tech Nine
LAN	DING	GE	AR &	AIRFROME.	_				Michael A. Lahey 3/3/1/2000
					-				michaetteettele Date
		-			-				
		1	-		_				A & P 264025341 IA.
					-	7			

GENERAL INFORMATION AIRCRAFT RECORD PA38-181

MODEL N90874.

DATE MFG.

ENGINE(S) CURRENTLY INSTALLED. SERIAL L-31152-36A. 0-360-A4M

MEG LYCOMING MODEL

MANUFACTURER PIPER

REGISTRATION NUMBER

BLADE MODEL

SERIAL MODEL

PROPELLER(S) CURRENTLY INSTALLED. HUB MODEL

MODEL

SERIAL BLADE MODEL __

SERIAL SERIAL

SERIAL SERIAL -AIRCRAFT LOG

SERIAL

SERIAL

SERIAL

SERIAL 38-8690014.





Log #1
ends 3/2000



1ech = Aviation = Aviet 310/3000

Wilkes-Barre/Scranton International Airport • Avoca PA 18641

Telephone • 717-457-3400 • FAX 717-451-0952

TARY Lawir

RAR TURN COORDINATOR, PN. 1394 1700TZ SERIAL NUMBER 8911-361 INSTALLED, SERIAL NUMBER 9411-23 REMOVED, OP. CHECK GOOD.

mosceley ASP364035341 FOR TECH AVIATION.

JUSED SOLD THE

Aircraft Time

Total

This Date

Brought

the state of the s

Date

AIRCRAFT LOG Recorder Maintenance Reading 2967 VERTICAL TROUBLIN DILOTS SERT TRU PA 38 MM, OP CHECK GOOD, INSTALLED WELL LEFT &RIGHT BRAKE UNING. LUBED LANDING. GEAR & AIRFRAME SERVICED BATTER -0300 & 124 FOO 1-5CR-0216. IN ACCORDANCE, WITH AD THESE HOSES. MEET 150-538 TYPE D REQUIREMENTS DUE 8 YEARS OR LOCO HRS. INSTACLED WELL BAS WOULD

Registration No. N90874, Certificate No. Signature and Remarks FORMED AN ANNUAL INSPECTION USING PIPER CHECKLIST. FAR 91.307(d) NO DEFECTS NOTED BATTERY DUE 7/3001. OR STABILATOR STATIC WICKS, LUBED AND ADJUSTED CK. GOOD. RAR # 2 SHOULDERHARNESS-UNJAMMED, OP. CLEANED INSPECTED, REPACKED BLL WHEEL BEAKING. INSTACLED 3 NEW OIL COOLER HOSES, PN. 194FOOL-SCR 95.36-13 nomt. 39-2788 THE NEW PIPER AIRCRAFT INC. NO REPETITVE INSPECTIONS ARE REQUIRED NEXT REPLACEMENT AIRFILTER ONEW B-3-5-1 VAC FILTER. "I certify that this AIRCRAFT inspected in accordance with AN ANNUAL

has been, inspection and was determined to be in Airworthy condition." 99-05-09
AD'S revised through Tach Time 2167 Total Time 2967 Michael &. Laboy Date 1 P 2640353411A.

Date	Aircra	ft Time	Recorder	
	This Date	Total	Reading	Maintenance
11/10/99	Brought Forward ->	2867.	2867	TACH. THIS TIME & DATE INSPECTED ELT IAW
DEW BA	3 INDUC	CK. 600	D. REK	RT. FRONT COULING FAS R. CLEANED AND LUB
FOUND TO	OBE WI	77+1N C11	1115,	
	4			
tord (a)	day on the	TOTAL	12	
41 +4 63	hearings as restricted	orde us bess W Envisoris Milabel essa	4 =	
1 + 44(1-4 - 1111 - 4.8)		N. J. / Tem, see		
	FEST LANGT	· · · · · · · · · · · · · · · · · · ·	H ch.	
nie.		***** / (a	9 (10)	
Total To Carry Forward				

Registration No. N 90 674.

	Signature	
VOIL	=01.0 TO 11 K	A-11 10001
,		has been
ingacted in	was determined	to be in
Tach Time 380	7 Total Time	2006
Mickael A. Jah	ey 11	10 199
mukaelee	Tilley	2/-
A & P 2640253	14.	
'	Tach Time See	Tach Time 2867 Total Time A & P 264025341 14.

AIRCRAFT	LOG

Recorder

Reading

THIS TIME & DATE

2768 CHECKUST. INSPECTED ELT IAW FARGI. 207(1)

RAR DORSBL FAIRING PN 99619-002 WITH

WITH NEW. RESEACED & SERVICED SHIMMY

Total

2768

Aircraft Time

This Date

Brought

Forward

Date

9/17/99

Total To

AERO PN 907. PMB REPLACEMENT LANDING LIGIT, OP. CK GOOD SERVICED

CHECKED BRAKE WEAR OFOUND TO BE

and Remarks Maintenance PERFORMED AN ANNUALINSPECTION USING PIPER

NO DEFECTS NOTED. BAITERY DUE. 7/2001, PAR LEFT MAINTIRE WITTONEW. BERLEFTSHOW- WER HARNESSCOVER. PN 78054-00ZWITHONEW

NEW, BARDOME LIGIBTUEND, PW. 12715-000 DAMPER. RAR BTWINDSHILD WITTHLA

WITHIN LIMITS.

POSSEMBLY RELAMPED

inspected in accordance with ANANUAL BATTERY dTIRES-

Registration No. N90874,

inspection and was determined to be in

Michael & Laber

mideae la tellet

Signature

Tach Plan 2768 Total Plan 3768

Certificate No.

Date	Aircra	ft Time	Recorder		
	This Date	Total	Reading	Maintenance	and Remarks
8/27/99	Brought Forward →		2712	REIR ADI PART.	NUMBER
SN. REA	POVED.	9589.	OP.C	K. GOOD. RER BOTH	SHOULL
SERVICE.	ABLE A	SSEMA	BLIES.	INSTACLED NEW.	HINGE
NEW L	PAERO	CAPT.	WIND	SHEILD PART NO.	905 1L
#950/	CON-1	JO WT.	d BAL	ANCE CHANGE	NOTED
		barr	2		
9/17/99	10-15-6	- 176 M. (3) -11623 (4)21	2768	TISE ABOVE ENTRY	FOR U
ERROR	PAR	TINST	ALLE	DISPMB	APPR
		Y8.6. A. A.	19		
Total To Carry Forward		20.04			

Signature Certificate No. ks R 060-0020-01, JN INSTALLED. 12941 DER HARNESS ASSEMBLIES WITT REPART E ON OIL ACCESS DOOR, INSTALLED A U ACCORDANCE WITH STC. 2A13 & DRG.), EXECUTED FORM 337. Mortech Agricusy WINDSHELLD INSTALL ATTON IS IN. ROVED, NO 337 IS BEGUINED

Registration No.

N90014. Registration No.__ AIRCRAFT LOG Certificate No. Signature Aircraft Time Date Recorder and Remarks Maintenance This Date Total Reading INDICATOR. 060-0020-01-SERIAL NUMBER, INSTALLED Brought -7/23/99 mosciled PAPACHOUSE SCA4.7 TACH. RAR ATTITUDE GOOD. R9589- SN. REMOUSE 10514, OP, CHECK. PERFORMED AN ANNUAL INSPECTION USING PIPER ELT IAW FAR 91. ZOT (6) NO DEFECTS NOTED, BATTERY DUE DD, AND FAR 91. ZOT (6) NO DEFECTS NOTED LARRIESTE 3668 CHECKLIST, INSPECTED OD, CK GOOP. REIR RIGHT & LEFT SHOULDER HARDESES NEW INDUCTION AIR FILTER LYBED LANDING GEAR 8/10/99 MOSTALLED NEW BRAKE LINING & DISCS, INSTALLED Certify that this AIRCRET has been inspected in accordance with AN ANNUAL ALL WHEEL BEARINGS AND AIR FROME · CLEANED IN SPECIED AND REPARED inspection and was determined to be in JERVICED BAINERY Airworthy condition." 99-05-09 AD'S reviewed through Tech Time 2668 Total Time 2668 8/10/99 midual Ce Belees TO SECUL VA

		AI	RCRAFT LOG		Registration No. 190	874.		
Date	Aircro This Date	oft Time Total	Recorder Reading	Maintenance	and Remarks		Signature	Certificate No.
6/16/99 BRACKET BOMT, 39- INSPECTE BIRFROM	Brought Forward ABAN 11057. BAREDINE ALA	ASTO ERY, OL PAPER ACKED O A WOING	CKGG	THIS TIME & DATE CHECK LIST, INSPETED TOD BATTEKY CHANGE TEL DOES NOT RAPLY BEALINGS & CHECKED R SERVICED BAITERY.	DERFORMED AN ANNUAL IN ELT IBW FAR 91. 207(d) IN DUE TIDOOI. BD99-05-09 THE BREE WERE, A FOUND TO BE	SPEC STAC WEWN WITH	CTION USIN LLED NEW PIPER AIRCA BINFILTEL, G BINLIMITS	G PIPER HOLD DOWN 6 PT INC. SLEANED, LUBED
111 505 B	7-18 7-80 8-18 7-80 8-18 7-8 8-18 7-8 185 0-8	the state of the s	4 4		insp Arre	ection a	hat this HIRCUS a accordance with and was determined oudition." ad through 79-	to be in 05-09
Total To Carry Forward	+	k del			me	echtee.	la Haley	/16/99 Date

		AIR	CRAFT LOG		Registration No		Certificate No.
Date	Aircra This Date	ft Time Total	Recorder Reading	Maintenance	and Remarks	Signature SINGPIPER C	1000
5/7/99	Brought Forward ->	3470	2470	THIS TIMES DATE PERF INSPECTED ELT IN ACC	ORDANCE WITH FAR91, 307(d) NO	DEFECTS NOTE D WHEEL BEF	CINOS,
SERVICED	BATTER	1 d TINE	5 INST	THE WITH NEW, HUED NEW LEFT &	PLANCE WITH FAR91, 207(d) NO CLEANED, INSPECTED & KEPACKE RIGHT BRAKE LINING, RE-LAMP FILTER, REPARED WOSE HEIDT	SHELD ON TOP	COWLING
_	J						
61a 199				RAK KIGHT MIEIN			
MRE, RA	K 78161	ST NAL	141612	ST PECPTICIAL -OP.	[vil con	tify that this AIRCRAF	ANNUAL
CK: 6001	REURA	MPEP LOC	CIGHT	modeleef Heradosson	inspec	tion and was determined	to be in
नार वर्ष कर	September 14		728	FOR TECHO OBVILLO TICA	AD S	eviewed through 99-0	9470
managalanis (d.	the particular of the V	(1) (N () (1) (1)					
The same and a second	M2 ET - 8 A /				Micke	weeka Heleg- 3	7/99 Date
		· da.				264025341 IA.	

		AIRCRAFT LOC	•	Registration No. 9087	ref -	
Date	Aircraft Time This Date To	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.
12/28/98	Brought ->		LANDING LIGHT, OP.	487-904 PILOTS PUSH TO THIK SU CHECK GOOD, BLED LEFT BRI	UNCH. RELAN AKE. OP, CHE	MOED ECK GOOD.
LEAK CO	5D.				moxelees	15 TALLED
. 1/18/99		3331	RD98-35-10 MIRCHOFT.	BELTS INC. DOES LOT APPLY TO I	myaley-	1491
212/99			HAR ELECTICIO FUEL OR MAINT. MANUAL. OR	CK. GOOD; LEAKCK GOOD.		
3/1/99	33	71 2371	THIS TIME & DATE DERFORMED PIPER TABLETTE-1 INSPECTION PAR	REDUCTION USING Impacts	d in accordance with on and was determined	to be in
D9-18-1- O FOUND WIT BATTERY &	HIN LIMITS, TIRES, INS	SCIS NOTED	BHITERYDOLE	THECKED BRAKE WEAR BULD AD'S TON	rieved through 98-1	
Total To Carry Forward				Michael	rechte Heleg	Date

Registration No. N90874, AIRCRAFT LOG Aircraft Time Date Recorder Certificate No. Signature This Date and Remarks Maintenance Total Reading 11/13/98 Brought "LATOR TRIM SYSTEM IAW PADS MAINT, MANUAL Forward 2219 TACH - RERIGGED moreleux 264025341 11/16/98 PARKER HANNIFIN BER DRIVE DRY BIR PUMP DRIVE. 2248 TACH. C/W AD98-23-01 PN 350 NISTALLED IAW 5L48-GROUND RUN CD.CK GOOD, LEAK CK GOOD. RELAMPED LIGHT, GPCK GOOD. REPORMED AN ANNUAL INSPECTION USING PIPER 12/1/98 THIS TIME EDATE 2371 2271 REPORT. INSPECTED ELT IAW FI TABLE III - 1 INSPECTION TO BENUBBER PN. 79073-00-CLEANED INSPECTED & REPORTS NOTED BATTERY DUE. 7199, BER NOSETTRE EL NOSELAG TO BE WITH IN LIMITS SERVICED BATTERY- AD98-14-03 ALL WHEEL BEARINGS CHECKED BRAKE WEAR AND FOUND GCS NOT ROPPLY TO SERVAL NUMBER OF K 1600 INSTALLED ADMI, 34-1063 (ALLIED SIGNAL RTIGHS ATCHANSANDE ESTED IN BOOORDANCE WITH AN ANNUAL INSPETON (45428) I CERTIFY THAT TIES AIRCROFT WAS INSP CONDITION PUD IS APPROVED FOR LETUENTO SERVICE BND WED DETERMINED TO BE IN AN AIRWORD mrkaly, ASP 264025341.IA FOR TECH AVIATION. Total To Carry Forward

			KCKAFI LOC	•	Registration No			
Date	Aircrat This Date	t Time Total	Recorder Reading	Maintenance	and Remarks		Signature	Certificate No.
CABLE TE	USIONS.	POJUS	ED RU	THEH. THE STITE & DATE III-1 INSPECTION REPORT INSPECTION REQUIRED TALLIOTON LA A NEW ODER & RIGHT HIELRON- TR. SERVICED BATTERY -1 DRYBIR FILTER,		SBER	WHITE DOT.	CHECKED CE BEALINE
					112	and the	that this AIRCRAF a accordance with a and was determined	to be in
					AS	rworthy i	ondition." ond through al7/ Total Time	901-00
					70	steal A.		1016198
Total To Carry Forward						A P 26.10		

		AIF	CRAFT LOG		Registration No. No. No.	ref
Date	Aircra This Date	ft Time Total	Recorder Reading	Maintenance	and Remarks	Signature Certificate No.
E/14/98 INSPECTION INSPECTED DUE 1/99. C	Brought Forward ON USING ELT IA SIW # AL	W FARG 176-01-1	PTABL 1. 20 To	THIS TIME & DATE PERFORMED AN ANNUAL EMIL-1 INSPECTION RECONS. EMIL-1 INSPECTION RECONS. EMIL-1 INSPECTION BATT. EMIL-2 INSTALLED	9/10/98 - 2125.0 TACH . RAR IGNTION PIPER P.U. 688-178 TCMAU. 10.3.	FOR TECH AVIONON
NEW LEA BIGHT TO	T MAII ORGUE	UTINE KNEE.	3.ERVI		MAIN TINE.	MASTER SOLVE TERHAVIATION
- 8		+	inspecte inspecti Airworth AD S rev Tach Tim	on and was determined to be in sy condition. Writered through 98-09-08		
Total To Carry Forward			13	A. Leibey 8/14/98 Rec Concluded Bate 1025341 IA.		

		AIF	CRAFT LOG			Registration No.	N90874	6	
Date	This Date	Tima Total	Recorder Fooding	Worntenan	0	and Remarks		Signature	Certificate No.
r c a f	FACRS # TVMR35 required by FAI comply to Appealtimeters are of the aircra Altimeter #1 P/I Altimeter #2 P/I Signature NEXT DUE	AR 91.411 To a second	TECH AVIATION 101 HANGAR RD AVOCA, PA 18641 ESTS AND INSPERT 18641 ESTS AND	CTIONS and static tests ccordance with and		TIBIPS - 1971, & TACH THE PAN ANNUAL INSPECTION REPORT, INSPECTION REPORT, INSPECTION REPORT, IN PANEL PN. 67436 BRAKE WEAR & FOUND OF REPACKED OF REPACKED OF REPACKED OF REPACKED OF REPACKED OF REPACKED OF THE PROPERTY O	TED NE. HT, RAR -004-0. TO BE WI WHEEL. DAIRER SWITCHE Inspected Inspection Airworthy Tech Time Michael A. Michael A.	PIPER TAE PIPER TAE	DUE DUE SUITCH CHECKED
carry rormand							1 8 P 26AC	143341 IA.	- Company of the Comp

TECH AVIATION 101 HANGAR RD	Registration No
Date Aircraft Time AVOCA, PA-18641 This Date Ford Reading	and Remarks Signature Certificate No.
N90874 AIRCRAFT LOG BOOK ENTRY 06/24/98 1941.5 TACH	TECH AVIATION 101 HANGAR RD AVOCA, PA 18641
REMOVED AND RELACED DIRECTIONAL GYRO PART NO. 060-0022-00 SN. REMOVED 1882. SN. INSTALLED 1672 OPERATIONAL CHECK. GOOD. MICHAEL A. LAHEY A&P 264025341 FOR TECH AVIATION	FAR 91.413 TESTS AND INSPECTIONS CRS # TVMR353S certifies that the transponder tests required by FAR 91.413 were performed in accordance with and comply to Appendix F of part 43. Aircraft N# 90879 The aircraft is returned to service.
Bi si a a a a a a a a a a a a a a a a a a	Transponder # 1 P/N KT 76A S/N Transponder # 2 P/N S/N
	Signature Date Work Order # NEXT DUE 7-2000
Total To Carry Forward C1616T OP, CK. GCOD, A&PO35341	

Registration No. N90874, AIRCRAFT LOG Certificate No. Aircraft Time Recorder Signature Date Maintenance and Remarks This Date Reading Total DATE PERFORMED AN ANNUAL INSPECTION USING PIPER Brought Forward 5/22/98 REPORT, INSPECTED ELT I.A.W. FAR91, 2070, NO DEFECTS 1873 9575 BENDIX IGNITION SWITCH, OD. CK, GOOD NEXT DUE NOTED BATTERY DUE 7199. CIWHAD-16-07-12 ADMIT, 39 MOUHRS. CIWAD-95-36-13 ADMIT. 39-9472 THE NEW PN, 194FOOI-8CR-0300 AND PN-129FOOI-8CR-210 LINES IN PIPER AIRCROFT OIL COOLER LINES, INSTALLED NEW RAR RIGHT & LEFT MAIN TIRES, RAR LEFT BRAKELINING DREQUIREMENTS ELIMINIATING REPETITIVE INSPECTION CABIN STEP, RAR STABILATOR TRIM BAIRRELL BUDSHAFT BLLOTHER DISCSALINING WITHIN LIMITS REPAIRED REGLUED CABIN DOORSEAL, QUEANED & LUBEO LANDING SERDELO SESAY6-000 IAW PAJS MAINT. MANUAL GEAR & AIR FRAME, SERVICED BATTERY. T certify that this AIRCROFT imported in accordance vish AUANUVAL TACE BAR AVIONICS 1919 impaction and was determined to be in GOOLING FAN ASSEMBLY P.W. 553.003 OP. Airworthy condition." AD'S reviewed through 78-03-08

Tach Time 1879 Total Time 1879 CHECK GOOD. muchae Redeler 5/32/98 modeley AAP 36402534 Total To A & P 26402\$341 Ya Carry Forward

Registration No. NYOS14 AIRCRAFT LOG Certificate No. Signature Aircraft Time Maintenance and Remarks Recorder Date PERFORMED AN ANNUAL INSPECTION USING AIRER Reading This Date Total TACH THIS TIME & DATE TABLE III - I INSPECTION REPORT. INSPECTED ELT I.A.W. FAR 91: 207(4) NO DEFECTS REPACKED WHEEL BEARINGS, SERVICED BATTERY, INSTANCED NEW AN, 66894-03 MUFFLER, CIWA AD-76-07-12 ADMIT. Brought Forward 3/24/98 1772 1772 NOTED, BATTERY DUE 7/94, OLEANED, INSPECTED, AND CO-10500 BRAKE LINING IN RIGHT POSITION. INSTALLED 100 HRS Q/W #AD. 95-36-13 ADMT. 39-9472 PIPER OIL COCKER 100 HRS HOSE BEPLACEMENT DUE 10/99 OR 1829 TACH. 39-2575 BENDIX IGUITON SWITCHES, ORCK, GOOD NEXT DUE TIRES - CLEANED & LUBED LANDING GEAR AND AIRFREME HOSES - BY INSA, NO DEFECTS NOTED, NEXT INSA. DUE REPAIRED CARB HEAT MUFF, SERVICED BATTERY TOND RELAMPED LANDING THI certify that this AIRCRAFT 4120198 inspected in accordance with AN ANWUAL 1822 inspection and was determined to be in LIGHT, OP, CHECK 6000

AD'S reviewed through_ 98-03-08 modeley A\$P264025341. Tach Time 1773 Total Time 1773 3/24/98 Mickael A. Lahey machaelerteles Date A & P 264025341 IA. Total To

Aircraft Time

Total

This Date

Brought

Forward

Date

Total To Carry Forward Recorder Maintenance Reading

1672 1672.

and Remarks

Registration No. N90874,

VRG FILTERS.

Signature

The certify that this AIRCOST inspected in accordance with W ANNUAL inspection and was determined to be in

Certificate No.

Arworthy condition." AD'S reviewed through Tach Time 1672 Total Time 1672 Michael A. Lahey midial & Haley Date A & P 264025341 IA

AIRCRAFT LOG Registration No._ Aircraft Time Recorder Certificate No. Date Sianature This Date Maintenance Total Reading and P-----Date: 8/21/97, A/C Time: hours, N Number: 90874 A/C Make: PIPER A/C Model: PA28-181 A/C SN: 28-8690,014 W.O. Removed the following equipment: 3M WX-10A SYSTEM Installed the following equipment: TECH AVIATION The installation was performed in accordance with manufacture specifications and is approved for return to service. 101 HANGAR RD The new aircraft empty weight is: 1615.7 lbs. AVOCA, PA 18641 The new center of gravity is: 86.82 inches. Tach Time 1630.3 N90874 10/24/97. The new moment is: 140273.3 The new yseful load is: 934.3 lbs. Remove battery part # G35 S/N G1064630 install batery part# G35 S/NG01723574 mest Causes Authorized Signature James D Falvo A&P 187568332 Lunes O falo A4P 187568332 INTEGRITY AIR SERVICES, INC. 63 TOM HARVEY ROAD WESTERLY, RI 02891 FAA CRS # WWZR309K Total To

Carry Forward

Registration No. 90874 Certificate No. Aircraft Time Signature Recorder Date and Remarks Maintenance This Date Total Reading Brought Forward 4454003X ILA Total To Carry Forward ed Done

Signature

Certificate No.

This Date Total Reading Maintenance	Date	Aircraf	t Time	Recorder		_
This acircraft inspected and serviced using Piper Inspection Report #230-1039 and the current FAR'S. C/W AD 76-07-12 Bendix Switch ops checked satisfactory. C/W SB #977 Inspection of aft wing attach fittings and treated with Dinitrol AV8. Replaced pitot/static line grommet in wing. Fiberglass repaired wheel fairing fastener areas. Cleaned and treated R/H & L/H windshield post fittings with Dinitrol and installed new AN bolts. Welded small cracks in heat muff. Ops checked ELT per 91.207. Adjusted rudder cable tensions. Cleaned and painted elevator actuating arm. Replace flap ground strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	Date	This Date	Total		Maintenanc	е
Switch ops checked satisfactory. C/W SB #977 Inspection of aft wing attach fittings and treated with Dinitrol AV8. Replaced pitot/static line grommet in wing. Fiberglass repaired wheel fairing fastener areas. Cleaned and treated R/H & L/H windshield post fittings with Dinitrol and installed new AN bolts. Welded small cracks in heat muff. Ops checked ELT per 91.207. Adjusted rudder cable tensions. Cleaned and painted elevator actuating arm. Replace flap ground strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in						6
Switch ops checked satisfactory. C/W SB #977 Inspection of aft wing attach fittings and treated with Dinitrol AV8. Replaced pitot/static line grommet in wing. Fiberglass repaired wheel fairing fastener areas. Cleaned and treated R/H & L/H windshield post fittings with Dinitrol and installed new AN bolts. Welded small cracks in heat muff. Ops checked ELT per 91.207. Adjusted rudder cable tensions. Cleaned and painted elevator actuating arm. Replace flap ground strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	This	s acircraft	inspected a	and service	d using Piner Inspection	
attach fittings and treated with Dinitrol AV8. Replaced pitot/static line grommet in wing. Fiberglass repaired wheel fairing fastener areas. Cleaned and treated R/H & L/H windshield post fittings with Dinitrol and installed new AN bolts. Welded small cracks in heat muff. Ops checked ELT per 91.207. Adjusted rudder cable tensions. Cleaned and painted elevator actuating arm. Replace flap ground strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	Report #2	230-1039 and	the curren	nt FAR'S.	/W AD 76-07-12 Ronding	-
line grommet in wing. Fiberglass repaired wheel fairing fastener areas. Cleaned and treated R/H & L/H windshield post fittings with Dinitrol and installed new AN bolts. Welded small cracks in heat muff. Ops checked ELT per 91.207. Adjusted rudder cable tensions. Cleaned and painted elevator actuating arm. Replace flap ground strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	Switch of	os checked s	atisfactor	v. C/W SR #	977 Inapostion of oft wing	
areas. Cleaned and treated R/H & L/H windshield post fittings with Dinitrol and installed new AN bolts. Welded small cracks in heat muff. Ops checked ELT per 91.207. Adjusted rudder cable tensions. Cleaned and painted elevator actuating arm. Replace flap ground strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	allacii 11	LLLIngs and	treated wi	th Dinitrol	ATTO Dont I /	10-
Dinitrol and installed new AN bolts. Welded small cracks in heat muff. Ops checked ELT per 91.207. Adjusted rudder cable tensions. Cleaned and painted elevator actuating arm. Replace flap ground strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	TIME STOR	muer III MIIIS	• riberglas	ss repaired	raboal fire f	
muff. Ops checked ELT per 91.207. Adjusted rudder cable tensions. Cleaned and painted elevator actuating arm. Replace flap ground strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	aleas. Ul	leaned and L	reated R/H	& L/H Wind	chiold near City	-
strap. Serviced tires and brake reservoir. Weighed and inspected fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	DILLITETOT	and Install	ed new AN	polts. Weld	od omell	
fire ext. per NFPA-10. Note: 12 yr. hydrock due 9/97. Cleaned and lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	Cleaned a	and nainted	elowater a	J/. Adjust	ed rudder cable tensions.	
lubed all hinge points. Aircraft exterior and windows cleaned and fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	strap. Se	rviced tire	s and brake	rocom	m. Replace flap ground	
fuel sumps drained. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in	fire ext.	per NFPA-1	0. Note: 13	vr bydra	• Weighed and inspected	
in accordance with an Annual Inspection and was determined to be in	Tubea all	. HTHE POIN	LS. ALICIA	T exterior		_
In decordance with an Annual Inspection and was determined to be in	Tuci Sump	o draffied.	T CELLILA 1	nat thic o	inc. C. 1 1 1	
airworthy condition.	in accord	ance with a	n Annual Ir	aspection a	nd was determined to be in	_
Startel heller	airworthy	condition.		1	" " " " we we ter ill lied to be ill	
			Del.	adll h	Mes	-

Installed loane transporder KT76 Att 1523. 06-26-96 MORTHEASTERN AVIONICS INCA Barnes Municipal Almort Ave temperate facts and increasions Westfield, Min PAR Pric 63 Reproducts FAM FYIMODE Ma 2: KG K776A#1527 W.O. # 5454 Telunde APP & Paro. A C.C to 20000 feet Ethendirl make United Duction 5974P-1 serial 96609 06-26-96 Plant careform Avionics Inc.

Registration No.

and Remarks

AirFlyte
Barnes Municipal Airport
32 Airport Drive
Westfield, MA 01085
CRS #QFYR349K

Total TACH/TT = 1564.9 Hours SMOH = 535.7

AIRCRAFT LOG Registration No.__ Aircraft Time Date Recorder This Date Maintenance Cer ficate No. Total Reading and Remarks Signature Brought Forward 1551,2 Installed Voltage Regulator "IN AR-8314 5/W 80018406. Hdj. &
Test Ran Mircraft O.K. — end— 8-28-95 Total To Carry Forward

		AIR	CRAFT LOG	;	Registration No			
Date	This Date Total Read		Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.	
NovemBEQ 29,19	Brought +	TACHE READS	1502.6	REMOVED DLD TURN COORDINATOR	3-21-95 Tach 1524.1 Removed + reins	talled overha	whed	
	AND INST	ALLED NE	V TURN	COORDINATOR MODEL # 1344 T100-72,	h 4 1 1 2 00 0 1 1 10514	the sell of	of Turne	
	S/N 9411-2	. REINSTALL	ED DIREC	TIONAL GYRO AFTER OVERHAUL	tay, work was done 1/4/w Pipe	PA-28-181	mantenare	
	MODEL # KG	107, S/N 18	82. OPS	CHECK OhEND-		1001		
				Paris of Mill.	Michael Nem	Re A+ P 4356	8879	
		A TO SECURE		A+ P:30671288				
Total To								
Carry Forward								

10-0200

				AB	10-0200-000	CIAAT
	Al	RCRAFT LOG		Registration No		•
Date	Aircraft Time This Date Total	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.
	Brought Forward → Data 5-/2	Z-94 Total Ta	1399,1	august 12,1994 Pack Reads 1441.	3. Roslocal	lest
11	Manager of the Inspect of	7377,/	certify that this Haling has been		Sequices	batter
large or	Co . I () Condition	Mertinent desait	with a formed in the anti-delity are or file at this facility are or	bake Res. and Times lights still	CARNING + 8	tothat
4. Stall WARRING	condition.	Sikorsky Me	Three Wing Maintena a morial Airport, Stratford, CTa66467.	of Lecked good. Lived exformal fly	all confels	-END
loter screen	leased Canding Signature	Spair Station Si	5R201N Strattory CT-96467	THREE WING MAINTENANCE CEI SIKORSKY MEMORIAL AI STRATFORD, CT 064	RPORT	
Gear, wheelbe	sings Lubed Hight con	tible cleck	ed & I had and	Authorized Signature	rode	
			The series	WORK ORDER NO	26	
	Cont ;			- SENTIFIED NEPARTON	OF SUSCINA	
Total To Carry Forward						

		AIR	Registration No				
Date		Aircraft Time					
	This Date	Total	Recorder Reading	Maintenance	and Remarks		
2-15-93	Brought Forward	TACH	209.4. INS	MILLED NEW PLN CO1-100 DIACHRALM	Pr		
IN COMPASS	AM) SERMU	ED WITH CO.	npass Fun	and to appropry with FAR. 43 Access	Date 4/29/93 Total Time 1238:2 TSMO		
-	THRE	WING MAINTEN ORSKY MEMO STRATFORD	ANCE CENTER	INC HAS ISBAN	Hourmeter 1238.2 I certify that this Airc		
	OII	STRATFORD	17 1 102497	TIGHT	inspected in accordance with An Annual Transpected in accordance with Annual Transpected in acc		
	SAMONICS	Authorized	Dien .	Visitaria (1)	Work Order # 10357 Three Wi		
-	TOP CERTIFICATION	ORDER NO.	TATION SLEE	3201N	Certified Repair Station SL5R201N Signature		
-	1912.01				wheel begins - and		
	1				helpour Replant 1352.8. Replan		
	4				hel Pressure guage w/Now unit.		
Total To Carry Forward					hal Papersura guage w/NOW unit. a heat charled good - No teaks No		
	1						

and Remarks	Signature	Certificate No.
Prop 17 = 1238	2	
./ /	Installed new	condor
Date 429/93 Total Time 1238,2 TSMOH 19/9 Hourmeter 1238,2 I certify that this Aircraft has been		
Department 1258.2 certify that this 2000 has been	100+676 1105	/ >>
As Regulations and was determined to be in an airworthy		7n 6015
Pertinent details are on file at this facility under	1 1/- noline	stbled
Work Order # 10351 Three Wing Maintenance	-3	
Center, Inc., Sikorsky Memorial Airport, Stratford, CT 06497 Certified Repair Station SL5R201N	Oralhes, Inones	
Signature Put any	Flight controls	Gear and
wheel bearing - and		
20 0 - 10	VING MAINTENANCE CEN	TER, INC.
SIKO	RSKY MEMORIAL AIF STRATFORD, CT 064	
The supply work with the supply with a	nner R. Moos	
Charles I a la l	(Authorized Signature	7
WORK	EDER NO. 1062	2 5B201N

10-0200-000 -

		AIR	CRAFT LOG		Registration No		
Date	Aircra This Date	ft Time Total	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.
4-30-97 BETWEEN PURE		THEE WI		TO NEW PLN 63901-057 FAIL HOLE VICE CENTER, INC.	TOUR IN Complie willis EAD A2 Appondix E	the altimeter and statle to	yelein heen
		ST	RA, FORD, C	T 06497	Make King Model 1714 s/N 45728 Model 5/N 45728 Model 5/N 95728 Model 5/N 16,600	10	A-
11-13-92		WORK OR	PEDAID OF	9725 ATION SLER201N	THREE WING AVIONICS STRATFORD, CT 06497 CRS SL52201N Da	gnature 2-f-97	-hr:
aired als	Junes ch	Replaced P. Go	I left lead	Line of Condon 600x6x680		TRATFORD, CT 06497 CRS SL52201N	
Anled Aff	eftend	flighten	Gold N	CENTIFIED REPAIR STATION SLERZON	JN 00-10-009 ALS functions ST		rt · O
Total To Carry Forward			Co	THREE WING MAINTENANCE CENTER, INC. SIKORSIXY MEMORIAL AIRPORT STRATFORD, CT 06497 (Authorized Signsture)	end	DER NO 10311 REPAIR STATION SL5R	2201N

AIRCRAFT LOG Registration No. Aircraft Time Date Recorder Certificate No. Maintenance Signature and Remarks This Date Total Reading Brought Forward Total To Carry Forward

-		AIR	CRAFT LOG		Registration	No		
Date	Aircra This Date	ift Time Total	Recorder Reading	Maintenance	and Remarks		Signature	Certificate No.
-	Brought Forward ->					2	frag Do	2
3-27-91	w/018	27A In	1211 E	XCH Toler Constant	March 19, 1992 Yach Reach 1029.2. Engine Total	16 1029.2. A	A DA DECON	Ali M
P/NI.	394700-	3-SP S/	V4651	Remp ck of	SN L-31152-36A . ENge	Time 1029,2 1	la de co	10000
Maintenna	w Kelest	1 -1 -1/2	bed	Oll partiaged state on the	for med OUD	7 / THREE W	ING MAINTENANCE CENTE	R, INC.
No.		ntonance T 06497.	oo Wing Ma Stratford, C	Order 8 Silverstor Memorial Aircott	Thereand This ill	SIKOR	RATFORD, CT 06497	
		Graphic Control	HEI AIR S	VING AVIONICS TO THE TRANSPORT			Authorized Signature	
Dec 23/4/ Yar	1 889 P R	0 0				WORK OF CERTIFIE	DER NO. 9648 DREPAIR STATION SL	5R201N
Condon 600×6x	GPR Replace	of Rt disco	Re SIKO:	MG MAINTENANCE CENTER, INC. MEMORIAL AIRPORT AUTO A MARCH				
Repacled RT A	earing -air	edall gina	Things of	Authorized Signature)				
Carry Forward			WORK OF	RDER NO. 9485 DREPAIR STATION SL5R201N				
				MAIN SIATION SL5RZUTT				

T UBUI-DOS

Date	Aircra	ft Time	Recorder	Maintenance	and Remarks	Signature	Certificate No.
	This Date	Total	Reading	Mullion			
nogd (HREE WING MAINT SIKORSKY ME STRATFOR VAUINCE	Reing Reing ENANCE CENTER WORLD ALRECT DICT OSCIP Moscle	806.6 Baffer	Replacement Safe	cted in accordance with An Annual Free and current ition. Pertinent details are on file at this facility under ter, Inc., Sikorsky Memorial Airport, Stratford, CT 0649	Because Class	all primary
CE	RTIFIED REPAI	STATIONEL	1201N	THE WING AVIONICS ON THE PROPERTY OF THE PROP	TITE THANCE CENTER UIC.		
Total To Carry Forward				THE MESSAGE AND ACT OF THE STREET	WORK ORDER NO. CURTIFIED REPAIRSTATION SLORZOTM		

Registration No.__

Registration No. 90874

Date	Aircraft	Time	Recorder		and Remarks	Cinnatura	Carrica A
	This Date	Total	Reading	Maintenance	Nemarks	Signature	Certificate No.
	Brought Forward				11-30-90 776,4 Tach. Sustalled	Pu "O" RING SE	us.
	TACH 718.1	10/1	red 50 h	e Inspection on Ainthone	and wiper Assembly in piloss fer	hans desuec	
Chacked B	rokes and t	Res Sen	ired Lier	- 11 worke	Assembly. bled brane as required.	/	CRSSL5R WO# 86
Carlalla	V. V. I	Dattery,	with flui	d, lubed and decked flight		t the altimeter and static	system
checked G	neched ope	ration of	Lights, F.	totheat, Stall waring , Ops	and found to comply with FAR. 43 Appendix F. Make KUG Model KT7(As IN 45728	nd by FAR Part 91.44 ha	ested to
Checked Ge	THREE W	100, 97	acidor of	Page Sud	Make NA Model LTAR 43 Appendix F. Make NA Model LTAR S/N 45728 Make NA Model NA S/N NA Date 1-16-90 Signed M. Coouliff	feet. W/O #	SH
	9	TANFORD, C	J 06497		THREE WING AVIONICS STRATFORD, CT 06497	1-16-91	ng3
	Wanie	Authorized Sig	nature		CRS SL52201N	THREE WING AMONICS PRATFORD, CT 06497	
Total To	CERTIFIE	DER NO DREPAIR STA	TIONSIED		THREE WING AVIONICS	CRS SL62201H	
Carry Forward			SHOLDR2	DIN	STRATFORD, CT 06497 M-Cascalth		

Date	Aircraft Time This Date Total	Recorder	Maintenance	and Remarks	Signature	Certificate No.
	Brought Total	Reading	Mallieller			
	Forward	TI.	ODD TO THE OWNER OF THE OWNER OF THE OWNER OF THE OWNER OF THE OWNER OWN	5-16-90 TACH 673.8 INSTALLED ALL NOW ERAKE	IMMES. SERVICED T	RES , BATTORY &
4-19-90	Tach 633.1 Pope	no Less II	insp Inspected tire, bakes	BRAKE RESERVOIR, REPARED B/IT WHERE FAMEING IMED	emar Multon Ci	es SLSRDOIN 7970
battery o	and airtrame for me	the in an air	dition. Send stand by	46/91 Tactt= 806.6 Replaced B/		
	TO COCK	SCHOOL SECTION	0 - M	Scale O To To Both Mepiter & by	Le resevoi	r.
back-in	stalled and performe	legar.	Recieved vaccoum sistem	Ret C. My CAS-515R20IN -	_ and-	
bellitin	916B by istallact	cops ch	329 stall strips. End	CRS-SLOKKOIN		
19	, arming h	IT 765-	329 stall strips. End	WTENANCE CENTER, INC.	MAREE VONS MA	
381 6379	70 24	0 0 0 0 0	KORSKY MEMORIAL AIRPORT	PMORIAL AIRPORT	R-Y 7(6)75(1)278802	
187 187	SIKORSKY MEMORIAL A STRATFORD, CT 08		STRATFOED. CT 06497		anchors while shift distributions	
Total T	The same of the sa	Mon	(Authorized Signature)	0	WORK ORDER N	
Carry Forward	WORK ORDER STATION	Cic	CICUMETA MILITARIA	MRSTATIONSLERZOIN	Apple (Post at 65 cm?)	
	WORK OFFERANSTATION					

Registration No.___

		Recorder	t Time	Date	
Maintenance		Reading	Total	This Date	Date
new Gill	Installed	05.6	TacH= 5	Brought Forward →	10/1/89
HREE WING AVIATION	G1040331.8	s/n G	TacH= 5 Battery	G-35	
RATFORD, CT 06497 CRS E19-111	81				
LG. Pysicuthorized signature)	18				
7510	W.O. No.				
aw tep com stiff		du sons	ALLES NEW	548.8 INST.	11-28-89 TACH
and TEP COM STITE	LIMINGS - SEC	THE BRITER L	EG AVIATION	SIKORS	HTAT SHOUDS,
		2012	RD, CT 08497	A CRS	
		Name of Street, or other Designation of the Street, or other Desig	od signature)		Total To

and Remarks		Signature	Certificate No
509 A PROPEREL TO	me in service		2 /
Date 2-3-90 Total Time 589.0 TOY	OH NA	Cleaned, inspect	one luber
o neter 589.0 I certify in All	CRAFI has been		
hade and colours in	DECIMAL ALLERANT	All Might CONTRO	Is apples,
			1. 1
THE PROPERTY ADVANCE OF A DOLLING AL	THE PERSON OF TH	and puffers as	required.
10. Ordana 7779	or Maintenance	Service all	chis laugh
Perified Received Station Of FROMAN	atford, CT 06497.		1000 1000/5
Gerified Repair Station SL5R201N		as required -	
REPLACED ALTERNATION DELT AS	5V.	0	
ETT 3M Gameso appropriately a curry 236		by SEPT 19	90.
Est geration (check good,	replace patrick	y by string	1
splaced LH (white) wavigation	11/-	WING MAINTENANCE CE	NTER INC.
LA (white) NAVIGATION	19h AIKE	ORSKY MEMORIAL A	RPORT
Statisting Call Oliver in 14 hours	assv I	STRATFORD CT 06	497
"Safednew" O" Ring in LH BRANCE	21/1	1	
where any block boaux. Repor	red J	(Authorized Signatu	(0)
LECON SPECONDARY STOP ASSY, E/	ID WORK	ORDER NO	29
SPCONDARY STOP ASSYS	CEPTI	FIED REPAIR STATION	SL5R201N

Date		ft Time	Recorder	Maintenance	and Remarks	Signature	Certificate No.
-	This Date	Total	Reading	Maintenant	Tollidik?		
Date //20/9	Brought Forward	Tacttd C Total Time	30/6	lunco all Plight controls	3/14/89 - Tach 369.7 - Serviced fires, bat		
HAS BEEN I	NSPECTED IN	ACCORDAN		gear & wheel bearings	arient controls, rights bear a	tot heat checked	HIGAVIATION (Y AIRPORT
TO BE IN AIRWO	RTHY CONDI	HONS AND E	ETERMINED	Replaced bagginge hor del	0/1000	STRATEC	RD, C1 03497 E19-111
OHDER NO.	694	& THE DINDE	R WORK		and painted and.	Howard H.	od signEtufo
neal	mountain fatin	1 0 0	The state of the state of	ELT battery. Buttery		VV.O.100	
_replacem.	ent Dal	= 9/90		THREE WING AVIATION	2-15-89 They 447.9 INSTRUCTO NEW O-RING IN F	PHODE CONTEST WHILE	אנשטא הנוחוצ
				STRATFORD, CT 06497 CRS E19-111	9-14-89 492.3 jach: /nsxa/lex new	CON DOR 600.	6:4PR
Total To Carry Forward		More	W.	(authorized signature)	Tire on IH main gear:	CRS E 19-111	
		883-4	VA CHE DO		V. 11	THREE WING AV	VATION IAL AIRPORT

Registration No._ Certificate No. ale reservoirs. died good, WHOSE SIMME BUSHING 500. 6:4PR

Registration No. Aircraft Time Certificate No. Date Recorder Signature and Remarks Maintenance This Date Total Reading Brought Replaced R/A brake pads te 46/88 TACH 340.3 LUBRICATED Forward TACH 118.1 12-22-86 VC Total Time 1/8.1 THREE WING AVIATION I CERTIFY THAT THIS but Rt. main strut, Replaced Elist controls, SERVICED TIRES, GATTERS AND AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNINGS INSPECTION AND CURRENT FAA REGULATIONS AND DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS ARE ON FILE AT THIS FACILITY UNDER WORK W.O. No. 681 Replaced use set AND STALL WARNING ALL OPERATE NORMALLY ORDER NO. 4562 Seen 2 The ATC Transponder tests and inspections certify that the altimeter and static system and found to comply with F.A.R. 43 Appendix F. required by FAR Part 91.17% have been Make 1/45 Mcdel £ 776A S/N 45728 THREE WING AVIATION orlormed. The altimeter has been tested to Repair St tion No. E19. /// Date 1-17-69 SIKORSKY AIRPORT -feet W/01115A STRATFORD, CT 06497 Pertinent details of the repair are on file at this CRS E19-117 repair station under work order Date 1-17-49 No. 1115A (authorized signature) Total To Carry Forward W.O. No 4562 THREE WING AVIATION Certificate Number REPAIR STATION E19-111

Date	Aircraft	Time	Recorder			
	This Date	Total	Reading	Maintenance		
12-11-85	Brought Forward →		21.7	Complied with AD 85-234		
20-1/		1-	£3.0	Bulletin K.C 190/191/192-9		
7-25-76	Installed		1101	+ STOLANSCOPP.		
	06m 33		pleted	W/0512A		
	Vew E	upty L	Verghi	1629		
	New En	apty (.(-,	F7.2		
	New Cy	ehl L	2d	92/		
	Ven m	onest		142061		
				Ruh		
Total To Carry Forward			Т	HREE VINC AVIATION REPAIR STATION E19-111		

Registration No. N90874

and Remarks	S	ignature	Certificate No.
by complying with ring R	acio Service Cliffor	de. Bood	CRS E19-11
TERT"			
9/18/81e - Tachtime 98.1- Holds	1076 - Luber High	nt controls	- serviced
tires, buttery and broke reser	voirs-lights, stall	exem+ P	itot heat
1005, chedred of the Tire	boles sevie	ecable at	- this time
Re-sected gasolator Litting	E-WING AVIATION noted -	- Aircrah	t returned
Z SIAC	ORSKY AIRPORT ATFORD, CT 06497		
Howars	H. Srouel F		
W.O. No	norized signat		
VA.O. 100 10			* ******
25-86 TACH 118-1 960 SB839 by	installing Kit 765-191	21 Vollin C	20# 4461 85F19-111

		AIR	CRAFT LOG		Registration No. N90874		
Date	Aircraft This Date	t Time Total	Recorder Reading	Maintenance	and Remarks	Signature	Certificate No.
Comple New 1: New C New C New M	Brought Forward + In SIZIA Leted. Empty L ampty C compty C compty lo	leight C.C.	Reading KW69	DME, Folia 337	Date 4/2/8C A/C Total Time 59.4 ICERTIFY THAT THIS Automotive HAS BEEN INSPECTED IN ACCORDANCE WITH AND CURRENT FAA REGULATIONS AND DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THIS INSPECTION ARE ON FILE AT THIS FACILITY UNDER WORK ORDER NO. 36.75 Signed Charles and Active States of the States and Active States	Signature	Certificate No.
Total To	perseded 1-25		THRE	E WING AVIATION N MR. STATIGN E19-111			

Registration No. N90874

Date	Aircraft Time		Recorder	0.10	Signature	
	This Date	Total		Maintenance and Remarks		
OCT 1 5 1985	Brought Forward	2.2	I HAVE INSPECTED	THIS AIRCRAFT AND ISSUED RWORTHINESS CERTIFICATE 91	ler Tests and Inspections required by FAR	
			DATED OC	1 5 1985, I/A/W.	med this date and found to comply with	_
			FAR/21.183(a) PER		Model KT76A S/N 45428	
			THE ALTIN	2. Make NA	AM AM	
			MANE REEL	148 91	Model 113 S/N 111 S/N 111 Rection are on file at this facility under $8-21-85$	
			HAVE BEEN TES	TILL TO 20 000 FT	Tiffainy	
			SIGNED	Lany DATE OCT 15 1985	IPER AIRCRAFT CORP.	
			The FIT is in	Pup		
			11.52.	Satisfy re-	C PRESSURE ALTITUDE IIPMENT TESTS REQUIRED	_
Total To			placement dat	PERFORMED THE	1.36 MAVE BEEN	
Carry Forward		2.2	D. O. A. N Piper Aircr	- ATE: 8-21-85	SIGNED: J. T. H. CANY	

AIRCRAFT DESCRIPTION

Registration NoN91	0874
odel: PA 28-181	Popular Name: Archer
erial No.: 29-8690014	Type Certificate No
olors: Blanco (white)/Laser Opaque/	Propeller Manufacturer: Sensenich 76 FM855-0-62
Original Engine Model: 0-360-A4M	Propeller Manufacturer:
Derial Numbers: Single	Hub or Serial Number: Single 24644K
Left	Right —
Right	Blade Numbers