

MAINTENANCE/INSPECTION ENTRIES

Aircraft Model Boechcraft A36 Serial Number E 3448
Reg # N934 PC Owner's Name [REDACTED]

DATE			TIME	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D	HOURS			

N934PC PROPELLER HARTZELL S/N EE4087B HOBBS 2677.3 TSMOH 899.3

REMOVE SPINNER AND INSPECT BACK PLATE , HUB ATTACH , TKS LINES , DRESS BLADES , GREASE HUB #6 AEROSHELL GREASE , REINSTALL SPINNER.

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION ON THIS DATE 7-1-2024 , ALL AD'S HAVE BEEN CHECKED THROUGH THIS DATE.

ROY S. PLACKIS CERT.# 3122678 I/A

Boy 5 Plackin




[illegible]

Boys. Plor Kus

MAINTENANCE/INSPECTION ENTRIES

Aircraft Model _____ Serial Number _____

Reg # _____ Owner's Name _____

DATE			TIME	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D	HOURS			
				DATE 5-23-18 HOBBS 2157.4 TT 2157.4	N934PC	
				I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AND AIRWORTHY CONDITION. INSPECTED IAW FAR 43 APPENDIX D. ALL ADS CURRENT, SEE AD COMPLIANCE RECORDS. OPERATIONAL AND LEAK CHECK PERFORMED SATISFACTORY. END.		
				 KURT SCHIMPF AP 3661540 IA SELECT AIRCRAFT SERVICE		
				DATE 5-28-19 HOBBS 2264.0 TT 2264.0	N934PC	
				I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AND AIRWORTHY CONDITION. INSPECTED IAW FAR 43 APPENDIX D. ALL ADS CURRENT, SEE AD COMPLIANCE RECORDS. OPERATIONAL AND LEAK CHECK PERFORMED SATISFACTORY. END.		
				 KURT SCHIMPF AP 3661540 IA SELECT AIRCRAFT SERVICE		
				DATE 6-20-20 HOBBS 2393.9 TT 2393.9	N934PC	
				I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AND AIRWORTHY CONDITION. DRESS OUT PROP. INSPECTED IAW FAR 43 APPENDIX D. ALL ADS CURRENT, SEE AD COMPLIANCE RECORDS. OPERATIONAL AND LEAK CHECK PERFORMED SATISFACTORY. END.		
				 KURT SCHIMPF AP 3661540 IA SELECT AIRCRAFT SERVICE		



Reg # _____ Owner's Name _____

10

MAINTENANCE/INSPECTION ENTRIES

Aircraft Model _____ Serial Number _____



Reg # _____ Owner's Name _____


DATE			TIME	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D	HOURS			
				 Certified Repair Station E5ZR316Y 513-871-9966 4760 Airport Road, Hangar 6, Cincinnati, Ohio 45226 Date: February/18/2013 Model: IO-550-B W.O. #E5561 Hobbs: 1778.1 Hours N934PC Removed prop for reseal and reinstalled. End.  Joseph K. Schott, Inspector		
				3-1-2013 HOBBS 1778.1 TOTAL TIME I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH AN <u>ANNUAL</u> INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION.  CES# E5ZR316Y FOR SIGNATURE ENGINES REF: WO# E5561		
				S-16-14 HOBBS 1869.9 TOTAL TIME 1869.9 WO# E6073  CES# E5ZR316Y FOR SIGNATURE ENGINES		

MAINTENANCE/INSPECTION ENTRIES

Aircraft Model _____ Serial Number _____

Reg # _____ Owner's Name _____

DATE			TIME	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D	HOURS			
5	9	11	1403BS	1060.2 AFTT PROP TT	1060.2	
				I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH AN <u>Annual</u> INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION.		
						
6	8	12	1731.6 TT	1731.6 TT		
				I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH AN <u>Annual</u> INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION.		
						

1. Approving National Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 151438	
4. Organization Name and Address: Aircraft Specialists Inc. 6005 Propeller Ln. Sellersburg IN 47172 Repair Station # PZ4R458M						5. Work Order/Contract/Invoice Number: 151438	
6. Item:	7. Description:	8. Part Number:	9. Eligibility:	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	Hartzell Propeller	PHC-C3YF-1RF	N/A	1	EE4087B	Repaired	
13. Remarks: Resealed propeller (disassembled, cleaned, visually inspected, and reassembled using new seals and gaskets) and balanced propeller. All work performed in accordance with Hartzell Manual 113B Rev. 40 dated 8/2012. Complied with Hartzell Service Bulletin 61-315 by installation of pitch change rod bore bushing in engine side hub half.							
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 13.				19. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature:		16. Approval/Authorization No.:		20. Authorized Signature:		21. Approval/Certificate No.:	
						PZ4R458M	
17. Name (Typed or Printed):		18. Date (m/d/y):		22. Name (Typed or Printed):		23. Date (m/d/y):	
				Jeff Davis		Feb/8/2013	
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

MAINTENANCE/INSPECTION ENTRIES

Aircraft Model _____ Serial Number _____

Reg # _____ Owner's Name _____

DATE	TIME	ENTRIES MAY BE ON MULTIPLE	INSPECTOR'S	LICENSE
Y M D	HOURS	LINES IF REQUIRED	SIGNATURE	NUMBER



6320 Highland Road
Waterford, Mi. 48327
Oakland County International Airport

N934PC

Date: 08-19-08 1410.1 TT ----TSO 1410.4 Hobbs

AD2008-13-28 Hartzell propeller hub cracks. N/A by propeller model.

A&P

Avionics, Inc. 4696 Airport Rd. Cincinnati, Ohio 45226 513-871-6222
April 17, 2009 Hobbs 1468.4 TTAF and engine

Completed inspection this date per Beech Inspection Guide. Inspected hub, blades and spinner assembly. I certify that this propeller has been inspected in accordance with an annual inspection and has been determined to be in an airworthy condition.-----end-----

Joseph K. Schott A&P272464269IA



4696 Airport Rd. Hangar 2 Lunken Airport Cinti, OH 45226
513-871-6222
joesavionics@zoomtown.com

N934PC Beech A36 S/N E-3448
5-14-2010 Hobbs 1588.0 AFTT
Engine TT 1588.0
Propeller TT 1588.0

Completed inspection this date in accordance with Beech Maintenance Manual. Inspected hub, blades and spinner assemblies. Greased hub with Aeroshell #6. All ground checks performed satisfactory. I certify that this propeller has been inspected in accordance with an annual inspection and has been determined to be in an airworthy condition.-----end-----

Joseph K. Schott A&P272464269IA

DATE			TIME	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D	HOURS			



MAINTENANCE/INSPECTION ENTRIES

Aircraft Model _____ Serial Number _____

Reg # _____ Owner's Name _____

DATE			TIME		ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D		HOURS			



6320 Highland Road
Waterford, Mi. 48327
Oakland County International Airport

N934PC

Date: 03-17-06 927.1 TT ----TSO 927.1 Hobbs

This Propeller has been inspected in accordance with an ANNUAL inspection and is approved for return to service as of this date and time. Details are on file at this facility under work order # 1880.

A&P 5892278327A

6320 Highland Road
Waterford, Mi. 48327
Oakland County International Airport

N934PC

Date: 03-16-07 1156.4TT ----TSO 1156.4Hobbs

AD2006-24-07 Effective date 01/03/07 N/A not repaired by CSE Aviation.
This Propeller has been inspected in accordance with an ANNUAL inspection and is approved for return to service as of this date and time. Details are on file at this facility under work order # 1956.

A&P 5892278327A

MAINTENANCE/INSPECTION ENTRIES

04

Aircraft Model _____ Serial Number _____

Reg # _____ Owner's Name _____

DATE			TIME		ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D		HOURS			

 **Tradewinds
Aviation**
"the professional approach"

6320 Highland Road
Waterford, Mi. 48327
Oakland County International Airport

N934PC

Date: 05-06-05 713.5TT ----TSO 713.5 Tach

This Propeller has been inspected in accordance with an ANNUAL inspection and is approved for return to service as of this date and time. Details are on file at this facility under work order #1808.

A&P 5892278327A

 **Tradewinds
Aviation**
"the professional approach"

6320 Highland Road
Waterford, Mi. 48327
Oakland County International Airport

N934PC

Date: 08-04-05 816.0TT 816.0 HOBBS
AD2005-14-12 Amendment 39-14189 effective date 07-29-05 does not apply due to propeller model not listed. No further action required.

A&P 589227832

MAINTENANCE/INSPECTION ENTRIES

Aircraft Model _____ Serial Number _____

Reg # _____ Owner's Name _____

DATE			TIME		ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D	H	OURS			



6320 Highland Road
Waterford, Mi. 48327
Oakland County International Airport

N934PC

Date: 05-11-04

401.4TT

401.4 Hobbs

AD2002-09-08 Does not apply due to blade serial numbers.

AD2003-13-17 Does not apply due to not returned to service by T&W Propellers.

A&P 58922832PROPELLER LOG ENTRYAerospace Systems & Technologies Inc.

3213 Arnold Ave. Salina, KS 67401 Tel: (785) 493-0946

N934PC3 January 2005Make: RaytheonModel: A36S/N: E-3448HOBBS: 609.7

Removed propeller. Installed TKS De-icing parts to the blades and bulkhead, re-installed and torqued. Installation done I/A/W TKS Ice Protection Kit Per STC# SA01136WI and in conformance with the Manufactures installation manual P/N: 10353-01 Rev. 3. FAA Form 337 on file this date. The preceding work was accomplished using the following:: Raytheon Maintenance Manuals, AC43.13 1B-2A and/or AS&T Inc. Installation and Procedures Manuals.

This aircraft **IS APPROVED** for flight into known icing conditions when the required equipment is installed and operating properly. (That list may be found in the TKS POH supplement, section 2 pages 3-9.)

Balanced propeller to _____ In/sec.


Updated the POH/AFM and Weight and Balance.


Lance O. Rudman AP2710783

MAINTENANCE/INSPECTION ENTRIES

Aircraft Model _____ Serial Number _____

Reg # _____ Owner's Name _____

DATE			TIME	ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D	HOURS			
 Tradewinds Aviation "the professional approach"				6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport		
				<u>N934PC</u>		
Date: 05-16-03 173.4TT ---TSO 173.4 Hobbs						
This Propeller has been inspected in accordance with an ANNUAL inspection and is approved for return to service as of this date and time. Details are on file at this facility under work order # 1632.						
				A&P 5892278327A		

 Tradewinds Aviation "the professional approach"				6320 Highland Road Waterford, Mi. 48327 Oakland County International Airport		
				<u>N934PC</u>		
Date: 05-11-04 401.4TT ---TSO 401.4 Hobbs						
This Propeller has been inspected in accordance with an ANNUAL inspection and is approved for return to service as of this date and time. Details are on file at this facility under work order # 1721.						
				A&P 5892278327A		

MAINTENANCE/INSPECTION ENTRIES

Aircraft Model A36 Serial Number E-3448
 Reg # N934PC Owner's Name HARTZEN PROPELLER PHC-C34F-INF
S/N EE 4087B

DATE			TIME		ENTRIES MAY BE ON MULTIPLE LINES IF REQUIRED	INSPECTOR'S SIGNATURE	LICENSE NUMBER
Y	M	D	H	OURS			



6320 Highland Road
 Waterford, Mi. 48327
 Oakland County International Airport

N934PC

Date: 05-14-02 16.1TT 000.0TSO 16.1HOBBS

Opened this propeller logbook.

[Signature]

A&P

589227872



6320 Highland Road
 Waterford, Mi. 48327
 Oakland County International Airport

N934PC

Date: 07-11-02 50.3TT ---TSO 50.3Tach

This Propeller has been inspected in accordance with a 50HR inspection and is approved for return to service as of this date and time. Details are on file at this facility under work order # 1548.

[Signature]

A&P

589227872

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PMC-C34F-1RF

PROPELLER S/N EE 4087B

LOGBOOK # _____

[illegible]

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model PNC-C34F-1RF

Propeller S/N EE4087B

Blade Design F8468A-6R

Blade S/N's

No. 1 J 71360

No. 2 J 71563

No. 3 J 71553

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer _____

Aircraft Model _____

S/N _____

Registration _____

HARTZELL PROPELLER
MODEL PHC-C34F-1RF
PROP S/N EE4087B

BLADE S/N'S #1 J71360
#2 J71563 #3 J71553