

☐ **HUB & BLADE INSPECTIONS, F** 732-363-6400

Aviation Charters Patrol Services, Inc.
1900 Cedarbridge Ave.
Lakewood, NJ 08701

Year: _____	Total Time in Service	Descr
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	Mech. C
Reg.# N-32326 Tach Time 3284.8 Total Time 3284.8 Propeller, spinner, and backplate inspected. Blades dressed. Aircraft returned to service. All AD's complete to 2015-11A I certify that on this date 11/03/2015 this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Details on file at Aviation Charters Patrol Services, Inc. on work order #. 53362566 AP IA Signed <i>William T. Bienes</i> 732-363-6400 Aviation Charters Patrol Services, Inc. 1900 Cedarbridge Ave. Lakewood NJ 08701 Reg.# N32326 Tach Time 3311.2 Total Time 3311.2 Propeller, spinner, and backplate inspected. Blades dressed. Aircraft returned to service. AD's complete thru 2017-8A I certify that on this date 08/01/2017 this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. 53362566 AP IA Signed <i>William T. Bienes</i> William T. Bienes		

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year: <u>2019</u>	Total Time in Service	Description
Date: <u>1/2</u>		
Next Inspection Due: _____	Time Since Overhaul	Mech. C
Propeller, spinner, and backplate inspected. Blades dressed. I certify that this propeller has been inspected in accordance with annual inspection. Mech. Cert. # or Repair Station # <u>1A 282537S AP</u> <i>[Signature]</i>		
Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	Mech. C
Reg. N32326 Tach 3326.5 Total Time 3326.5 Propeller, spinner and backplate inspected. Blades dressed. AD's complete to 2020-11A I certify that on this date 11/01/2020 this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. William T Bienes 53362566 AP-IA <i>William T. Bienes</i> Mech. C		

Year: _____	To in
Date: _____	
Next Inspection Due: _____	Tir Ov
Year: _____	To in
Date: _____	
Next Inspection Due: _____	Tir Ov
Year: _____	Tot in
Date: _____	
Next Inspection Due: _____	Tin Ovi

Reg #: N32326	S/N: 28-7525050	Model: PA28-140	Date: 3/9/12
Make: Piper	Tach: 3209.11	Hobbs: 311.9	TSN: 3209.11

1. Propeller insp. and dressed as required.
2. Supplied customer with this propeller logbook started this date.
3. AD search complete this date. No AD's due this visit. Access restored.


"The airframe/engine/ propeller identified APU/ above was repaired and inspected in accordance with manufacturer's specifications and current regulations of the Federal Aviation Administration and with respect to the work specified in work order(s) 32326022712, is approved for return to service only for the work performed

Authorized Signature:

Richard W. Thomas,

**Marlboro Aircraft Services, LLC
Monmouth Executive Airport Bldg. 4
1717 Highway 34 Farmingdale, NJ 07727**

ALTERATIONS ☐

1717 Highway 34 Farmingdale, NJ 07727								
Year: _____	Total Time in Service	Descr	Reg.#	N-32326	Tach Time	3244.6	Total Time	3244.6
Date: _____			Propeller, spinner and backplate inspected. Blades dressed.					
Next Inspection Due: _____	Time Since Overhaul		Aircraft returned to service.					
			All AD's complete to 2013-05A. See AD Compliance report dated 05/31/2013.					
			I certify that on this date 06/01/2013 this propeller was inspected in accordance with an annual inspection and was determined to be in airworthy condition. Details on file at Marlboro Aircraft Services/LLC on work order #3440					
		Mech. C						
Year: _____	Total Time in Service	Descr	53362566 AP IA Signed 					
Date: _____			William T. Bienes					
Next Inspection Due: _____	Time Since Overhaul							
		Mech. Cert. # or Repair Station #						
Year: 2014	Total Time in Service	Description	ANNUAL INSPECTION. DRESSED PROP.					
Date: 9/16	3244.9 3269.9							
Next Inspection Due: _____	Time Since Overhaul							
		Mech. Cert. # or Repair Station #	Sal Filippone AP2223682AA					

Propeller Record General Information

Propeller Manufacturer Sensenich Corp.

Model 74DM6

Hub Series # K36057

Date of Manufacture UMK

Type Metal.

Blade #

Make/Model

Serial #

Aircraft Installed On: Piper PA-28-140

28-7525050