

The subject aircraft was involved in an incident / accident on <u>5/24/2025</u> rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: <u>6056898496US</u>.

Signed: Underwriters Salvage Company

Date: 6/19/2025 AIG Aerospace Adjustment Services Inc 3500 Lenox Road, Suite 1100

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Rep Facility. (See back pages for other specific entries.)
DATE				L STATE OF CHIEFS.)
	Model GT	(327 5	/N <u>83737</u>	sponder: Make Garania 488 has been tested uirements of FAR 91.413.
	Signature _	Lan	loce L	onics Division
	systems-co		ations-war	onics Division
	FAA Repair	Station	XBFR736K	
	w	1025	606	
		1		

DATE	TACH TIME	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
122023	330.\$			I certify This Airframe has been inspected					Clw All repetives S.B. From VAN RV-12 List.
				in Accordance with M.M. and inspection					2000 1000
				procedures For AN Annual inspection and					
				WAS found to be within an Air wowthy Condition.					7. Scott Healing
				Scrviced BRAKE Reservoin. Installed NEW					A+P3154904 IA.
				brake Linnings. Pln: mbb-106. Installed New	<u> </u>				Sept. 127 2023
				MLG TIRES. 5.00-5 4 ply from Wilkerson.	7-24-24	378.1			Asscraft impacted I/A/w 100 hr Van AV chacklist, luked
				PIN: 30841 SIN: B3D25013 PIN: 38841 SIN:					all honges, rodends, barts service bellatos e buted tromplied
				B3 D24417. Re-PACKED All Wheel begrings.					with Elt cheleper 91.207 (d) op de.
				Performed Lubrication of All CAbles + pullags.	· —				I certify that this exerett has been inspected F/A/
			<b>-</b>	to could EL TAW 91.207 (d) ODS Chells					a condition in spection and was found to be in a
				good Batter Exp. JAN 2027. Over 7					andition for sofe operation Robert m. Seem
									A+P1318173 IA

Heart of Virginia Aviation  11152 Aurpark Rd  Ashland, VA 23005  N813/C Hobbs: 206.2 ATT: 206.2 ETT: 206.2 PTT: 206.2  I certify this aircraft has been inspected in accordance with the manufacturer's, maintenance and inspection procedures for a annual condition inspection and was found to be in condition for safe operation. Inspected and lubed all flight  —controls, pulleys, and hinges. Serviced brake reservoir. Removed, cleaned, inspected, and reinstalled fuel gascolator; no containments found. Inspected ELT in accordance with 91.207 (d); battery expiration: Jan 2027. Removed and replaced trim motor Reconnected voltage regulator wires to harness. Extended LH nav light screw tab at wing root to reach contact; nav lights operation checks good. Aircraft operations performs satisfactory and no leaks found at this time. Aircraft is approved for return to	304211	THE ATC TRANSPONDERS AND INSPECTIONS AS REQUIRED BY FAR 91.413 WERE PERFORMED THIS DATE AND FOUND TO COMPLY WITH PART 43 APPENDIX F AND APPENDIX E PARAGRAPH C.  TRANSPONDER  MAKE:  MODEL:  S/N:  TRANSPONDER  MAKE:  MODEL:  S/N:  DATE:  OCAROLINA AVIONICS GROUP, LLC  FAA APPROVED REPAIR STATION # QCCR-389K	is, Tests, Repairs and Alterations Name, Rating and Certificate Number of Technician or Repair ner specific entries.)
10770000	thangi?		
The state of the s			
7) 0			

	<u> </u>								
YEAR: 2021 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR:  ALA  DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	159.3			(continued) C/W SB 19-08-23 nose gear leg replacement, replaced gear leg (P/N WD-1201-1-RTR).  C/W SB 16-05-26 RV-12 Data plate, etched U.S.A. to data plate. Replaced both mown landing gear thres (P/N 5.00-5), and ELT battery (P/N 458-0012) exp. date Jan-2627.		159.3		159.3	I certify that this Assessment with Assessment Conference with Conference with Assessment Conference with Assessment Conference with Assessment Conference with
.21									

YEAR:		I manaya I			-				
2020 DATE		TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: 2021 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
12-4-20	20 158.6		158.4		06-23	159.3		157.3	C/W SB 16-08-01 Stabilator bearing
				Persy Municipal Amport (F22) to Stillwater	·				inspection, due every annual.
				Regional Auport (SWO) AND determines to Be					C/W SB 18-02-02 hardzontal
				IN SAFE CONDITION FOR SAID FLIGHT END					Stabiliator Front spour inspection.
				Bugan 8 1 1 264 1847					no cracks noted due every
									100 hr or annual. C/W SR 18-02-03
									Inspection of the anti servo tab,
								,	no Cracks noted, due every annual.
									C/U SB 16-05-23 nose fork Crack
									inspection, no cracks found,
19									dué every 25 hrs. (continued->)

The state of the s

YEAR:	RECORDING	TODAY'S	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations	YEAR:	RECORDING		TOTAL	Description of Inspections, Tests, Repairs and Alterations
DATE	TACH	FLIGHT	SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	DATE	TACH	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6/23/16	123.5			IN GTALLED MIXTURE CONTROL	1-10-16	158.4		158.4	Person accorded danalitims inspection
				1NOT AWED TRITE GUTTER ON THE CONTRACT STICK 237 2593 HIGHLAND				,	FAR 43 Agid Sagrey System including
6/2/16	123.5		:	SET THE TRIMMER ON SISPLAY PANEL	_				Perform success & analition inspection pur FR 43 Agrid Soprion System including torque table. Inspect SB 110-08-24 Engine mond
900	12 7.			CALIBRATED FUELTLOS					furts. Ingert BB (6-08-01 Stale. bearing
				237 2593 ( ) Consul				·	Imput SB 16-05-23 money doch Cracks.
5/20/17			158.3	V					Scuting this airrest Two resures conformative
									Condition inscretion cole Facet 3 gran Jan Jan Jan
									Considered Date for April Eco Ding 200
									000 APSATBUT

The second secon

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: RECORDING TODAY'S TOTAL Description of Inspections, Tests, Repairs and Alterations TACH FLIGHT TIME IN
5/06/16	114.8		114.8	REPLACED ELT BATTERY. CHECKED 9/6NAL 121.5HHZ	TIME  TIME  TIME  TIME  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Facility. (See back pages for other specific entries.)
7 11.	0.3			REPLACE AGAIN JUNE 2023,	THIS TRANSPONDER SERIAL NUMBER  47x-327 HAS BEEN TESTED IN
5/07/16	11/4 0		114.8	REPLACED ELT REMORE BATTERY	ACCORDANCE WITH F.A.R. PART 43, APPENDIX F, AND MEETS THE REQUIREMENTS
10 110	UTVO	14	(14,0	REPLACE AGAIN JUNE 2023	OT T.A.R.91.413
w/ ed 6	111 5		1111.0	2372593 (BCGOW)	DATE: 5/13/20/6 SIG. The full
5076	114.8		114.8	FOUND TO BE ARWORKSTY	AVIONICS SERVICES INC
0				CHECKED ALSBA LORD TOKEN TOURD	NORMAN, OKLAHOMA  N 8/3JC
	1 040	\	1.1	THUIS MINCHAUL (5/10 (19MD)) JAIZED WITHIN MILL	
				THIS AIR CLAPT IS CONGIDERED SAFETOFIG	
5		ll		237 2593 ( )2194	

7									
YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair. Facility. (See back pages for other specific entries.)
8-4-1	5 112			Another word Cather France	7-13	110			Visity complexed of surice bullition from Vara Sireset from SB#11-9-13 to
	na Para Para		<b>Y</b>	Enorgin System Moneta Boltone					55#15-03-05. Performing work on 55 13-12 -19 modification of gultank 58 14-12-06
		ė		bush Bur sottmeta Good up to					inotall linforcement brocents for flaperon torque ormo. Comply with service motan
				B Brusse R.PM. FNO					14-05-14 Nose rely cracks in storilator. 05-17-11 notan Complied with and Notan
				Tyan mith 4/03/47/847					14-06-30 sil return Chapping rosius. END
									( July Sour 1 Crot 1854 (

YEAR: 2013  DATE		TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEAR: 2014 DATE	RECORDING YACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
03/18	48.1		48.1	1 (ERTIEF THAT SB- 12-11-09 KIT HAS	8/8	92		92	c/w NOTICE 14-06-30 BY RE- ROUTING DIL
				BEEN INSTALLED AND SUBJECT SB HAS BEEN COMPLIED WITH, WEB MODIFIED.	·				RETURN HOSE PER NOTICE pur w 1 Lise, Downer
				Infer REPAIRMAN 1798526	8/8	92		92	CHECKED FLAPERON TORQUE ARM WELDS
13/27	50.1		50.1	CERTIFITHAT SB 13-04-05 KIT MAS BEEN					PER 3B 3-17-11; FOUND TO BE OK pumple like
				INSTALLED & SBHAS BEEN INSTALLED. ROTAX FILTER E'DIL CHANGE (AFROSHELL SPORT 4) COMPLETED.	4/20/15	109		109	Completed annual Condition Inspection James
				5B 13-2-6 COMPLIED WITH. COMPLETED					to be airenathy him what ISA REPARRIAN 1407 543
				CONDITION INSPECTION FWF & AIR FRAME THIS AIRCRAFT IS IN COMPLIANCE W/ALL					C/W SB 14-12-06 by installing Kit & No further regression
				VANS S/B'S AIVO IS SAFE FOR FLIGHT.					c/w 5B 14-05-14 - Juspertal - no cracks found c/w 5B 13-12-19 - Kit installal
1				JEN RENAIRMAN 1798526					ham w Water LSA Repairem 1407543

YEAR: 2011	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Facility. (See back pages for other specific entries.)	DATE		TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
9				I certify that the prescribed flight test hours have been completed and the aircraft is controllable throughout its normal range of speeds and throughout all maneuvers to be executed, has no hazardous operating characteristics or design features and is safe for operation. The flight test was completed under the following conditions: maximum operating weight, style/set of wing or sail, maximum demonstrated airspeed and minimum demonstrated stall speed.  John J. Cooke  John J. Cooke	2012 10/31	<b>31.9</b> 40.7		40.7	Service Bulletin 11-12-14 complied with. Sealed off sight fuel gauge, installed mechanical fuel indicator and pressure tested tank for leaks. No leaks found, fuel tank installed in aircraft and aircraft run up OK. Aircraft returned to service.  John Cooke, Repairman 1798526.  / CERTIFY THAT THIS AIRCRAFT (NB13JC) HAS RECEIVED A CONDITION INSPECTION PER CHECK LIST  CONTAINED IN VAN'S PROPUCTION ACCEPTANCE  PROCEFOURS HANUAL AND DID NOT EXHIBIT AIRP DEFECTS.  THIS AC IS IN COHPULANCE WITH ALL SERVICE LETTERS &  NOTIFICATIONS FROM MFG'R. THIS B/C IS COMSIDERED  SHEE FOR FURNITY OF THE 1798526

A Property of the Control of the Con

YEAR: 2011 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/17		-	0	I FIND THIS AIRCRET METTS THE REQUIREMENTS
			r	FOR THE CENTIFICATE REQUESTED AND HOUSE
				135UED A SPECIAL AINWORKHINGS CENTIFICATE
				FOR THE PURPOSE OF OPERATING hIEAR-SPORT
				AIRCRAFT THIS DATE. Elmify Refunde
				PART 60/89/NM EDMUND J. DESANTIS
0/20			-0	FROP, BALANCED
/				benjen
0/24	-0	1.3	1.3	FIRST FLIGHT, COMPLETED
/ /				SECTION FI, FOIGHT TEST CARD
				John flere

YEAR: 2011 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Description of Inspections, Tests, Repairs and Alterations</b> Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10/25	1.3	1.2	2.5	COMPLETED SECTION FZ, FLIGHT
10/26	-سر رسد	و عو	7.5	TEST CARO the fluce
126	Z.5	1.4	3.9	CONSLETED SECTION F3, FLIGHT
10/27	3.9	-6	4.5	COMPLETED SECTION F4, FLIGHT
				TEST CARD Shute
10/28	4.5	1.2	5.7	COMPLETED SECTION F5, FLIGHT TEST
				GARO JELON
			•	

F

YEAR:	TACH TIME	FLIGHT	TIME IN SERVICE	Description of Inspections, Tests, Repairs Entries must be endorsed with Name, Rating and Ce Facility. (See back pages for other specific entries.)	Certificate Number of Technician or Repair	YEAR: 2011 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
rer's Certification	Standard(s System will following the on this state	s) identifice in the consentation identification is identification in the consentation	ied on this staced to suppensus standa (2)conforms (4) is in a cor	rtify that aircraft kit serial number 120219 of statement of compliance and that the Manufa export the aircraft throughout its life. This aircraft ard(s) procedures and Manufacturer's Qualities to the manufacturer's design data, (3) was condition for safe operation. Additionally, at the estricted access to its facilities.	raft (1)was manufactured lity Assurance System identified ground and flight tested	09/16		contain exhibit notifica John J.	ned in Van t any defect ations from . Cooke, da	aircraft (N813JC) has received a Condition Inspection per check list aircraft Production Acceptance Procedures manual and did not ets. This aircraft is in compliance with all Service Letters and the manufacturer. This aircraft is considered safe for flight.
l fa	Harrio.	tt Risan eral Mana	ager	Signatur	Date DECEMBER 3, 2009	- 09/		Repair	1	
	Section G-1 Tests T1-1	1 throug have be	gh Section een success	g aircraft's (N813JC) Production Accept G-10, Weight and Balance Worksheet stilly completed. This aircraft conform	t W&B-1 and Taxi ms to the design	/30	1.0			ELT BATTERY EXPIRATION DATE  NOV 2015. July
	John J. Coo Repairman	oke, date		turer and is considered safe for flight tes	sting					

The second secon

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Layer:	9863 TEC HS 9864 ACR EN VOC (#gl): 3.95	0	helin	S7 43931	SHI FEED	App Layer:	9903 SS TS275 CC TS276 CC TS218 HS VOC (#/gl);	10 3	. 1   0 .	YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	<b>Des</b> Entrie Facili
			Single Stage	PS PT	>	Yellow	-00-V [00]		Single Stage	SSECRETE DEL SSECRETE LOW STENGTH LOW STENGTH HS BLACK	oke,J Airplane 2K MixING OL UHS BO WHITE	1-00-L [60]	404	0		DATE: 8-4-20 MAKE: VANS	
			Mixed By: Bailey's Mixed: 9/6/2011 2:	VOC Less Exempt(#gl): 4 13 Photo: Lead: 0.03	SIZE / Ounce(s)  SIZE / Ounce(s)  SIZE / Ounce(s)	2012	CODE: 4610		9 S	Les	SIZE: 2 Ounce(s)	CODE: 8624 1993-2013 Che				Performed pit I certify that t And the trans	tot/station
			38:49 PM	(#/gl): 4 13 ead: 0.03	ENT 28.6	Navistar International Truck			Lead: 0.00 : Bailey's Body Shop 5/2011 2:48:10 PM		VENT 8.2	Chevrolet			 	Dustin Shawve	er #3565

YEAR: O// DATE	RECORDING TACH TIME	TODAY'S FLIGHT	Tests, Repairs and Alter ne, Rating and Certificate Nu specific entries.)			
104	0		,	<u>Mesquite Avionics LLC</u> CRS#Q5KR301B		
		_	DATE. 8-4-2 MAKE: VAN	/ III 11 11 11 11 11 11 11 11 11 11 11 11	WO#: 0100 SN#: 120219	HOBBS: 0 TACH: 0
		_		itot/static system leak check IAW FAR Pa		_
		_		the transponder test required by 91.413 sponder system meets the requirements		- cate, -
		_			8-4-2011	-
		- 	Dustin Shawv	er #3565387		·

ircraft Record General Information
lanufacturer VAN'S AIRCRAFT, LL CModel RV-12
$\frac{120219}{120219}$ Registration Number $\frac{813JC}{120219}$
ate of Manufacture DEC 03, 2009
<sup>ngine</sup> (s) currently installed:
anufacturer ROTAX Modell 912 ULS-3 Serial 677523.0
anufacturer Model Serial
<sup>lopeller</sup> (s) currently installed:
anufacturer SENSENICH Model LAURSKIUG-V
UB Model BR 16871 BR Soviet
ade Model Serial 22699 Serial 22685 Serial
ade Model Serial Serial Serial