



The Standard

PROPELLER LOG

ASA-SP-L

The subject aircraft was involved in an incident / accident on 9/23/2025 rendering it a Constructive Total Loss as not repairable within its insured value. For further details refer to insurance claim: 9422955904US.

Signed: ***Underwriters Salvage Company***

Date: **1/6/2026**

AIG Aerospace Adjustment Services Inc
3500 Lenox Road, Suite 1100
Atlanta, GA 30326

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2016	Total Time in Service	Description: INSTALL OVERHAUL Propeller
Date: 2/2/16	571.14	
Next Inspection Due:	Time Since Overhaul	
	0	Mech. Cert. # or Repair Station #: Dan & Barbara AWP 1674145

Year: 2016	Total Time in Service	Description: ANNUAL INSPECTION FOR CONDITION AND SECURITY
Date: 6-23	593.5	SECURITY I CENT. FT HIS PROPELLER HAS BEEN INSPECTED IAW ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #: Dan & Barbara AWP 1674145 IA

Year: 2017	Total Time in Service	Description: ANNUAL INSPECTION FOR CONDITION AND SECURITY
Date: 6-23	630.61	I CENT. FT HIS PROPELLER HAS BEEN INSPECTED IAW ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #: Dan & Barbara AWP 1674145 IA

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year:	Total Time in Service	Description
Date:	HOBBS 652.77 TSOH 81.63	
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

Year: 2024	Total Time in Service	Description: Installed propeller RT position PA34-201T N1455, Aircraft TT 3735h Prop TT 652.7 Prop SOH 81.6
Date: 28 August	652.7	
Next Inspection Due:	Time Since Overhaul	
	81.6	Mech. Cert. # or Repair Station #: Dan & Barbara AWP 2049321 IA

Year: 2025	Total Time in Service	Description: Aircraft TT 3760.9 / Prop TT 675.6 / SOH 102.5
Date: 11 March 2025		Annual inspection completed this date
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #: Dan & Barbara AWP 2049321 IA

RIGHT

Propeller Record General Information

Propeller Manufacturer

MCCAULEY

Model

3AF34C503

Type

Hub Series #

Blade #

Date of Manufacture

Aircraft Installed On:

Make/Model

Piper Seneca II
N8076Y

Serial #